**Beurer GS10**

# Beurer GS10 Digital Glass Scale Instruction Manual

Model: GS10 (756.21)

## 1. Introduction

Thank you for choosing the Beurer GS10 Digital Glass Scale. This manual provides important information regarding the safe and proper use, setup, and maintenance of your new scale. Please read these instructions carefully before first use and keep them for future reference.

### Product Features:

- Easy-to-read LCD display
- Flat design height: only 1.9 cm
- Quick start technology
- Automatic switch-off function
- Overload indicator
- Maximum weight capacity: 180 kg

### Safety Information:

- Place the scale on a firm, level surface to ensure accurate measurements. Avoid carpets or soft flooring.
- Do not use the scale in areas with high humidity, such as directly next to a shower or bathtub.
- The scale is designed for personal weight measurement only.
- Clean the scale with a damp cloth; do not use abrasive cleaning agents.
- Keep batteries out of reach of children.

## 2. Setup

### 2.1 Battery Installation

Your Beurer GS10 scale requires 1 Lithium Metal battery (included). Locate the battery compartment on the underside of the scale. Open the compartment cover, insert the battery according to the polarity markings (+/-), and close the cover

securely.

## 2.2 Initial Placement and Calibration

Place the scale on a hard, flat, and stable surface. For the first use, or if the scale has been moved, it is recommended to perform an initial calibration:

1. Gently step onto the scale.
2. The display will show a reading, then turn off.
3. The scale is now calibrated and ready for use.




Figure 1: Beurer GS10 Digital Glass Scale. This image shows the sleek black glass surface of the scale with a digital display showing a weight reading.




Figure 2: Flat construction of the Beurer GS10 scale. A close-up view highlights the slim 19 mm profile of the scale, indicating its compact design.

## 3. Operating the Scale

### 3.1 Taking a Measurement

The Beurer GS10 scale features quick start technology:

1. Step onto the scale barefoot and stand still.
2. Your weight will be displayed on the LCD screen.
3. The scale will automatically switch off after a few seconds to conserve battery life.



Figure 3: Easy-to-read LCD display. A close-up of the scale's digital screen clearly showing a weight measurement, designed for quick and effortless reading.

### 3.2 Weight Unit Conversion (if applicable)

If your scale supports multiple units (e.g., kg, lb, st), there is typically a button on the underside of the scale to switch between them. Refer to the markings near the button for specific instructions.

## 4. Maintenance

### 4.1 Cleaning

Clean the scale regularly with a slightly damp cloth. Do not use abrasive cleaning agents or immerse the scale in water. Ensure the scale is dry before storage or next use.

### 4.2 Storage

Due to its flat design (1.9 cm height), the Beurer GS10 scale can be easily stored under furniture or in narrow spaces. Store in a dry place at room temperature.

## 5. Troubleshooting

- **Display shows "Lo":** The battery is low. Replace the battery as described in Section 2.1.
- **Display shows "Err" or "O-Ld":** The scale is overloaded. The maximum weight capacity is 180 kg. Step off the scale immediately.
- **Inaccurate readings:**
  - Ensure the scale is on a hard, flat, and stable surface.
  - Perform initial calibration (step on, step off) if the scale has been moved.
  - Ensure you are standing still during measurement.
- **Scale does not turn on:** Check battery installation and ensure the battery is not depleted.

## 6. Specifications

| Feature | Specification |
| --- | --- |

| Feature | Specification |
| --- | --- |
| Model Number | GS10 (756.21) |
| Brand | Beurer |
| Maximum Weight Capacity | 180 kg |
| Readout Accuracy | +/- 100 g |
| Display Type | LCD |
| Special Features | Backlit Display |
| Material | Glass |
| Product Dimensions | 30 x 1.9 x 30 cm |
| Item Weight | 1.52 Grams |
| Batteries | 1 Lithium Metal battery (included) |
| Color | Black |




Figure 4: Scale indicating 180 kg capacity. This image illustrates the maximum weight capacity of the scale, showing a dial indicating up to 180 kg.

## 7. Warranty and Support

### 7.1 Warranty Information

Egyserv Company provides a 1-Year service warranty on all Beurer products, with the exception of Blood Pressure Monitors which have a 3-year warranty. To activate your warranty, please visit the Egyserv website and upload your invoice on the activation page:

egyservshop.com

### 7.2 Contact Information

For support or inquiries, you may contact Egyserv at their branch locations:

- **Alexandria Branch:**
  40 Tout ankh amoun St, Smouha, second floor
  Mobile Number: 01000777452
- **Cairo Branch:**
  26 Mohamed Mekled St, Nasr City, 8th district, first floor
  Mobile Number: 01000777453

## Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

**Name**

Anonymous

**Email**

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

**Question**

Example: How do I reset this device or fix this error?

**Details**

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question