Saved from manuals.plus.
Open the live page for links to other documents and user manuals.

Fuzion UF-OG-200

Fuzion Digital Pocket Scale Instruction Manual

Model: UF-OG-200 | Brand: Fuzion

Product Overview

The Fuzion Digital Pocket Scale is a high-precision weighing instrument designed for accurate measurements of small items. It features a compact, portable design with a protective flip case, an easy-to-read LCD display, and multiple unit conversion modes. Ideal for weighing food, jewelry, coins, gemstones, medicines, and more.



Image: Fuzion Digital Pocket Scale, showing the scale, included 50g calibration weight, and AAA batteries.

Setup

Battery Installation

The Fuzion Digital Pocket Scale requires two AAA batteries (included). To install, open the battery cover located on the underside of the scale. Insert the batteries according to the polarity indications (+/-) inside the battery compartment. Close the battery cover securely.



Image: Diagram illustrating the steps for battery installation into the scale.

Initial Placement

Place the scale on a horizontal, flat, and stable surface. Ensure there are no vibrations or drafts that could affect the weighing accuracy.

Operation

Turning On/Off

Press the "ON/OFF" key to turn on the scale. The LCD display will show "0.00" or "0.000" when ready for weighing. To turn off the scale, press and hold the "ON/OFF" key until the display turns off, or it will auto-off after 180 seconds of inactivity.

Unit Conversion

Press the "MODE" key to switch between the 6 different units: grams (g), ounces (oz), grains (gn), carats (ct), pennyweights (dwt), and troy ounces (ozt).




Image: The scale's LCD display showing various unit conversions like grams, ounces, and carats.

Tare Function

To weigh items in a container, place the empty container on the weighing platform. Press the "TARE" key. The display will reset to "0.00" or "0.000". You can then add the items to be weighed into the container, and the scale will display only the net weight of the items.




Image: A four-step visual guide demonstrating how to use the tare function to weigh items in a container.

Weighing Items

Place the item(s) to be weighed gently onto the center of the weighing platform. The LCD display will show the weight instantly.

Video: Demonstrates the basic operation of the Fuzion Mini Gram Scale, including unit conversion and weighing various small items like feathers, coins, and spices.

Video: Shows the compact size and various applications of the Fuzion Digital Pocket Scale, including weighing coffee beans and tomatoes with mayonnaise.

Calibration

To ensure accurate results, periodically check and adjust the scale's calibration. A 50g calibration weight is included for this purpose.

1. Turn on the scale by pressing the "ON/OFF" key.
2. Press and hold the "MODE" key until the display shows "CAL", then release the button.
3. Press the "MODE" key again. The required weight (e.g., "50.00") will flash on the display.
4. Place the 50g calibration weight onto the center of the platform.
5. The LCD display will show "PASS" and then return to normal weighing mode. Calibration is complete.

If the process goes wrong, repeat the steps. Check the availability of weights at the store you bought your scale from if you need additional calibration weights.



Image: A visual guide detailing the steps to calibrate the Fuzion Digital Pocket Scale using the included 50g weight.

Maintenance

Cleaning

To clean the scale, use a soft, damp cloth. Avoid abrasive cleaners or harsh chemicals that could damage the surface or internal components. Keep the scale dry.



Image: A hand wiping the stainless steel weighing platform of the scale with a soft cloth.

Storage

Store the scale in its protective flip case when not in use to prevent damage to the weighing platform and display. Store in a cool, dry place away from extreme temperatures and humidity.

Troubleshooting

- **"Lo" or "Lo-" displayed:** Indicates low battery. Replace the AAA batteries.
- **"O-Ld" displayed:** Indicates overload. Remove items from the platform immediately to avoid damage.
- **Unstable readings:** Ensure the scale is on a stable, flat surface, away from vibrations, drafts, or electromagnetic interference. Recalibrate if necessary.
- **Scale does not turn on:** Check battery installation and ensure batteries are not depleted.

Specifications

Feature	Detail
Brand	Fuzion
Model Number	UF-OG-200
Weight Limit	200 Grams
Readout Accuracy	0.01 Grams
Units of Measurement	g, oz, gn, ct, dwt, ozt
Display Type	LCD (Backlit)
Power Source	2 x AAA batteries (included)
Auto-Off	180 seconds of inactivity
Material	Stainless Steel / ABS
Product Dimensions	2.2 x 1.59 x 0.3 inches

Warranty & Support

Fuzion is dedicated to 100% customer satisfaction. This product comes with a 2-year warranty and lifetime support. For any questions or concerns, please contact our service team.

For a detailed user guide, please refer to the official User Manual (PDF) available at:Fuzion Digital Pocket Scale User Manual

Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

https://manuals.plus/asin/B07L8ZVVRM

More documents and user manuals: **https://manuals.plus/**