Saved from manuals.plus.
Open the live page for links to other documents and user manuals.

Braun MQ60 Replacement Blade

Braun MQ60 Minipimer Multiquick Spice Grinder Replacement Blade

INSTRUCTION MANUAL

1. Introduction

This manual provides essential information for the safe and effective use of your Braun MQ60 Minipimer Multiquick Spice Grinder Replacement Blade. This product is an original Braun spare part designed specifically for the MQ60 spice grinder attachment, compatible with various Braun Minipimer Multiquick hand blender models. Please read these instructions carefully before installation and use, and retain them for future reference.

Important Note: This blade is intended exclusively for use within the Braun MQ60 spice grinder attachment. It is not suitable for use in standard choppers or other attachments.

2. Safety Information

- Always handle the blade with extreme care. The cutting edges are very sharp.
- Ensure the hand blender is unplugged from the power outlet before attaching, detaching, or cleaning the blade.
- Keep fingers and utensils away from the blade during operation.
- Do not attempt to sharpen the blade yourself.
- Keep the product out of reach of children.
- Inspect the blade for any damage before each use. Do not use if damaged.

3. Product Overview

The Braun MQ60 Replacement Blade is a precision-engineered component designed to restore the grinding efficiency of your MQ60 spice grinder attachment. It features durable stainless steel blades mounted on a robust shaft for optimal performance.



Image 1: The Braun MQ60 Replacement Blade, showing its sharp cutting edges and shaft.

4. Setup and Installation

Follow these steps to correctly install the replacement blade into your Braun MQ60 spice grinder attachment:

1. **Ensure Safety:** Disconnect your Braun hand blender from the power supply.
2. **Remove Old Blade (if applicable):** Carefully remove the existing blade from the MQ60 attachment. If the old blade is stuck, gently twist and pull.
3. **Insert New Blade:** Place the new replacement blade into the center shaft of the MQ60 spice grinder bowl. Ensure it sits securely and correctly engages with the drive mechanism.
4. **Attach Lid:** Securely place the lid onto the MQ60 spice grinder bowl, ensuring it locks into position.
5. **Connect to Hand Blender:** Attach the assembled MQ60 spice grinder attachment to the motor unit of your Braun Minipimer Multiquick hand blender.



Image 2: Visual guide demonstrating the insertion of the replacement blade into the Braun MQ60 spice grinder attachment.

5. Operating Instructions

Once the replacement blade is installed, your MQ60 spice grinder attachment is ready for use. Refer to your Braun Minipimer Multiquick hand blender's main instruction manual for detailed operating procedures. This blade is designed for grinding dry ingredients such as coffee beans, spices, nuts, and herbs.

- Do not overfill the spice grinder bowl.
- Use short bursts for grinding to achieve desired consistency and prevent overheating.
- Ensure the attachment is securely locked before starting the motor.

6. Maintenance and Cleaning

Regular cleaning ensures optimal performance and longevity of your replacement blade.

1. **Disconnect Power:** Always unplug the hand blender before cleaning.
2. **Remove Blade:** Carefully remove the blade from the MQ60 attachment.
3. **Wash:** Wash the blade under running water with a mild detergent. Use a brush if necessary to remove stubborn residues. Exercise extreme caution due to sharp edges.
4. **Dry:** Thoroughly dry the blade before storing or reassembling to prevent rust.
5. **Storage:** Store the blade safely, preferably within the MQ60 attachment, away from children.

7. Troubleshooting

Problem	Possible Cause	Solution
Blade does not fit into the MQ60 attachment.	Incorrect blade model or improper alignment.	Ensure you have the correct MQ60 replacement blade. Align the blade shaft correctly with the drive mechanism in the bowl.
Poor grinding performance.	Blade is dull, attachment is overfilled, or ingredients are too wet.	If the blade is old, it might be dull (this is a new replacement, so unlikely initially). Do not overfill. Ensure ingredients are dry.
Attachment not engaging with motor unit.	Lid not properly secured or attachment not correctly mounted.	Ensure the MQ60 lid is securely locked and the entire attachment is correctly twisted onto the hand blender motor unit.

8. Specifications

Product Type: Replacement Blade for Spice Grinder Attachment

Brand: Braun

Model Compatibility: Specifically for Braun MQ60 Spice Grinder Attachment. Compatible with Braun Minipimer Multiquick hand blender models including (but not limited to):

- 4192 - MQ3038, MQ3048
- 4193 - MQ3126
- 4199 - MQ738 SPICE+, MQ778 BAGEL
- 4200 - MQ9038X, MQ9078X

Dimensions (Blade): Approximately 9.5 x 5.5 x 9 cm (L x W x H)

Weight (Blade): Approximately 40 grams

Material: Stainless Steel (blade), Plastic (shaft components)

9. Warranty and Support

As this is a replacement part, specific warranty terms may vary. Please refer to the original warranty information provided with your Braun hand blender or MQ60 spice grinder attachment for details on replacement parts. For further assistance, technical support, or inquiries regarding compatible models not listed, please contact Braun customer service or your authorized dealer.

You can often find product data on the identification plate, usually located on the underside of your appliance.

Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

https://manuals.plus/asin/B07NZVF4HQ

More documents and user manuals: **https://manuals.plus/**