

[Manuals.plus](#) /

› [GUY-TECH](#) /

› GUY-TECH AC Power Adapter Instruction Manual for Drillmaster 69652 18V Tool

GUY-TECH 69652

GUY-TECH AC Power Adapter Instruction Manual

For Drillmaster 69652 18V Battery Screwdriver Driver Tool

Brand: GUY-TECH

INTRODUCTION

This instruction manual provides essential information for the safe and effective use of your GUY-TECH AC Power Adapter. This adapter is designed as a compatible replacement power supply for the Drillmaster 69652 18V Battery Screwdriver Driver Tool, ensuring reliable power delivery for charging and operation.

IMPORTANT SAFETY INFORMATION

- Read all instructions before use.
- Ensure the adapter's input voltage (100V-240V) matches your local power supply.
- Do not expose the adapter to water, moisture, or extreme temperatures.
- Avoid dropping or subjecting the adapter to severe impact.
- Do not attempt to open or modify the adapter. There are no user-serviceable parts inside.
- Always unplug the adapter from the power outlet when not in use or before cleaning.
- This adapter features Over Voltage, Over Current, and Short Circuit output Protection for enhanced safety.

PACKAGE CONTENTS

The package contains:

- 1 x GUY-TECH AC Power Adapter (7ft cable with barrel connector)



Image: The GUY-TECH AC Power Adapter, featuring a black casing, a 7-foot long cable, and a barrel-type DC output connector. An LED indicator is visible on the adapter body.

SETUP

1. **Verify Compatibility:** Before connecting, ensure your device is the Drillmaster 69652 18V Battery Screwdriver Driver Tool or another compatible device requiring an 18V DC input with a barrel connector.
2. **Connect to Device:** Insert the barrel connector end of the adapter cable firmly into the DC input port of your Drillmaster 69652 tool.
3. **Connect to Power Outlet:** Plug the AC prongs of the adapter into a standard 100V-240V wall power outlet.
4. **Power Indicator:** A small LED indicator on the adapter will illuminate, signifying that the adapter is receiving power and is ready to supply power to your device.



7
FEET



LED
light

Image: A graphic emphasizing the 7-foot cable length and the presence of an LED indicator light on the power adapter.

OPERATING INSTRUCTIONS

Once properly connected, the GUY-TECH AC Power Adapter will begin supplying power to your Drillmaster 69652 tool. This allows for direct operation of the tool when plugged in, or for charging the tool's battery if it has charging capabilities via its DC input port. The 7-foot cable provides ample reach for convenient use.

- Ensure the LED indicator on the adapter is lit to confirm power flow.
- Refer to your Drillmaster 69652 tool's manual for specific charging times and operational guidelines.

MAINTENANCE

- **Cleaning:** Disconnect the adapter from the power outlet and the device before cleaning. Use a soft, dry cloth to wipe the surface. Do not use liquid cleaners or solvents.
- **Storage:** Store the adapter in a cool, dry place away from direct sunlight and moisture when not in use. Avoid tightly coiling the cable to prevent damage.
- **Inspection:** Periodically inspect the cable and connectors for any signs of wear, cuts, or damage. If damage is observed, discontinue use immediately.

TROUBLESHOOTING

Problem	Possible Cause	Solution
Adapter LED not lit / No power to device	• Power outlet not active • Adapter not fully plugged in • Device not fully connected • Faulty adapter or cable	• Test the outlet with another device. • Ensure the adapter is securely plugged into the wall. • Verify the barrel connector is fully inserted into the device. • If issues persist, contact customer support.
Device not charging or operating correctly	• Incompatible device • Device issue	• Confirm your device is the Drillmaster 69652 18V tool or another compatible model. • Consult your device's instruction manual for troubleshooting specific to the tool.

SPECIFICATIONS

- **Brand:** GUY-TECH
- **Input Voltage:** 100V - 240V AC (Worldwide compatible)
- **Output Voltage:** 18 Volts DC
- **Cable Length:** 7 Feet (approximately 2.1 meters)
- **Connector Type:** Barrel Connector
- **Special Features:** LED Indicator, Over Voltage Protection, Over Current Protection, Short Circuit Protection
- **Compatible Devices:** Drillmaster 69652 18V Battery Screwdriver Driver Tool (and other compatible 18V DC devices)
- **Item Weight:** 5 ounces (approximately 141 grams)

WARRANTY AND SUPPORT

For warranty information or technical support regarding your GUY-TECH AC Power Adapter, please contact the manufacturer directly through their official channels. Refer to your purchase documentation for specific contact details.

© 2023 GUY-TECH. All rights reserved.

ASK A QUESTION ABOUT THIS MANUAL

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. [Privacy details](#).

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

<https://manuals.plus/asin/B091L2YJLX>

More documents and user manuals: <https://manuals.plus/>