Ricoh 828250

RICOH Pro C901 Yellow Toner Cartridge User Manual

Model: 828250

1. Introduction

This manual provides essential information for the proper use, installation, and maintenance of your Ricoh Pro C901 Yellow Toner Cartridge (Model 828250). This genuine Ricoh product is designed to deliver high-quality yellow prints for compatible Ricoh Pro C901 and Pro C901S printers.

The cartridge offers an estimated yield of up to 67,000 pages, ensuring reliable performance and professional-quality color printing. Adhering to the guidelines in this manual will help maximize the life and performance of your toner cartridge and printer.

2. Product Overview



Figure 1: Ricoh Pro C901 Yellow Toner Cartridge and Packaging

This image displays the Ricoh Pro C901 Yellow Toner Cartridge, model 828250, both inside and outside its brown retail packaging. The packaging indicates 'Pro Print Cartridge Yellow C901' and 'Genuine' with the EDP code 828250. The cartridge itself is cylindrical and yellow, with a dark brown end cap.



Figure 2: Ricoh Pro C901 Yellow Toner Cartridge

A detailed view of the Ricoh Pro C901 Yellow Toner Cartridge. The cartridge is cylindrical with a ribbed yellow body and a dark brown end cap featuring warning labels and connection points.



Figure 3: Ricoh Pro C901 Yellow Toner Cartridge Packaging

This image shows the top view of the Ricoh Pro C901 Yellow Toner Cartridge's retail box. The box is brown and clearly labeled 'RICOH Savin Lanier Pro Print Cartridge Yellow C901', with 'Color YELLOW' and 'Net Weight 2334g/82.33oz' visible. It also features handling symbols and the 'GENUINE' stamp with EDP code 828250.

3. Setup and Installation

Follow these steps to properly install the Ricoh Pro C901 Yellow Toner Cartridge into your compatible printer. Always refer to your printer's specific user manual for detailed instructions, as procedures may vary slightly by model.

1. **Preparation:** Ensure the printer is powered on and in a ready state. Open the front cover or access panel of your printer where the toner cartridges are located.
2. **Remove Old Cartridge (if applicable):** If replacing an empty cartridge, carefully pull out the old yellow toner cartridge. Place it in a bag or on a piece of paper to prevent toner spills.
3. **Unpack New Cartridge:** Remove the new Ricoh 828250 Yellow Toner Cartridge from its packaging. Avoid touching the green or blue drum surface, as oils from your skin can affect print quality.
4. **Shake Gently:** Gently shake the new toner cartridge horizontally 5-6 times to distribute the toner evenly inside.
5. **Remove Protective Seals:** Carefully remove any protective tapes, seals, or covers from the cartridge as indicated by the instructions on the cartridge itself.
6. **Insert New Cartridge:** Align the new yellow toner cartridge with the corresponding slot in the printer. Push it firmly until it clicks securely into place. Ensure it is fully seated.
7. **Close Access Panel:** Close the printer's front cover or access panel. The printer may perform a calibration or initialization process.
8. **Test Print:** Print a test page or a document to confirm proper installation and print quality.

Caution: *Do not force the cartridge into place. If it does not fit, recheck the alignment and ensure you have the correct cartridge for your printer model.*

4. Operating Instructions

Once the Ricoh Pro C901 Yellow Toner Cartridge is correctly installed, it operates automatically as part of your printer's imaging system. The printer will draw toner from the cartridge as needed to produce yellow prints.

- **Page Yield:** This cartridge is designed to yield approximately 67,000 pages at 8.75% coverage. Actual yield may vary significantly based on images printed, print settings, paper type, and frequency of printing.
- **Low Toner Alerts:** Your printer will typically display a warning message when the toner level is low. It is advisable to have a replacement cartridge on hand when this alert appears to avoid interruptions in printing.
- **Print Quality:** For optimal print quality, ensure your printer's drivers are up to date and that you are using recommended paper types.

5. Maintenance and Storage

Proper handling and storage can extend the life of your toner cartridge and ensure consistent print quality.

- **Storage:** Store unused toner cartridges in their original, unopened packaging in a cool, dry place, away from direct sunlight and extreme temperatures. Recommended storage temperature is between 0°C and 35°C (32°F and 95°F).
- **Handling:** Always handle the cartridge by its ends or sides. Avoid touching the photosensitive drum (usually green or blue) as fingerprints can cause print defects.
- **Recycling:** When the cartridge is empty, please recycle it responsibly according to local regulations. Many manufacturers, including Ricoh, offer recycling programs for used toner cartridges.
- **Cleaning:** Do not attempt to refill or clean the toner cartridge yourself. This can damage the cartridge and potentially your printer.

6. Troubleshooting

If you encounter issues with your Ricoh Pro C901 Yellow Toner Cartridge, consider the following common problems and solutions:

- **Faded or Light Prints:**
  - The toner cartridge may be running low. Replace it with a new one.
  - Gently shake the cartridge to redistribute remaining toner.
  - Check printer settings to ensure 'Toner Save' mode is not enabled.
- **Streaks or Spots on Prints:**
  - The photosensitive drum may be dirty or damaged. Ensure you did not touch the drum during installation.
  - Perform a printer cleaning cycle as per your printer's manual.
  - If the issue persists, the cartridge may be defective and require replacement.
- **"Toner Cartridge Not Recognized" Error:**
  - Remove the cartridge and reinstall it, ensuring it is firmly seated.
  - Turn the printer off, wait 30 seconds, then turn it back on.
  - Ensure you are using a genuine Ricoh cartridge compatible with your printer model.
- **Toner Leaks:**
  - Ensure the cartridge is properly installed and not damaged.
  - If the cartridge is leaking from its packaging upon arrival, contact your supplier for a replacement.

If these troubleshooting steps do not resolve the issue, please contact Ricoh customer support or your printer service provider.

7. Specifications

Property	Value
Manufacturer	Ricoh
Item Model Number	828250

Property	Value
Compatible Devices	Ricoh Pro C901, Ricoh Pro C901S Printers
Color	Yellow
Page Yield	Up to 67,000 pages (at 8.75% coverage)
Item Weight	7.63 pounds (approx. 3.46 kg)
Package Dimensions	27.5 x 9.8 x 6.7 inches (approx. 69.85 x 24.89 x 17.02 cm)
Included Components	Toner Cartridge
Date First Available	April 4, 2022

8. Warranty and Support

For specific warranty information regarding your Ricoh Pro C901 Yellow Toner Cartridge, please refer to the documentation provided with your printer or the official Ricoh website. Genuine Ricoh consumables are typically covered by a limited warranty against defects in materials and workmanship.

For technical assistance, product support, or to inquire about recycling programs, please visit the official Ricoh support website or contact their customer service department. Ensure you have your printer model and toner cartridge model number (828250) ready when seeking support.

- **Ricoh Official Website:** www.ricoh.com
- **Ricoh Support:** Refer to the support section on the official website for regional contact information and resources.

© 2024 Ricoh Corporation. All rights reserved. Specifications are subject to change without notice.

Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question