

[Manuals.plus](#) /

> [Generico](#) /

> Generico Needle Bar Guide Joint for Borletti FB F.B. Sewing Machines (Models 1095, 1096, 1100, 1101, 1102) Instruction Manual

Generico 1095, 1096, 1100, 1101, 1102

Generico Needle Bar Guide Joint

INSTRUCTION MANUAL FOR BORLETTI FB F.B. SEWING MACHINES (MODELS 1095, 1096, 1100, 1101, 1102)

1. Product Overview

This document provides instructions for the Generico Needle Bar Guide Joint, a replacement component designed for specific Borletti FB F.B. sewing machine models. This part is crucial for the smooth and accurate movement of the needle bar, ensuring proper stitch formation and machine operation. It is compatible with Borletti FB F.B. models 1095, 1096, 1100, 1101, and 1102.



Figure 1: Front view of the Generico Needle Bar Guide Joint. This image shows the main body of the joint, including the threaded opening for the needle bar and the shaft for attachment.

2. Safety Information

- Always disconnect the sewing machine from the power supply before attempting any installation, maintenance, or repair.
- Handle small parts with care to avoid loss or damage.
- If you are unsure about any step, consult a qualified sewing machine technician.
- Keep small parts away from children.

3. Setup and Installation

Replacing the needle bar guide joint requires careful attention to detail. Refer to your specific Borletti sewing machine's service manual for detailed disassembly and reassembly instructions, as procedures may vary slightly between models.

1. **Preparation:** Disconnect the sewing machine from the power source. Clear the work area and gather any necessary tools (e.g., screwdrivers, small wrenches).
2. **Access the Needle Bar Area:** Depending on your machine model, you may need to remove covers or panels to gain access to the needle bar mechanism.
3. **Remove the Old Joint:** Carefully loosen any screws or fasteners securing the existing needle bar guide joint. Note its orientation and how it connects to the needle bar and the machine frame. Gently remove the old joint.
4. **Install the New Joint:** Position the Generico Needle Bar Guide Joint in the same orientation as the old one. Ensure it aligns correctly with the needle bar and its mounting points. Secure it with the appropriate screws or fasteners, but do not overtighten initially.
5. **Reassemble and Test:** Once the new joint is in place, reassemble any covers or panels. Reconnect the machine to power. Manually turn the handwheel to observe the needle bar's movement. It should move smoothly without binding. Perform a test stitch to ensure proper function. Adjust tension or other settings as needed.




Figure 2: Side view of the Generico Needle Bar Guide Joint. This perspective highlights the overall shape and the attachment points of the component.

4. Operation

The Generico Needle Bar Guide Joint is a functional component that facilitates the precise vertical movement of the needle bar. Once correctly installed, its operation is integral to the sewing machine's normal function. No direct user interaction with the joint itself is required during sewing. Proper installation ensures the needle bar moves freely and accurately, which is essential for consistent stitch quality and preventing needle breakage.

5. Maintenance

- **Regular Inspection:** Periodically inspect the needle bar guide joint for any signs of wear, cracks, or looseness.
- **Cleaning:** Use a soft brush or compressed air to remove lint and dust accumulation around the joint and needle bar area. Avoid using harsh chemicals.
- **Lubrication:** Refer to your sewing machine's original manual for specific lubrication points and recommended

lubricants. Some guide joints may benefit from a small amount of sewing machine oil, while others are designed to be self-lubricating.

6. Troubleshooting

If you experience issues after installing the new needle bar guide joint, consider the following:

- **Needle Bar Binding/Sticking:** Ensure the joint is not overtightened and is correctly aligned. Check for any obstructions (e.g., lint, debris) in the needle bar channel.
- **Excessive Play in Needle Bar:** Verify that all fasteners securing the joint are tightened appropriately. If the joint itself is worn, it may need replacement.
- **Incorrect Stitch Formation:** While often related to tension or timing, an improperly installed or faulty guide joint can contribute to inconsistent needle movement, affecting stitch quality. Recheck installation.

For persistent issues, consult your sewing machine's service manual or a professional technician.

7. Specifications

Part Name	Needle Bar Guide Joint
Brand	Generico
Compatibility	Borletti FB F.B. Sewing Machine Models: 1095, 1096, 1100, 1101, 1102
Manufacturer	Singer Catania
ASIN	B09Z7XQZPH

8. Warranty and Support

Information regarding warranty coverage or specific customer support for this Generico product is not available in the provided product data. Please refer to your purchase documentation or contact the seller directly for details on warranty and support services.

© 2023 Generico. All rights reserved.

ASK A QUESTION ABOUT THIS MANUAL

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. [Privacy details](#).

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

<https://manuals.plus/asin/B09Z7XQZPH>

More documents and user manuals: <https://manuals.plus/>