SNDOAS GF3976WH

SNDOAS 30 inch Under Cabinet Range Hood User Manual

Model: GF3976WH

Introduction

This manual provides comprehensive instructions for the installation, operation, and maintenance of your SNDOAS 30 inch Under Cabinet Range Hood. Designed for efficiency and ease of use, this range hood improves kitchen air quality by effectively removing smoke and grease. Please read this manual thoroughly before installation and use to ensure proper function and safety.



Front view of the SNDOAS 30 inch Under Cabinet Range Hood, showcasing its sleek design and integrated lighting.

Setup and Installation

The SNDOAS Under Cabinet Range Hood is designed for flexible installation, supporting both ducted (vertical/top venting) and ductless (recirculating) configurations. Ensure you have all necessary components and tools before beginning installation.

Product Dimensions and Clearance

The compact design of this range hood makes it suitable for various kitchen layouts, especially smaller spaces. Its dimensions are 29.92 inches (W) x 17.52 inches (L) x 4.69 inches (H).




Detailed dimensions of the range hood, including width, length, and height, essential for proper cabinet fitting.

Venting Options

This range hood offers two primary venting methods:

- **Vertical (Top Venting):** Requires an exhaust pipe (not included) to vent air outside.
- **Horizontal (Rear Venting):** Also vents air outside.
- **Ductless (Recirculating):** Utilizes a carbon cotton composite filter to clean and recirculate air back into the kitchen. An indoor baffle is required for external exhaust but not for internal recirculation.



Visual representation of the ducted and ductless venting configurations for the range hood.

Operating Instructions

Your SNDOAS range hood is equipped with user-friendly controls for efficient kitchen ventilation and illumination.

Fan Operation

The range hood features a 2-speed rocker switch to adjust the exhaust fan performance. The maximum airflow capacity is 230 CFM, effectively removing smoke and cooking odors while maintaining a low noise level.

- **Low Speed:** Ideal for light cooking and maintaining air circulation.
- **High Speed:** Recommended for heavy cooking, frying, or when significant smoke and odors are present.




Illustration of the two-speed rocker switch for controlling the exhaust fan, allowing adjustment for different cooking needs.

Integrated LED Lighting

A built-in energy-saving LED light illuminates your cooking area, providing clear visibility. The light is controlled by a separate rocker switch for convenience.



The range hood's integrated LED light illuminates the cooking surface, enhancing visibility during meal preparation.

Maintenance

Regular maintenance ensures the optimal performance and longevity of your range hood.

Filter Cleaning and Replacement

The range hood is equipped with a 3-layer aluminum mesh filter with carbon cotton composite, designed to effectively capture grease and odors. For optimal performance, clean the aluminum mesh filter regularly. If using the ductless mode, the carbon filter should be replaced periodically based on usage.



Exploded view of the 3-layer aluminum filter system, designed to efficiently remove grease and odors from the air.

Exterior Cleaning

Clean the exterior of the range hood with a soft cloth and mild detergent. Avoid abrasive cleaners or scouring pads, which can damage the stainless steel finish.

Troubleshooting

This section addresses common issues you might encounter with your range hood.

Problem	Possible Cause	Solution
Fan not operating	No power supply; Fan switch is off; Motor malfunction.	Check power connection and circuit breaker. Ensure fan switch is in the 'ON' position. If problem persists, contact customer service.

Problem	Possible Cause	Solution
Poor suction performance	Grease filters are clogged; Incorrect venting mode; Obstruction in ductwork.	Clean or replace grease filters. Verify correct venting mode (ducted or ductless) is set up properly. Check for blockages in the exhaust duct.
Excessive noise	Loose components; Fan blades are dirty or damaged; Improper installation.	Ensure all mounting screws are tightened. Clean fan blades. If noise persists, verify installation according to manual or contact customer service.
LED light not working	Light switch is off; LED bulb failure; Wiring issue.	Ensure light switch is in the 'ON' position. If the light is integrated and not user-replaceable, contact customer service.

Specifications

Key technical specifications for the SNDOAS 30 inch Under Cabinet Range Hood.

Feature	Detail
Model Number	GF3976WH
Dimensions (W x L x H)	29.92" x 17.52" x 4.69"
Air Flow Capacity	Max 230 CFM
Material	Stainless Steel
Mounting Type	Under Cabinet Mount, Insert Mount
Controls Type	Push Button (Rocker Switch)
Voltage	120 Volts
Number of Speeds	2
Light Source Type	LED
Filter Type	Mesh (3-layer aluminum with carbon cotton composite)
Ventilation Type	Exhaust (Ducted/Ductless Convertible)
Item Weight	12.77 pounds (5.81 kg)
Included Components	1x aluminum mesh filter with carbon cotton composite, 1x round air outlet, 1x indoor baffle, 1x user manual

Warranty and Support

SNDOAS provides a **ONE YEAR LIMITED WARRANTY** for this under cabinet range hood. This warranty covers defects in materials and workmanship under normal use.
For any problems, questions, or warranty claims, please contact SNDOAS customer service. Have your model number (GF3976WH) and purchase information ready for faster assistance.
You can find contact information on the official SNDOAS website or through your purchase platform.

© 2023 SNDOAS. All rights reserved.
For more information, visit the official SNDOAS Store.