Saved from manuals.plus.
Open the live page for links to other documents and user manuals.

UNIWEIGH P01

UNIWEIGH Digital Pet Scale P01 User Manual

Model: P01

1. Introduction

This manual provides detailed instructions for the safe and effective operation of your UNIWEIGH Digital Pet Scale P01. Please read this manual thoroughly before use and retain it for future reference.



Image: The UNIWEIGH Digital Pet Scale P01, featuring a small puppy comfortably positioned on its surface, demonstrating its use for weighing pets.

2. Safety Information

- Place the scale on a hard, flat, and stable surface to ensure accurate readings.
- Do not overload the scale beyond its maximum capacity of 100kg (220lbs).
- Keep the scale away from water and extreme temperatures.
- Clean the scale with a soft, damp cloth. Avoid abrasive cleaners.
- This scale is designed for weighing pets, babies, and individuals. Use for other purposes may result in damage or inaccurate readings.

3. Package Contents

Verify that all items are present in the package:

- UNIWEIGH Digital Pet Scale P01
- USB Charging Cable
- User Manual (this document)

4. Product Features

- **High Accuracy:** Precision sensors provide accurate measurements up to 100kg (220lbs) with 10g readability.
- **Large LED Display:** Clear and spacious LED display for easy reading of weight.
- **Multiple Weighing Units:** Switch between kilograms (kg), pounds (lb), and stones (st:lb).
- **Tare Function:** Easily subtract the weight of a container or blanket for net weight measurement.
- **Hold Function:** Stabilizes the reading for moving subjects, such as pets or babies.
- **Durable Construction:** Made with tempered glass for long-lasting performance.
- **Anti-Slip Design:** Equipped with anti-slip pads on the bottom for stability.
- **USB Charging:** Built-in rechargeable Lithium Polymer battery, charged via USB.
- **Auto Shut-Off:** Conserves battery life by automatically turning off after a period of inactivity.




Image: A detailed view of the scale's control panel, highlighting the Type-C charging port, Unit button (kg/lb/st:lb), and Power/Tare button.



Image: A close-up of the large LED display, showing the weight reading and the maximum capacity and accuracy.

5. Setup

1. **Unpack the Scale:** Carefully remove the scale and all accessories from the packaging.
2. **Placement:** Place the scale on a firm, flat, and level surface. Uneven surfaces can affect accuracy. Avoid placing it on carpets or soft flooring.
3. **Initial Charge:** Before first use, connect the scale to a USB power source using the provided USB charging cable. The display will show "CHAr" during charging and "FULL" when fully charged.
4. **Power On:** Press the **Tare** button to turn on the scale.



Image: The scale being charged via its USB port, indicating the charging process.

6. Operating Instructions

6.1 Power On/Off

- To turn on: Press the **Tare** button.
- To turn off: The scale will automatically shut off after a period of inactivity to conserve battery. You can also long-press the **Tare** button to manually turn it off.

6.2 Changing Weighing Units

- Press the **Unit** button to cycle through the available units: kilograms (kg), pounds (lb), and stones (st:lb).
- The selected unit will be displayed on the LED screen.
- To change the direction of the LED display for easier viewing from different angles, long-press the **Unit** button.

Your browser does not support the video tag.

Video: This video demonstrates the operation of the UNIWEIGH Digital Pet Scale, including changing weighing units (kg/lb/st:lb), using the tare function, and showing the display orientation change. It also highlights the scale's use for pets, body weight, and luggage.

6.3 Tare Function

The Tare function allows you to weigh items in a container or with a blanket, subtracting the weight of the container/blanket to get the net weight of the subject.

1. Place the empty container or blanket on the scale.
2. Wait for the weight to stabilize.
3. Press the **Tare** button. The display will reset to zero.
4. Place the pet or item to be weighed into/onto the container/blanket. The display will show the net weight.




Image: A cat resting on a blanket on the scale, illustrating the use of the Tare function to exclude the blanket's weight.


6.4 Weighing Pets and Babies

For best results, ensure the subject is as still as possible. The scale's hold function will assist in stabilizing the reading.

1. Turn on the scale and select your desired unit (kg, lb, or st:lb).
2. If using a blanket or container, perform the Tare function as described above.
3. Gently place the pet or baby onto the center of the scale platform.
4. Wait for the display to stabilize. The scale will automatically hold the final weight.
5. Remove the subject from the scale.

Multifunctional Use of Pet Scales

Capacity: 100kg/220lbs , Accuracy: ±10g



For Pet



For Baby



For Body Weight

Image: Demonstrates the versatility of the scale for weighing a cat, a baby, and an adult, highlighting its multi-purpose design.



Image: A baby lying on the scale, illustrating its use as a baby scale.

7. Maintenance

- **Cleaning:** Wipe the scale surface with a soft, slightly damp cloth. Do not use harsh chemicals, abrasive cleaners, or immerse the scale in water.
- **Storage:** Store the scale in a cool, dry place when not in use. Avoid placing heavy objects on the scale during storage.
- **Battery Care:** Recharge the scale when the battery indicator is low. Avoid completely draining the battery for extended periods to prolong its lifespan.

8. Troubleshooting

Problem	Possible Cause	Solution
Scale does not turn on.	Low battery.	Charge the scale using the USB cable.
Inaccurate readings.	Scale on an uneven or soft surface. Scale overloaded. Subject moving during measurement.	Place on a hard, flat surface. Ensure weight is within 100kg (220lbs) limit. Use the hold function or re-weigh when subject is calmer.
Display shows "Err".	Overload or internal error.	Remove weight from the scale. If error persists, contact customer support.
Display shows "Lo".	Low battery.	Recharge the scale.

9. Specifications

Feature	Detail
Model Number	P01
Capacity	100 kg / 220 lbs
Accuracy	10 g
Weighing Units	kg, lb, st:lb
Display Type	LED
Material	Tempered Glass
Power Source	Rechargeable Lithium Polymer Battery (USB Charging)
Platform Dimensions	27.16 x 12.99 inches (approx. 69 x 33 cm)
Special Features	Auto Shut Off, Bodyweight, High Weight Capacity, Large Display, Tare Function




Image: Diagram showing the length (27.16 inches) and width (12.99 inches) of the scale platform, along with its height (2.67 inches).

10. Warranty and Support

For warranty information or technical support, please refer to the contact details provided with your purchase documentation or visit the official UNIWEIGH website. Keep your purchase receipt as proof of purchase.

© 2025 UNIWEIGH. All rights reserved.

Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

https://manuals.plus/asin/B0D8Q5R5ZT

More documents and user manuals: **https://manuals.plus/**