

[Manuals.plus](#) /

› [mucar](#) /

› MUCAR OBD2 Scanner with 6 Systems 7 Reset Services, Wireless Car Diagnostic Tool with All System and 2 Reset User Manual

mucar B0DG553346

MUCAR OBD2 Scanner User Manual

Model: B0DG553346

1. INTRODUCTION

The MUCAR OBD2 Scanner is a professional wireless car diagnostic tool designed to provide comprehensive vehicle health analysis. It offers 6 system diagnoses, 7 essential reset services, and full system diagnostics, making it an indispensable tool for vehicle maintenance and troubleshooting. This manual provides detailed instructions for setting up, operating, and maintaining your MUCAR OBD2 Scanner.



Image 1: The MUCAR OBD2 Scanner device (left) showing its main menu with options like Diagnose, OBD, Maintenance, Update, History, File, Consult, and Settings. Below the device, icons indicate 6 System Diagnostics, 7 Reset Services, Auto VIN, and Lifetime Free Update.

On the right, a smartphone displays the MUCAR app interface, showing options for Diagnostics, OBD Function, I/M Readiness, VE Calculator, Maintenance (Oil, AFS, BLEED, ETS), Reports, and Vehicle Coverage Inquire. Below the phone, icons represent All System Diagnostics, Oil Reset, SAS Reset, Full OBD2 Modes, and Lifetime Free Update.

2. SETUP

2.1 Unboxing and Initial Inspection

Carefully remove all components from the packaging. Verify that all items are present and undamaged. The package should include the MUCAR OBD2 Scanner device and any necessary cables or adapters.

2.2 Powering On the Device

Connect the OBD2 scanner to your vehicle's OBD-II port, typically located under the dashboard on the driver's side. The device will power on automatically once connected to the vehicle's power supply.

2.3 App Installation and Pairing (for wireless models)

For wireless functionality, download the official MUCAR application from your smartphone's app store (iOS or Android). Follow the in-app instructions to pair your device with the scanner via Bluetooth. Ensure your smartphone's Bluetooth is enabled.

3. OPERATING INSTRUCTIONS

3.1 Vehicle Connection and AutoVIN

Once connected to the vehicle's OBD-II port, the scanner will automatically identify your car using its AutoVIN retrieval feature. This quickly scans the vehicle and provides additional diagnostic trouble codes, allowing you to keep and share records of previously tested vehicles.

3.2 Professional 6 System Diagnosis

This OBD2 scanner provides professional diagnostic services for six commonly used systems. Navigate to the "Diagnose" option on the scanner's main menu or within the app to access these functions. You will have the ability to read codes and ensure all safety measures are in place. Not only will you receive the code definition, but you will also be able to view possible causes and reported fixes for specific vehicle codes. The systems covered include:

- **ABS (Anti-lock Braking System):** Diagnoses issues related to the braking system.
- **SRS (Supplemental Restraint System):** Checks for faults in the airbag and seatbelt systems.
- **Transmission:** Identifies problems within the vehicle's transmission.
- **Engine:** Reads and clears engine fault codes, including the Check Engine Light.
- **BCM (Body Control Module):** Diagnoses issues with the vehicle's electronic body components.
- **TPMS (Tire Pressure Monitoring System):** Monitors tire pressure sensors and related faults.

3.3 7 Most Useful Reset Services

The scanner provides 7 additional fixed resets for lifetime free use. Access these services through the "Maintenance" section. These are essential for post-repair calibration and maintenance:

- **Oil Reset:** Resets the oil life reminder after an oil change.
- **EPB (Electronic Parking Brake) Reset:** Resets the electronic parking brake system after brake pad replacement.
- **SAS (Steering Angle Sensor) Reset:** Calibrates the steering angle sensor.
- **ETS (Electronic Throttle System) Reset:** Clears learned values and initializes the throttle body.
- **ABS Bleeding:** Helps remove air from the ABS system by performing an auto bleed after component changes (e.g., ABS module or master cylinder).
- **DPF (Diesel Particulate Filter) Regeneration:** Initiates the DPF regeneration process (for applicable diesel vehicles).
- **TPMS Reset:** Resets the TPMS system after tire rotation or sensor replacement.

3.4 Full System Diagnostics (MUCAR BT200)

The MUCAR BT200 is designed for comprehensive full system diagnostics. It covers all engines, SRS, ABS, TPMS, BCM, EPB, air conditioning, transmissions, instruments, and steering systems. This feature allows for a thorough scan of your vehicle's entire electronic system.

3.5 Viewing and Sharing Reports

After performing diagnostics, you can view detailed reports of the scanned data and trouble codes. The device and app allow you to save and share these reports for future reference or professional consultation.

4. MAINTENANCE

To ensure the longevity and optimal performance of your MUCAR OBD2 Scanner, follow these maintenance guidelines:

- **Cleaning:** Wipe the device with a soft, dry cloth. Avoid using abrasive cleaners or solvents.
- **Storage:** Store the scanner in a cool, dry place away from direct sunlight and extreme temperatures.
- **Software Updates:** Regularly check for and install software updates to ensure compatibility with new vehicle models and access to the latest features and bug fixes. Updates are typically available through the device's "Update" function or the MUCAR app.
- **Cable Care:** Inspect the OBD-II cable for any signs of wear or damage before each use.

5. TROUBLESHOOTING

If you encounter issues with your MUCAR OBD2 Scanner, refer to the following common troubleshooting steps:

- **Device Not Powering On:**
 - Ensure the scanner is securely connected to the vehicle's OBD-II port.
 - Verify that the vehicle's ignition is in the ON position (engine can be off).
 - Check the vehicle's fuse for the OBD-II port.
- **No Communication with Vehicle:**
 - Confirm the vehicle supports the OBD-II protocol (most vehicles manufactured after 1996 do).
 - Check for loose connections between the scanner and the vehicle.
 - Try the scanner on a different OBD-II compliant vehicle to rule out a vehicle-specific issue.
 - Ensure the scanner's software is up to date.
- **App Connection Issues:**
 - Ensure Bluetooth is enabled on your smartphone.
 - Restart both the scanner and your smartphone.
 - Re-pair the device through the MUCAR app's settings.
 - Check if the MUCAR app is updated to the latest version.
- **Inaccurate Readings or Missing Data:**
 - Ensure the correct vehicle information (make, model, year) is selected or correctly identified by AutoVIN.
 - Perform a software update.
 - Contact MUCAR customer support if the issue persists.

6. SPECIFICATIONS

Feature	Detail
Brand	MUCAR
Model (ASIN)	B0DG553346
System Diagnostics	6 Core Systems (ABS, SRS, Transmission, Engine, BCM, TPMS)
Reset Services	7 Lifetime Free Services (Oil, EPB, SAS, ETS, ABS Bleeding, DPF, TPMS)

Full System Diagnostics	Yes (MUCAR BT200 model)
Connectivity	Wireless (Bluetooth via app)
First Available Date	September 5, 2024

7. WARRANTY AND SUPPORT

MUCAR products typically come with a manufacturer's warranty. Please refer to the warranty card included with your product or visit the official MUCAR website for detailed warranty terms and conditions. For technical support, product inquiries, or warranty claims, please contact MUCAR customer service through their official website or the contact information provided in your product packaging.

No official product videos from the seller were found to be embedded in this manual.

© 2024 MUCAR. All rights reserved.

ASK A QUESTION ABOUT THIS MANUAL

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. [Privacy details](#).

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question