Xtrike Me GW-119

Xtrike Me GW-119 Wireless Mouse User Manual

Model: GW-119 | Brand: Xtrike Me

INTRODUCTION

This manual provides comprehensive instructions for the setup, operation, maintenance, and troubleshooting of your Xtrike Me GW-119 Wireless Mouse. Designed for versatility and comfort, this mouse offers reliable performance for various computing tasks.

PACKAGE CONTENTS

- Xtrike Me GW-119 Wireless Mouse
- USB Receiver (for 2.4G connection)
- 1 x Lithium Ion Battery (pre-installed or included)
- User Manual (this document)

SETUP

1. Battery Installation

The Xtrike Me GW-119 mouse requires one Lithium Ion battery, which is included. If not pre-installed, locate the battery compartment on the underside of the mouse. Open the cover, insert the battery according to the polarity indicators (+/-), and close the cover securely.

2. Connecting the Mouse

The GW-119 supports two connection types: 2.4G wireless via USB receiver and Bluetooth (BT).

2.1. 2.4G Wireless Connection

1. Locate the USB receiver, usually stored within the battery compartment or a dedicated slot on the mouse.
2. Plug the USB receiver into an available USB port on your computer.
3. Turn on the mouse using the power switch on its underside.
4. Your computer should automatically detect and install the necessary drivers. The mouse will be ready for use.

2.2. Bluetooth Connection

1. Ensure the mouse is powered on.
2. Activate Bluetooth on your computer or device.
3. Put the mouse into pairing mode (refer to the mouse's underside for a potential pairing button or switch, or consult the device's Bluetooth settings).
4. On your computer, search for new Bluetooth devices. Select "Xtrike Me GW-119" from the list of available devices to pair.
5. Once paired, the mouse is ready for use.

OPERATING INSTRUCTIONS

Basic Functions

- **Left Click:** Primary selection and activation.
- **Right Click:** Accesses contextual menus.
- **Scroll Wheel:** Scrolls content vertically. Can also be clicked for middle-click functionality (e.g., opening links in new tabs).

Figure 2: Top view of the mouse highlighting the left and right click buttons, and the scroll wheel.

DPI Adjustment

The GW-119 mouse features adjustable DPI (Dots Per Inch) settings, allowing you to change cursor sensitivity. The available DPI levels are 800, 1200, and 1600dpi. To cycle through these settings, press the DPI button, typically located near the scroll wheel. Each press will switch to the next DPI level.

Figure 3: The DPI button is located directly below the scroll wheel, allowing for quick sensitivity adjustments.

Maintenance

Cleaning

To maintain optimal performance and appearance, clean your mouse regularly. Use a soft, dry, lint-free cloth to wipe the surface. For stubborn dirt, slightly dampen the cloth with water or a mild, non-abrasive cleaner. Avoid using harsh chemicals or submerging the mouse in liquid.

Battery Care

- If the mouse will not be used for an extended period, it is recommended to turn off the power switch to conserve battery life.
- Replace the battery when performance degrades or the mouse becomes unresponsive.
- Dispose of used batteries responsibly according to local regulations.

Troubleshooting

Problem	Possible Cause	Solution
Mouse is unresponsive or erratic.	Low battery, poor connection, or interference.	- Replace the battery. - Ensure the USB receiver is securely plugged in (for 2.4G). - Re-pair the mouse via Bluetooth. - Move the mouse closer to the receiver/device. - Avoid using the mouse on highly reflective or transparent surfaces.
Cursor movement is too fast or too slow.	Incorrect DPI setting.	Press the DPI button to cycle through sensitivity settings (800/1200/1600dpi).
Mouse disconnects frequently.	Interference, distance, or low battery.	- Ensure no other wireless devices are causing interference. - Reduce the distance between the mouse and the receiver/device. - Replace the battery.

Specifications

Brand	Xtrike Me
Model	GW-119
Connection Type	2.4G Wireless / Bluetooth (BT)
DPI Settings	800-1200-1600dpi
Battery Type	1 x Lithium Ion (included)
Item Weight	100 g (0.1 Kilograms)
Package Dimensions	15.7 x 8 x 4.6 cm

Manufacturer	Shenzhen Xtrikeme Electronics Co.,Ltd

WARRANTY AND SUPPORT

For warranty information and technical support, please refer to the documentation provided at the point of purchase or contact your retailer. You may also visit the official Xtrike Me website for further assistance.

Manufacturer: Shenzhen Xtrikeme Electronics Co.,Ltd

Related Documents - GW-119

XTRIKE ME GW-610 User Manual • Uživatelský manuál • Uživateľský manuál • Használati utasítás • Benutzerhandbuch	[Xtrike Me GW-610 User Manual](#) User manual for the Xtrike Me GW-610 gaming mouse, detailing features, specifications, usage instructions, troubleshooting, and warranty information.
XTRIKE ME GM-226 User Manual • Uživatelský manuál • Uživateľský manuál • Használati utasítás • Benutzerhandbuch	[Xtrike Me GM-226 Gaming Mouse User Manual](#) User manual for the Xtrike Me GM-226 gaming mouse, detailing features, specifications, usage instructions, troubleshooting, and warranty information in multiple languages.
XTRIKE ME GM-520 User Manual • Uživatelský manuál • Uživateľský manuál • Használati utasítás • Benutzerhandbuch	[Xtrike Me GM-520 Gaming Mouse User Manual](#) User manual for the Xtrike Me GM-520 gaming mouse, detailing features, specifications, usage instructions, troubleshooting, and warranty conditions. Includes multilingual support.
XTRIKE ME CMX-415 User Manual • Uživatelský manuál • Uživateľský manuál • Használati utasítás • Benutzerhandbuch	[Xtrike Me CMX-415 Gaming Keyboard, Mouse, and Headset Combo User Manual](#) User manual for the Xtrike Me CMX-415 gaming combo, detailing features, specifications for keyboard, mouse, and headset, usage instructions, troubleshooting, warranty conditions, and EU conformity.

CASIO
Module No. 3159, 5610

■ ■ ⚏ ✦ ● ● ◈Ⓡ
Руководство по пользованию функциями часов
GW-5000/5510/5530/M5600/M5610/M5630/
S5600

Полное руководство пользователя для часов Casio G-Shock с модулями 3159 и 5610.

Описание функций, гарантии и международных сервисных центров.