Manuals+
Q & A | Deep Search | Upload

DDE5808MDL

GE Dryer Lint Screen Filter Replacement Part DDE5808MDL User Manual

Instructions for installation, operation, and maintenance of your replacement lint filter.

1. Product Overview

This document provides essential information for the DDE5808MDL replacement lint screen filter, designed for compatible GE dryer models. The lint filter is a critical component that captures lint and debris from your laundry during the drying cycle, preventing blockages and ensuring efficient and safe dryer operation.

Image shows the gray plastic frame of the lint filter with a fine mesh screen. Text on the frame reads 'CLEAN THIS LINT FILTER BEFORE EACH USE', emphasizing the importance of regular cleaning.

Regular inspection and cleaning of the lint filter are crucial for maintaining dryer performance and preventing potential fire hazards.

2. Safety Information

- **Always unplug the dryer from the power outlet**before attempting any installation, removal, or maintenance of the lint filter or any other dryer component.
- Ensure the dryer has cooled down completely if it was recently in use.
- Keep children and pets away from the appliance during maintenance.
- Do not operate the dryer without the lint filter properly installed.
- If you are unsure about any step, consult a qualified appliance technician.

3. Compatibility

This lint screen filter is a replacement part compatible with specific GE dryer models that use the DDE5808MDL part number. Appliance parts can appear similar, so it is essential to verify compatibility

before installation.

Before proceeding, please:

- Check your dryer's model number, typically found on a label inside the dryer door or on the back panel.
- Confirm that your dryer specifically requires part number DDE5808MDL.

4. Installation (Replacement)

Follow these steps to replace your dryer's lint screen filter:

1. **Disconnect Power:** Unplug the dryer from the electrical outlet to prevent electric shock.
2. **Locate Filter:** The lint filter is usually located in a slot either on top of the dryer or inside the dryer door opening.
3. **Remove Old Filter:** Grasp the handle of the existing lint filter and pull it straight out of its housing.
4. **Inspect Housing:** While the filter is out, inspect the filter housing for any accumulated lint or debris and carefully remove it.
5. **Insert New Filter:** Take the new DDE5808MDL replacement lint filter. Ensure it is clean and free of any packaging materials.
6. **Secure Filter:** Slide the new filter firmly into the filter slot until it is fully seated and flush with the dryer surface.
7. **Reconnect Power:** Plug the dryer back into the electrical outlet.

Your dryer is now ready for use with the new lint filter.

5. Operating Instructions

The lint filter operates automatically as part of the dryer's normal cycle. Its primary function is to collect lint from your clothes. For optimal performance and safety, it is imperative to clean the lint filter before **every single load** of laundry.

Operating the dryer with a clogged lint filter can lead to:

- Reduced drying efficiency, requiring longer drying times.
- Increased energy consumption.
- Overheating of the dryer.
- A significant fire hazard due to lint accumulation.

6. Maintenance

Regular cleaning of your lint filter is the most important maintenance task for your dryer. Follow these steps:

1. **Before Each Load:** Pull the lint filter out of its slot.
2. **Remove Lint:** Use your fingers to peel off the accumulated lint from the screen. Dispose of the lint in a waste bin.
3. **Reinsert Filter:** Slide the clean lint filter back into its slot until it is fully seated.
4. **Periodic Deep Cleaning (Every 6 months or as needed):**

- Remove the lint filter and clean off all visible lint.
- Wash the filter screen with warm, soapy water. Use a soft brush if necessary to remove any residue that may be clogging the mesh.
- Rinse the filter thoroughly under running water to remove all soap residue.
- Allow the filter to air dry completely before reinserting it into the dryer. Operating the dryer with a damp filter can cause issues.

A clean lint filter ensures proper airflow, which is vital for efficient drying and dryer longevity.

7. Troubleshooting

If you experience issues related to lint accumulation or drying performance, consider the following:

- **Dryer Not Drying Efficiently:**
  - *Solution:* Ensure the lint filter is clean before each load. Check the dryer vent hose for kinks or blockages.
- **Excessive Lint on Clothes:**
  - *Solution:* Perform a deep clean of the lint filter as described in the Maintenance section. Ensure the filter is properly seated.
- **Burning Smell:**
  - *Solution:* Immediately stop the dryer and unplug it. Check the lint filter and the dryer vent for severe blockages. Contact a technician if the smell persists after cleaning.

8. Specifications

Part Number	DDE5808MDL (FRIC-PL-APP-TP-22052025-019106)
Model Compatibility	Specific GE Dryer Models requiring DDE5808MDL
Manufacturer	Fricparts
Color	Black/White (as per product specifications)
Size	One Size (standard for DDE5808MDL)
Item Package Quantity	1

9. Warranty and Support

As a replacement part, specific warranty details may vary. Please refer to the original purchase documentation or contact the seller directly for information regarding warranty coverage and customer support for this DDE5808MDL lint filter.

For general dryer troubleshooting or service not related to the lint filter, please consult your GE dryer's official user manual or contact GE customer service.

Disclaimer: This manual provides general instructions for the DDE5808MDL replacement lint filter. Always prioritize safety and consult professional

assistance if needed. The manufacturer and seller are not responsible for damages resulting from improper installation or use.