Saved from manuals.plus.
Open the live page for links to other documents and user manuals.

VEVOR SH01

VEVOR Digital Shipping Scale 660 lbs

Model: SH01

1. Product Overview

The VEVOR Digital Shipping Scale is designed for accurate and reliable weighing of various items, including packages, postage, and luggage. With a maximum capacity of 660 lbs (300 kg) and an accuracy of 0.1 lbs (50 g), this scale provides precise measurements for diverse applications. It features a detachable LCD display, multiple weighing units, and convenient functions like Tare and Hold.



Image: The VEVOR Digital Shipping Scale, demonstrating its capacity and unit conversion capabilities with a dog on the platform.

Key Features:

- **High Capacity & Accuracy:** Weighs up to 660 lbs (300 kg) with 0.1 lbs (50 g) precision.
- **Multiple Units:** Easily switch between kilograms (kg), pounds (lb), and pounds:ounces (lb:oz).
- **Tare Function:** Deducts container weight for net weight measurement.
- **Hold Function:** Freezes the weight reading, useful for large items that obstruct the display.
- **Detachable LCD Display:** Provides clear readings and flexible placement options (wall-mounted or tabletop).
- **Dual Power Supply:** Operates with 3 AA batteries (included) or an AC/DC power adapter.
- **Durable Construction:** Crafted from stainless steel for long-lasting performance and stability.


Product Video:

▶ **Watch video online**
VEVOR Postal Scale

Video: An overview of the VEVOR Postal Scale, demonstrating its features and applications.

2. Included Components

Verify that all components are present in the package before proceeding with assembly and operation.



Item Model Number: SH01
Material: Stainless Steel
Maximum Weighing: 660 lbs / 300 kg
Minimum Weighing: 0.66 lbs / 300 g
Accuracy: 0.11 lbs/50 g
Weighing Units: kg,lb,lb:oz
Power Mode: 3 X AA Batteries(Included)
Product Weight: 33 lbs / 15 kg
Product Size: 41.0 x 22.6 x 2.2 in /1042 x 573 x 56 mm

Accessories

1 x User Manual 1 x Carrying Handle 1 x Screwdriver
1 x Wrench 1 x Adapter (with US Plug) 3 x AA Batteries
4 x Support Feet 4 x Screws 4 x Expansion Screws

Image: A visual representation of the scale's dimensions and a detailed list of all accessories included in the package.

- 1 x User Manual
- 1 x Carrying Handle
- 1 x Screwdriver
- 1 x Wrench
- 1 x Adapter (with US Plug)
- 3 x AA Batteries
- 4 x Support Feet
- 4 x Screws
- 4 x Expansion Screws

3. Safety Information

- Do not overload the scale beyond its maximum capacity of 660 lbs (300 kg).
- Place the scale on a stable, level surface to ensure accurate readings.
- Avoid exposing the scale to extreme temperatures, humidity, or direct sunlight.
- Keep the scale away from strong electromagnetic fields.
- Do not immerse the scale or display unit in water. Clean with a damp cloth.
- Use only the specified batteries and power adapter.
- If the scale is not used for an extended period, remove the batteries to prevent leakage.

4. Setup

4.1 Unpacking and Initial Inspection

Carefully remove all components from the packaging. Inspect for any damage that may have occurred during transit. Retain packaging for future storage or transport.

4.2 Attaching Support Feet and Handle

1. Turn the scale platform upside down.
2. Screw the four support feet into the designated holes on the underside of the platform. Adjust them to ensure the scale is level.
3. Attach the carrying handle to the side of the platform using the provided screws and screwdriver.

4.3 Connecting the Display Unit

Connect the coiled cable from the scale platform to the port on the back of the LCD display unit.



Image: The detachable LCD display unit can be wall-mounted or placed on a tabletop for flexible setup and space-saving convenience.

4.4 Powering the Scale

The scale can be powered by either AA batteries or the AC/DC power adapter.

- **Battery Power:** Open the battery compartment on the back of the display unit and insert 3 AA batteries, ensuring correct polarity.
- **AC/DC Power:** Plug the AC/DC adapter into a standard electrical outlet and connect the other end to the power input port on the display unit.

4.5 Placement

Place the scale on a firm, flat, and level surface. Uneven surfaces can lead to inaccurate measurements. Ensure the display unit is positioned where it can be easily read and operated.

5. Operating Instructions



Image: The control panel of the VEVOR Digital Shipping Scale, highlighting the functions of each button.

5.1 Power On/Off

- Press the **ON/OFF** button to turn the scale on.
- Press and hold the **ON/OFF** button to turn the scale off.

5.2 Unit Conversion

To switch between weighing units (kg, lb, lb:oz):

- With the scale on, press the**MODE** button repeatedly until the desired unit is displayed.

5.3 Tare Function

The Tare function allows you to subtract the weight of a container, so only the net weight of the contents is measured.



Image: Demonstrates the Tare function by showing how to weigh a pet in its bed, excluding the bed's weight.

1. Place the empty container on the scale platform.

2. Wait for the reading to stabilize.
3. Press the **TARE** button. The display will reset to zero.
4. Place the item(s) to be weighed into the container. The display will show the net weight of the item(s).

5.4 Hold Function

The Hold function allows you to lock the weight reading on the display, which is useful when weighing large items that might obscure the display.

1. Place the item on the scale platform.
2. Wait for the reading to stabilize.
3. Press the **HOLD** button. The current weight reading will be locked on the display.
4. You can now remove the item from the scale. The reading will remain displayed.
5. Press the **HOLD** button again to release the reading and return to normal weighing mode.

5.5 Auto-Off Setting

The scale features an auto-off function to conserve battery life. To adjust or disable this setting:

- With the scale on, press the**TARE** button to cycle through auto-off times (e.g., 0, 180, 300 seconds). Select '0' to disable auto-off.

5.6 Calibration Mode

For advanced users or if accuracy issues arise, the scale can be calibrated. Refer to the detailed user manual for specific calibration steps.

- Hold the **MODE** key until "Cal + Zero" flashes.
- Press **MODE** again to display "Cal > 100kg" flashing, then enter calibration mode.

6. Maintenance

6.1 Cleaning

- Wipe the scale platform and display unit with a soft, damp cloth.
- Do not use abrasive cleaners, solvents, or harsh chemicals, as these can damage the finish and electronic components.
- Ensure no liquid enters the display unit or the gaps around the platform.

6.2 Storage

- Store the scale in a dry, cool place, away from direct sunlight and extreme temperatures.
- If storing for an extended period, remove the batteries from the display unit to prevent potential leakage and damage.
- The carrying handle allows for easier transport and storage.

6.3 Battery Replacement

- When the battery indicator appears on the display, replace the 3 AA batteries in the display unit.

- Ensure correct polarity when inserting new batteries.

7. Troubleshooting

7.1 Scale Not Turning On

- Check if the batteries are correctly installed and not depleted. Replace if necessary.
- If using the AC adapter, ensure it is securely plugged into both the display unit and a working power outlet.
- Verify that the coiled cable connecting the platform to the display is securely attached.


7.2 Inaccurate or Fluctuating Readings

- Ensure the scale is placed on a completely flat and stable surface. Uneven surfaces can cause significant inaccuracies.
- Remove any objects from the scale platform before turning it on or performing a Tare operation.
- Avoid placing the scale near vibrating machinery or in drafty areas.
- If readings are consistently off, consider performing a calibration as described in section 5.6.
- Ensure the item being weighed is centered on the platform.

7.3 Display Shows "H" or Error Message

- "H" typically indicates an overload. Remove the item from the scale immediately to prevent damage.
- If an error message appears, try turning the scale off and then on again. If the error persists, contact customer support.

8. Specifications



Item Model Number: SH01
Material: Stainless Steel
Maximum Weighing: 660 lbs / 300 kg
Minimum Weighing: 0.66 lbs / 300 g
Accuracy: 0.11 lbs/50 g
Weighing Units: kg,lb,lb:oz
Power Mode: 3 X AA Batteries(Included)
Product Weight: 33 lbs / 15 kg
Product Size: 41.0 x 22.6 x 2.2 in /1042 x 573 x 56 mm

Accessories

1 x User Manual 1 x Carrying Handle 1 x Screwdriver
1 x Wrench 1 x Adapter (with US Plug) 3 x AA Batteries
4 x Support Feet 4 x Screws 4 x Expansion Screws

Image: Detailed technical specifications and dimensions of the VEVOR Digital Shipping Scale.

Item Model Number	SH01
Material	Stainless Steel
Maximum Weighing Capacity	660 lbs / 300 kg
Minimum Weighing	0.66 lbs / 300 g

Readout Accuracy	0.1 lbs / 50 g
Weighing Units	kg, lb, lb:oz
Power Mode	3 x AA Batteries (Included) / AC/DC Adapter
Product Weight	33.07 lbs / 15 kg
Product Size	41.0 x 22.6 x 2.2 in / 1042 x 573 x 56 mm
Display Type	LCD

9. Warranty and Support

VEVOR products are designed for durability and performance. For specific warranty details, please refer to the warranty card included with your product or visit the official VEVOR website.

If you encounter any issues or have questions regarding your VEVOR Digital Shipping Scale, please contact VEVOR customer support for assistance. Have your model number (SH01) and purchase information ready when contacting support.

Online Support: Visit the VEVOR official website for FAQs, troubleshooting guides, and contact information.

Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

https://manuals.plus/asin/B0G2W41YQC

More documents and user manuals: **https://manuals.plus/**