Manuals+ — User Manuals Simplified.

iCUE Software Release Notes Instruction Manual

**CORSAIR iCUE Software Release Notes
Instruction Manual**

Contents

iCUE Software Release Notes

For additional information about your products, visit **https://help.corsair.com/hc/en-us** for product support and FAQs.
For iCUE tutorials, visit our CORSAIR LAB YouTube channel: **https://www.youtube.com/playlist?list=PL8YayGMfPGnVq1c-tKd8r9NPqTWEmW9Ly**

Modular Installation

With the latest update to iCUE, we have changed how iCUE will be installed and updated from this point forward. With our new modular back end, iCUE will no longer consist of a single large package.

Instead, users will be downloading a very small installer that, when started, will uninstall existing versions of iCUE and automate the downloading and installation of modules.


To address the previous experience of iCUE having a large footprint (3+ GB), we have streamlined the experience by only installing what is required to support your products.

For example, if iCUE only detects a K100 RGB Air Wireless keyboard, then the software will only download two modules: iCUE Core and the K100 RGB Air Wireless module.

As a result, iCUE will no longer need to host the files to support products you currently do not own yet and will now only take up a fraction of the hard drive space compared to previous versions.

If, in the future, as you add more iCUE-supported products to your setup, iCUE will automatically detect them and install the additional modules you need for the products to be fully supported. Users will also be able to choose and install specific third-party plugins from our partners that share our ecosystem.

After this update, iCUE will no longer require a complete uninstallation and installation of the software for each update.

iCUE 5.3.102 Issues Resolved

Software Enhancements

- A new version of the iCUE plugin is now available in the Stream Deck store. The iCUE plugin now features CORSAIR audio features such as EQ change, microphone on/off toggle, surround sound toggle, battery widgets for wireless devices, and more!
  - Lenovo iCUE laptops now have Murals support
  - We have resolved an issue that caused some devices to no longer be detected after updating to Windows® 11 version 22H2
  - Murals Audio Lighting Effect will no longer cause iCUE to crash when the system is awakened from Sleep/Hibernate

HID Product Enhancements

- SoundID is now supported in iCUE for macOS®
- Resolved an issue with popping noises related to aggressive EQ settings in iCUE for macOS®
- Support has been added for iCUE LINK devices

DIY Product Enhancements

- The Clock Screen Effect for Elite LCD Coolers will no longer cause iCUE to crash

iCUE 5.2.128 Issues Resolved

Software Enhancements

- The iCUE plugin for Stream Deck has been vastly improved. Users can now populate their Stream Deck keys

to display any available sensor from the Dashboard. In addition, users will be able to toggle different cooling settings for their DIY devices, change the active Mural effect with a single button, and more

- iCUE-compatible motherboards and GPUs are now supported in Murals
- Users will now be able to choose different layout sizes (4:3 or 16:9) for Murals
- CPUID SDK has been updated
- Improved the stepping (1%) and the zoom range (1-200%) for the media editor when customizing an image for iCUE NEXUS, Profile Icons, Profile Backgrounds, Screen Settings (Elite LCD), and custom images/videos for Murals
- Long device names in Murals will no longer overlap the Hide Device button
- Unplugging a device will no longer reset the Murals layout(s)
- iCUE longer will no longer prevent an installation if the Portuguese language is selected

HID Product Enhancements

- Unplugging and re-connecting a Dark Core RGB/SE mouse will no longer result in a duplication of Lighting Effects
- Dark Core RGB/SE now properly shows the correct alternating colors for the Water Lighting Effect
- Harpoon RGB will now properly wake a system from sleep
- Resolved a detection issue associated with the HS80 Receiver

iCUE 5.1.1114 Issues Resolved

DIY Product Enhancements

- We were able to identify an issue with the XMP Profile Manager affecting users with CORSAIR DDR4 memory in iCUE. As a result, we have temporarily removed the XMP Profile Manager feature and will re-implement it once we are able to provide a fix. Users on existing versions of 5.0 and 5.1 should upgrade to this version of iCUE immediately.

We apologize for any inconvenience as a result of this problem, and any users that have issues with iCUE and their DRAM should reach out to our tech support team at **https://help.corsair.com/hc/enus/requests/new** for assistance.

iCUE 5.1.1113 Issues Resolved

Software Enhancements

- Resolved issues with missing iconography in Lighting Effects
- Various improvements have been made to module updates
- Improvements have been made to Murals to support resetting device sizes back to default and allowing users to simultaneously resize across different devices
- Color accuracy has been improved for the Monitor Screen effect in Murals on HDR-enabled monitors
- Users will now be able to reinstall a module after uninstalling it
- Resolved various issues with ASUS motherboard support

DIY Product Enhancements

- Images in iCUE will no longer disappear for Elite LCD after a firmware update
- Resolved issues with RGB DRAM lighting playback in a different direction other than what is configured

HID Product Enhancements

- iCUE Audio Driver has been updated with minor fixes
- Add Current Profile" is no longer missing from Dark Core RGB/SE

iCUE 5.0.147 Issues Resolved

Software Enhancements

- Dashboard sensors and plugins are now available as optional when no devices that rely on sensors are installed, this is part of the new modular update
- Resolved various bugs with iCUE Murals and improved the Murals Wizard
- Murals now has a "Send to Back" order feature when stacking device images on top of one another
- The coolant temp widget is no longer disabled when an Alert is triggered
- Retrying firmware updates through notifications will now properly restart the firmware update process
- Resolved an issue with scrolling when the pointer is hovering over the bottom of the Home screen
- Sensors and Fan widgets are no longer shown in random order on the Dashboard
- Resolved an issue that prevented Key Assignments to from being assigned to a key after the Clear feature was used

HID Product Enhancements

- K100 AIR and K65 MINI RGB will no longer cause a crash when creating a lighting effect from the Library while the devices are in wireless mode
- K65 MINI RGB will now properly show a tilda (~) when FN+Shift+Esc is pressed
- Resolved issues with Retain Original Key Output and Disable Key if Lock Button is On for certain keys for K65 MINI RGB
- Resolved an issue that prevented iCUE from detecting the keyboard on Voyager laptops

Documents / Resources

CUE iCUE Software Release Notes [pdf] Instruction Manual

iCUE Software Release Notes, iCUE, Release Notes, iCUE Release Notes, Software Release Notes