Manuals+ — User Manuals Simplified.

# Davis Instruments Universal Sensor Mounting Bracket Instructions

Contents [hide

Davis Instruments Universal Sensor Mounting Bracket

Universal Sensor Mounting Bracket

The Universal Sensor Mounting Bracket can be used to mount Solar Radiation or UV sensors. Install the sensor using the hardware and manual included with it.
Install the bracket using the included hardware:

- Two 1½" U-bolts,
- Three each: spacers, #6 split washers, 6 X 32 x 3/8" machine screws
- Four each: ¼-20 nuts, ¼" split lock washers, ¼" flat washers

Solar Radiation or UV Sensor
& Mounting Hardware
(not included)

Spacer

1 ½ " U-Bolt

¼-20 Nut

#6 Split Lock
Washer

¼" Split Lock Washer

¼" Flat Washer

6 x 32 x 3/8"
Machine Screw

Davis Instruments®

Documents / Resources

Davis Instruments Universal Sensor Mounting Bracket [pdf] Instructions
Universal Sensor Mounting Bracket, 6670

References

- **Davis Instruments**