Screen brightness adjustment steps

1 Long press the output button for five seconds to enter the setting interface

2 Press the knob three times to reach serial number **3**

3 Turn the knob to parameter **0**

Low brightness mode

3 Turn the knob to parameter **1**

High brightness mode

4 Press the knob to serial number **6** and continue to press it once to save the setting

Mute function setting steps

1 Long press the output button for five seconds to enter the setting interface

2 Press the knob three times to reach serial number **4**

3 Turn the knob to parameter **0**

Mute function on

3 Turn the knob to parameter **1**

Mute function off

4 Press the knob to serial number **6** and continue to press it once to save the setting