ZONDA 9-WASH SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V110	12-Mar-22	V1	First Release
			Error Record function added
V111	20-mai-22	V1	Minor bug fixes
V112	27-mai-22	V1	Color Preset bug fix
V120	13-déc.-22	V1	Chases improvements
			New SW for new PCB
			Pan & Tilt speeds improvements
V122	1-juin-23	V1	RDM functions improved
V123	12-mars-24	V123	Improved the CCT chanels
			Fixed the bug on USB
			Fixed the bug when play the chase, 2nd ring not taking the good back ground value under Ring control
			Corrected some chase effects
			Corrected background color in PIXLE mode
			Improve color shift problem.
			Added the menu of "Reset From MAC" for IP address
			Cut part of low-light value
			Corrected address issue
			Changed channels in Pixel Control Mode to keep it same as Zonda 9 FX
			Change dimmer curve to improve color shift problem in one situation
			Adjusted Chase and Color Preset
			Added Pixel Control Mode, modify DMX Channel and Menu
			Modes name changed to "Extended Ring" and "Extended Pixel"
V124	19-Jul-24	V124	Fix changing RGBW of chase affect background issue
			Fix changing speed of chase cause a flash issue
			Fix head temperature error issue
V125	6-Aug-24	V124	Fix the "DMX output" option
V130	25-Jun-25	V130	Fix a flash issue when using strobe, dim out and go to open with the dimmer at 0%
			Add Tungsten Simulation
			Improve Dimmer in Low level
			Correct the RDM Modele ID "AA86"
			Add Function to read and set address, universe and signal via Fixture Manager Software

NOTE: Updating software does not restore factory default settings