Epson LS12000/LS11000 B/W

Release Notes

Version 3.00

Bug fix

1) Fixed a problem when using Rear or Rear/Ceiling projection, turning on frame interpolation may result in abnormal picture quality.

2) Fixed a problem where sound would stop coming out of the sound bar connected via ARC if the HDMI cable on the device connected to HDMI1 was plugged in or unplugged during ARC connection

Version 2.01

The projector model identification information was modified. This does not affect the operation of the projector.

Version 2.00

1) Support for "Web Control" functions to add the following items in the projector's menu.

- Network Settings: Web Control Password

- Network Settings: Projector Control: Basic Control

Bug fix

1) Fixed an ARC connection issue

2) Fixed an image problem when connecting an Amazon FireTV Stick 4K and playing HDR10+