# SECTION 6
EXPLODED VIEWS

Note:
- -XX and -X mean standardized parts, so they may have some difference from the original one.
- Items marked "*" are not stocked since they are seldom required for routine service. Some delay should be anticipated when ordering these items.

- The mechanical parts with no reference number in the exploded views are not supplied.
- Color Indication of Appearance Parts Example:
  KNOB, BALANCE (WHITE) . . . (RED)
             ↑   ↑
   Parts Color Cabinet's Color

6-1. MAIN CHASSIS SECTION

Note: When the complete MAIN board (Ref. No. 1) is replaced, be sure to refer the following, and perform them.
- DESTINATION SETTING METHOD (Except IND3 model) (page 5)
- COMMUNICATION CHECK OF Apple CarPlay AND Android Auto (page 7)
- FLICKER ADJUSTMENT (page 25)

6-2. FRONT PANEL SECTION

Note 1: Replaced old complete TFT board (Ref. No. 54) is destroyed with the hammer, and throw out it.

Note 2: When the complete TFT board (Ref. No. 54) is replaced, be sure to refer the following, and perform them.
- COMMUNICATION CHECK OF Apple CarPlay OR Android Auto (page 7)
- FLICKER ADJUSTMENT (page 25)

Note 3: When the TFT (6.5) (Ref. No. LCD1) is replaced, refer to "FLICKER ADJUSTMENT" on page 25.

Note 4: When the touch panel (Ref. No. TPN1) is replaced, refer to "TOUCH PANEL ADJUST" on page 9.

XAV-AX100/AX100C2
Ver. 1.4

(AX100: AEP, UK/AX100C2: AEP)

501

BRACKET
× 1

502

RELEASE KEY
× 2

(AX100: IND, IND3)

504

COLLAR ASSY
(SOFT TYPE COLLAR WITH
DOUBLE-SIDED TAPE)
× 1

503

HARD COLLAR
× 1

**(AX100: AEP, UK
/AX100C2: AEP)**

505

POWER SUPPLY
CONNECTION CABLE (ISO)
× 1

**(AX100: US, CND, E, AUS,
IND/AX100C2: E)**

505

POWER SUPPLY
CONNECTION CABLE
× 1

(AX100: IND3)

505

POWER SUPPLY
CONNECTION CABLE
× 1

506

MICROPHONE
× 1

DOUBLE-SIDED TAPE
× 1

MICROPHONE UNIT
× 1

507

EXTENSION USB CABLE
× 1

508

STOPPER
× 1

509

+K5 × 8
× 4

**(AX100: IND: Supplied with
Serial No. 7104601 or larger,
AX100: IND3)**

510

CONNECTION CABLE
(RC-SR1)
× 1

Note 1: The MICROPHONE UNIT (Ref. No. 506) supplied with this
unit has been changed in the midway of production. Refer to
the figure below when replacing the MICROPHONE UNIT.

BLACK : Former type
GREEN : New type

Note 2: The CABLE FOR AUTOMOBILE (RC-SR1) (Ref. No. 510)
has been added only to AX100: IND model in the midway of
production.
Serial No. 7104600 or smaller : Not supplied
Serial No. 7104601 or larger   : Supplied
(This part attaches to all AX100: IND3 model)