starlab S7166-0010 ErgoOne Fast Pipette Controller User Manual

starlab S7166-0010 ErgoOne Fast Pipette Controller

Contents

## Removing the discharge protector

Prior to first usage please proceed as follows:

1. Slide the battery compartment lid open.

2. Remove the battery and discharge protection.

3. Install the battery and close the battery compartment lid.

## Battery status display

Ready for operation:

1. **Solid green light:**
   The rechargeable battery is fully charged.


2. **Solid yellow light:**
   The rechargeable battery is half-charged.

3. **Solid red light:**

   The rechargeable battery is almost empty.

Charge battery:

- **Flashing red light:**

 The rechargeable battery is <5% charged.

- **Flashing yellow light:**

 The rechargeable battery is 5-60% charged.

- **Flashing green light:**

  The rechargeable battery is 60-99% charged.

Empty battery

- **Flashing red light:**
  The rechargeable battery needs to be charged.

Loading battery

3 h

Speed control

The liquid aspiration speed is regulated continuously by controlling the pressure on the control buttons, i.e. how far in the button is pressed.

Slow aspiration

To slowly aspirate or dispense liquid, press the corresponding control button lightly.

Quickly aspirating

To quickly aspirate or dispense liquid, press the corresponding control button firmly.

Passonate for science.

Documents / Resources

	starlab S7166-0010 ErgoOne Fast Pipette Controller [pdf] User Manual S7166-0010, ErgoOne Fast Pipette Controller