



ALICAT KC-100 CODA Touchscreen Interface User Guide

[Home](#) » [ALICAT](#) » ALICAT KC-100 CODA Touchscreen Interface User Guide 




A Hama COMPANY

Contents

- [1 CODA Touchscreen Interface](#)
- [2 Troubleshooting](#)
- [3 Documents / Resources](#)
- [4 Related Posts](#)

CODA Touchscreen Interface


Quick Start Guide: Controllers



1. Use a Micro-USB cable to connect power to the display, and wait for the device to initialize. You may see a “device not found” error, which is not a problem at this point.
2. Connect a USB-A to a USB-C cable between the display and the controller or meter.
3. Connect power to the controller via DB-15 cable.

Download the full manual: alicat.com/coda

- 1.




Use a Micro-USB cable to connect power to the display, and wait for the device to initialize. You may see a “device not found” error, which is not a problem at this point.

2. Connect a USB-A to a USB-C cable between the display and the controller or meter.


Troubleshooting

- **Questions:** +1 520-290-6060
- info@alicat.com
- Live web chat at alicat.com



DOC-MANUAL-CD-QUICK

Documents / Resources



[ALICAT KC-100 CODA Touchscreen Interface](#) [pdf] User Guide
KC-100, KC-1K, KC-10K, KC-100 CODA Touchscreen Interface, CODA Touchscreen Interface

Manuals+.