

KERBL 29920

KERBL DigiScale 50 Digital Hanging Scales Instruction Manual

Model: 29920

INTRODUCTION

Thank you for choosing the KERBL DigiScale 50 Digital Hanging Scales. This manual provides essential information for the safe and efficient operation of your device. Please read these instructions carefully before use and retain them for future reference.

The KERBL DigiScale 50 is designed for fast and reliable weighing of items up to 50 kg. It features high accuracy, a pull-out measuring tape, and multiple display units.

PACKAGE CONTENTS

- KERBL DigiScale 50 Digital Hanging Scales (Model 29920)
- Batteries (pre-installed or included separately)

PRODUCT OVERVIEW

Familiarize yourself with the components of your DigiScale 50.



Image 1: Front view of the KERBL DigiScale 50, showing the digital display, ON/OFF, TARE, and SET buttons, and the hanging hook and handle.

- **Display:** LCD screen for weight readings and unit indication.
- **ON/OFF Button:** Powers the scale on or off.
- **TARE Button:** Resets the display to zero, useful for weighing items in a container.
- **SET Button:** Used to change weighing units (kg/lb/oz) and temperature unit (°C).
- **Hanging Hook:** For attaching items to be weighed.
- **Handle:** For holding the scale during weighing.
- **Measuring Tape:** Pull-out tape for length measurements (100 cm).

SETUP

1. Battery Installation

The DigiScale 50 is supplied with batteries. If replacement is needed:

1. Locate the battery compartment on the back of the scale.
2. Open the compartment cover.
3. Insert new batteries, ensuring correct polarity (+/-).
4. Close the battery compartment cover securely.

2. Initial Power On

Press the **ON/OFF** button to turn on the scale. The display will show "8888" and then "0.00" or "0.0" with the current unit.

OPERATING INSTRUCTIONS

1. Weighing an Item

1. Ensure the scale is powered on and displaying "0.00".
2. Hold the scale by its handle.

3. Carefully attach the item to be weighed to the hanging hook.
4. Wait for the display to stabilize. The weight will be shown.
5. The scale features a data hold function, which will lock the stable weight reading on the display.

2. Changing Weighing Units

With the scale powered on, press the **SET** button repeatedly to cycle through the available units: kg (kilograms), lb (pounds), oz (ounces), and °C (Celsius for temperature display).

3. Tare Function

The Tare function allows you to weigh items in a container by subtracting the container's weight.

1. Hang the empty container on the hook.
2. Wait for the display to stabilize.
3. Press the **TARE** button. The display will reset to "0.00".
4. Place the item to be weighed into the container. The display will show the net weight of the item.

4. Using the Measuring Tape



Image 2: A hand pulling out the integrated measuring tape from the side of the KERBL DigiScale 50, demonstrating its use for length measurement.

The DigiScale 50 includes a retractable measuring tape for convenience. Gently pull the tape from its housing to extend it.

After use, guide it back into the housing.

5. Automatic Shutdown

To conserve battery life, the scale will automatically turn off after a period of inactivity.

MAINTENANCE

- Clean the scale with a soft, damp cloth. Do not use abrasive cleaners or immerse the device in water.
- Store the scale in a dry place, away from extreme temperatures and direct sunlight.
- If the scale will not be used for an extended period, remove the batteries to prevent leakage.

TROUBLESHOOTING



Problem	Possible Cause	Solution
Scale does not turn on.	Dead or incorrectly installed batteries.	Replace batteries or check polarity.
Inaccurate readings.	Scale not stable, overloaded, or on an uneven surface.	Ensure scale is held steadily. Do not exceed 50 kg capacity. Use on a stable surface.
Display shows "Err" or "O-Ld".	Overload.	Remove the item immediately. Do not exceed the maximum capacity of 50 kg.


SPECIFICATIONS

- **Model:** 29920
- **Brand:** KERBL
- **Maximum Capacity:** 50 kg
- **Display Type:** LCD
- **Units:** kg, lb, oz, °C
- **Special Features:** Lightweight, Portable, Smart, Data Hold Function, Automatic Shutdown, Integrated 100 cm Measuring Tape.
- **Power Source:** Batteries (included)
- **Color:** Black
- **Dimensions (Package):** 5.67 x 3.19 x 1.42 inches

WARRANTY AND SUPPORT

For warranty information or technical support, please refer to the contact details provided with your purchase or visit the official KERBL website. Keep your proof of purchase for warranty claims.


 AniScale #291322 - Bedienungsanleitung - Mode d'emploi - Istruzioni per uso - Instrucciones per l'uso - Gebruiksaanwijzing MAX 750 kg KERBL	AniScale Animal Scale #291322 - Operating Instructions Operating instructions for the KERBL AniScale Animal Scale #291322, detailing setup, operation, safety precautions, and technical specifications for weighing animals up to 1500 kg.
 KERBL	PS 1000/PS 2000/PS 3000 Quick User Guide This guide provides essential information for the installation, operation, and maintenance of the Kerbl PS 1000, PS 2000, and PS 3000 scales. It covers safety precautions, electrical installation, routine maintenance, cleaning, and operational features such as zeroing, taring, unit selection, hold mode, and printing.
 #291365 #291366 Wiegebalken-Set mit Displayanzeige Kit de barres de pesée avec écran d'affichage Weighing Loadbar Set with Display Set di barre per pesatura con display Weegbalkenset met display - Bedienungsanleitung - Mode d'emploi - Operating Instructions - Istruzioni per l'uso - Gebruiksaanwijzing - Keypoints KERBL	KERBL Weighing Loadbar Set with Display Operating Instructions Comprehensive operating instructions for the KERBL Weighing Loadbar Set with Display (models #291365, #291366), covering setup, functions, maintenance, and troubleshooting. Available in multiple languages.
 KERBL Automatische Hühnertür EasyProtect Porte de poules automatisée EasyProtect Automatic Chicken Door EasyProtect Automatyczna Drzwi dla Kura EasyProtect Hühner	KERBL EasyProtect Automatische Hühnertür Bedienungsanleitung Die KERBL EasyProtect Automatische Hühnertür automatisiert das Öffnen und Schließen der Stalltür für Geflügelhalter. Sie funktioniert über Zeitsteuerung oder Lichtsensor und erhöht die Sicherheit und den Komfort im Hühnerstall. Dieses Handbuch bietet detaillierte Anleitungen zur Installation, Bedienung und Wartung.
 PS 1000 / PS 2000 / PS 3000 Kalibrierung Calibration KERBL	PS1000/PS2000/PS3000 Scale Calibration Guide This guide provides instructions for calibrating the Kerbl PS1000, PS2000, and PS3000 scales, including parameter settings and calibration procedures.
 KERBL	Kerbl Heat Lamp 22318: Operating Instructions and Safety Guide Comprehensive operating instructions and safety guidelines for the Kerbl Heat Lamp 22318, designed for chick rearing and young animal heating. Includes specifications, installation, recommended lamps, and safety precautions.



[\[pdf\]](#) User Manual Instructions Declaration of Conformity

Instruction manual 182996 kerbl ftp product doc |||


SV Digital hängvg DigiScale 50 Produktbeskrivning: Brbara hängvgar r moderna vgningsenheter som impon ... ion Funktioner: Modell Vgningsomrde max Avlsningsbarhet/ Vgningsomrde kalibreringsvrde min **29920** 50 kg d = 20 g e = 40 g 400 g Display: Viktvisning: 4-siffrig Funktionsversikt: Automat...
lang:no **score:49** filesize: 120.48 K page_count: 2 document date: 2022-03-29



[\[pdf\]](#)

29920 BA Digitalwaage 441x210 screen kerbl ftp prod documents |||

SV Digital hängvg DigiScale 50 Produktbeskrivning: Brbara hängvgar r moderna vgningsenheter som impon ... ion Funktioner: Modell Vgningsomrde max Avlsningsbarhet/ Vgningsomrde kalibreringsvrde min **29920** 50 kg d = 20 g e = 40 g 400 g Display: Viktvisning: 4-siffrig Funktionsversikt: Automat...
lang:no **score:28** filesize: 302.25 K page_count: 2 document date: 2017-12-04



[\[pdf\]](#) Instructions

1207650 GG Bruksanvisning 222 KB Digital våg Kerbl 50kg granngarden se productassets 9a3da8d7 61a1 4f1e ba7c 115f6c25b238 gg bruksanvisning |||

SV Digital hängvg DigiScale 50 Produktbeskrivning: Brbara hängvgar r moderna vgningsenheter som impon ... ion Funktioner: Modell Vgningsomrde max Avlsningsbarhet/ Vgningsomrde kalibreringsvrde min **29920** 50 kg d = 20 g e = 40 g 400 g Display: Viktvisning: 4-siffrig Funktionsversikt: Automat...
lang:no **score:19** filesize: 221.82 K page_count: 2 document date: 2014-08-29

[\[pdf\]](#) Instructions

ANVÄNDNING VARNING SÄKERHETSINSTRUKTIONERDigital hängvåg DigiScale 50 kalibrerbar upp till kg521500 bda kerbl digiscale50media lantkompaniet se 521500 digiscale50

SÄKERHETSINSTRUKTIONERBEDIEN WARN SICHERHEITSHINWEISEDigital kgDigitale Hängewaage

kalibrierfähig bis 50kg521500 digiscale50521500 weidezaun info de ||| ||| SV Digital hängvg DigiScale 50

Produktbeskrivning: Brbara hängvgar r moderna vgningsenheter som imponerar genom sin tilltalande design, behndiga storlek och hur lita de r att transportera. Genom multifunktionssystemet och den hga vgningsexakt

SV Digital hängvg DigiScale 50 Produktbeskrivning: Brbara hängvgar r moderna vgningsenheter som impon ... ion Funktioner: Modell Vgningsomrde max Avlsningsbarhet/ Vgningsomrde kalibreringsvrde min **29920** 50 kg d = 20 g e = 40 g 400 g Display: Viktvisning: 4-siffrig Funktionsversikt: Automat...
lang:no **score:18** filesize: 120.48 K page_count: 2 document date: 2022-03-29



[\[pdf\]](#)

DigiScale 50 299201207650 gg bruksanvisninggranngarden se productassets 9a3da8d7 61a1 4f1e ba7c 115f6c25b238 1207650 bruksanvisning |||

SV Digital h ngv g DigiScale 50 Produktbeskrivning: B rbara h ngv gar r moderna v gningsenh ... ner: Modell V gningsomr de max Avl sningsbarhet/ V gningsomr de kalibreringsv rde min **29920** 50 kg d = 20 g e = 40 g 400 g Display: Viktvisning: 4-siffrig Funktions versikt: Au...
lang:no **score:13** filesize: 221.82 K page_count: 2 document date: 2014-08-29