

## Omix-Ada 17477.14

# Omix-Ada 17477.14 Engine Valve Cover Gasket Instruction Manual

For 1983-2002 Jeep CJ / Wrangler YJ 2.5L Engines

## 1. PRODUCT OVERVIEW

The Omix-Ada 17477.14 Engine Valve Cover Gasket is a high-quality replacement component designed to ensure a proper seal for your engine's valve cover. This gasket is crucial for preventing oil leaks and maintaining optimal engine performance. It is constructed from durable rubber to meet or exceed original equipment (OE) standards.

### Key Features:

- **Direct Fitment:** Specifically designed for 1983-2002 Jeep CJ and Wrangler YJ models equipped with 2.5L engines.
- **OE Reference:** Replaces OE part number 3241731.
- **Durable Material:** Made from robust rubber for long-lasting performance and a reliable seal.
- **Quality Assurance:** Manufactured to meet or exceed factory quality standards.




Image: Omix-Ada 17477.14 Engine Valve Cover Gasket, a black rubber gasket with multiple bolt holes, designed to seal the engine valve cover.

## 2. INSTALLATION INSTRUCTIONS

Proper installation of the valve cover gasket is essential for preventing oil leaks and ensuring engine longevity. If you are not experienced with automotive repairs, it is recommended to seek professional assistance or consult a detailed service manual for your specific vehicle model.

### Required Tools and Materials:

- Socket set and ratchet
- Torque wrench
- Scraper or plastic razor blade
- Brake cleaner or degreaser
- Clean rags or shop towels
- RTV sealant (optional, as per vehicle manufacturer's recommendation)

### Installation Steps:

1. **Preparation:** Ensure the engine is completely cool before beginning work. Disconnect the negative terminal of the vehicle's battery. Remove any components obstructing access to the valve cover (e.g., air intake, wiring harnesses, spark plug wires).
2. **Remove Valve Cover:** Loosen and remove the bolts securing the valve cover. Carefully lift the valve cover off the cylinder head. If it's stuck, gently pry it loose with a plastic tool to avoid damaging the mating surfaces.
3. **Remove Old Gasket:** Remove the old gasket from the valve cover and the cylinder head. Inspect both surfaces for any remaining gasket material, hardened sealant, or debris.
4. **Clean Surfaces:** Thoroughly clean both the valve cover and cylinder head mating surfaces. Use a

scraper or plastic razor blade to remove all old gasket material and sealant. Finish by cleaning with brake cleaner or degreaser and a clean rag to ensure surfaces are free of oil and residue. A clean surface is critical for a proper seal.

5. **Install New Gasket:** Place the new Omix-Ada 17477.14 gasket onto the valve cover. Ensure it is seated correctly in the grooves. Some gaskets may have metal inserts or specific orientations; refer to your vehicle's service manual if unsure. Apply a thin bead of RTV sealant to specific areas if recommended by your vehicle's service manual (e.g., corners where the cylinder head meets the timing cover).
6. **Reinstall Valve Cover:** Carefully place the valve cover back onto the cylinder head, ensuring the gasket remains properly seated. Hand-tighten the valve cover bolts.
7. **Torque Bolts:** Using a torque wrench, tighten the valve cover bolts to the manufacturer's specified torque settings. It is crucial to follow the correct tightening sequence (usually from the center outwards in a spiral pattern) to ensure even pressure and prevent warping. Consult your vehicle's service manual for specific torque values and sequence.
8. **Reassemble Components:** Reinstall all previously removed components, including wiring, hoses, and the air intake system. Reconnect the negative battery terminal.
9. **Test for Leaks:** Start the engine and allow it to reach operating temperature. Carefully inspect around the valve cover for any signs of oil leaks. Address any leaks immediately.

### 3. OPERATION

---

The Omix-Ada 17477.14 Engine Valve Cover Gasket functions as a critical seal between the engine's valve cover and the cylinder head. Its primary role is to contain engine oil within the valve train area, preventing it from leaking out and contaminating other engine components or the environment. A properly installed and functioning gasket ensures that the engine's lubrication system operates efficiently and without loss of oil pressure due to external leaks.

### 4. MAINTENANCE

---

While the valve cover gasket itself does not require routine maintenance, regular inspection of the engine compartment is recommended to ensure its continued integrity.

#### Maintenance Checks:

- **Visual Inspection:** Periodically check the area around the valve cover for any signs of oil seepage or leaks. Look for oil stains on the valve cover, cylinder head, or engine block below the valve cover.
- **Cleanliness:** Keep the engine compartment clean to easily spot any new leaks.
- **Torque Check:** If you suspect a minor leak, you may attempt to re-torque the valve cover bolts to the manufacturer's specifications. However, overtightening can damage the gasket or valve cover, so proceed with caution and use a torque wrench.

If significant leaks are observed, the gasket may need to be replaced again, or there might be other underlying issues requiring professional diagnosis.

### 5. TROUBLESHOOTING

---

Most issues related to a valve cover gasket involve oil leaks. Here are common problems and potential solutions:

#### Common Issues:

- **Oil Leak After Installation:**

- **Cause:** Improper cleaning of mating surfaces, incorrect torque sequence or values, damaged gasket during installation, or warped valve cover.
- **Solution:** Re-check bolt torque and sequence. If the leak persists, remove the valve cover, thoroughly clean surfaces again, inspect the gasket for damage, and reinstall carefully. Consider checking the valve cover for warping.

- **Persistent Oil Smell:**

- **Cause:** Small oil leak dripping onto hot exhaust components.
- **Solution:** Inspect for very small leaks around the valve cover. Even minor seepage can cause a smell. Address any leaks found.

- **Gasket Does Not Fit Correctly:**

- **Cause:** Incorrect part for your vehicle model or engine.
- **Solution:** Verify the part number (Omix-Ada 17477.14) against your vehicle's specifications (1983-2002 Jeep CJ / Wrangler YJ 2.5L). Ensure the gasket is not folded or damaged from packaging.

If troubleshooting steps do not resolve the issue, consult a certified mechanic.

## 6. SPECIFICATIONS

Specification	Detail
Brand	Omix-Ada
Model Number	17477.14
Material	Rubber
Item Thickness	0.25 Inches
Color	Black
Shape	Round (referring to the overall shape of the gasket's sealing path)
OEM Part Number	3241731
Product Dimensions	21 x 5.5 x 0.25 inches
Item Weight	1.13 ounces
UPC	804314228217

## 7. WARRANTY INFORMATION

The Omix-Ada 17477.14 Engine Valve Cover Gasket comes with a **Limited 5-Year Warranty**. This warranty covers defects in materials and workmanship under normal use. For specific terms, conditions, and claim procedures, please refer to the official Omix-Ada warranty documentation or contact customer support.

Additionally, purchases made through Amazon typically include a 30-day return/replacement policy, fulfilled by Amazon.

## 8. CUSTOMER SUPPORT

---

For further assistance, technical questions, or warranty claims regarding your Omix-Ada 17477.14 Engine Valve Cover Gasket, please contact Omix-Ada customer support directly. You can typically find contact information on the manufacturer's official website or through the retailer where the product was purchased.

## 9. OMIX-ADA BRAND OVERVIEW

---

Omix-Ada is a trusted leader and resource for Willys & Jeep restoration, offering a wide range of replacement parts and accessories. The following video provides an overview of the Omix-Ada brand and its commitment to quality automotive parts.

Video: An official brand video from Omix-Ada (via Rugged Ridge), showcasing the company's dedication to Jeep restoration and the quality of their replacement parts. This video provides insight into the brand's heritage and product philosophy.