



[Manuals.plus](#) /

> [NEWLINE NY](#) /

> NewlineNY Auto Step On Super Mini Travel Bathroom Scale User Manual

## NEWLINE NY SBB0638SMTW

# NewlineNY Auto Step On Super Mini Travel Bathroom Scale User Manual

Model: SBB0638SMTW | Brand: NEWLINE NY

## INTRODUCTION

---

The NewlineNY Auto Step On Super Mini Travel Bathroom Scale is designed for convenience and accuracy, especially for those on the go or with limited space. Its compact and lightweight design makes it an ideal travel companion, while its advanced features ensure consistent and reliable weight measurements. This manual provides comprehensive instructions for setting up, operating, maintaining, and troubleshooting your scale.



Image: The NewlineNY Super Mini Travel Bathroom Scale, showcasing its compact design and digital display.

## SETUP

---

- Battery Installation:** The scale requires 1 C battery (CR2032), which is included. Locate the battery compartment on the underside of the scale. Remove the plastic insulator strip if present before first use. Ensure the battery is inserted with the correct polarity.
- Placement:** For accurate readings, always place the scale on a hard, flat, and level surface. Avoid carpets or uneven flooring, as this can affect measurement consistency.
- Unit Selection:** On the underside of the scale, you will find a switch to select your preferred unit of measurement: kilograms (kg), pounds (lb), or stones (st). Slide the switch to your desired unit. The selected unit will be displayed on the screen.
- Initial Calibration:** Before your first use or after moving the scale, perform an initial calibration. Briefly step on the scale with one foot, then step off. The display should show '0.0' (or '0.00' depending on the unit) indicating it's ready for use.



Image: The underside of the scale, highlighting the battery compartment and the unit selection switch (kg/lb/st).

## OPERATING INSTRUCTIONS

---

The NewlineNY scale features an auto 'Step-on' technology for quick and easy measurements.

1. **Step On:** Gently step onto the center of the scale. The display will briefly show a red light, indicating it is weighing.
2. **Wait for Green Light:** Continue standing still until the red light turns green. This indicates the weight has been correctly measured.
3. **View Weight:** Step off the scale. Your weight will be displayed on the 3.5-inch extra-large LCD for approximately 10 seconds before the scale automatically turns off to preserve power.



Image: A user's feet on the scale, demonstrating the weighing process and the digital display showing a weight reading.

Video: Official product video demonstrating the ease of use and features of the NewlineNY 600 Series Digital Scale,

including the step-on function and compact size.

## MAINTENANCE

- **Cleaning:** To clean the scale, wipe it with a damp cloth and mild detergent. Do not use abrasive cleaners or immerse the scale in water.
- **Storage:** When not in use, especially during travel, store the scale in its protective sleeve to prevent scratches and damage. Its thin profile allows it to fit neatly into luggage or vanity drawers.
- **Battery Replacement:** If the display becomes dim or shows a low battery indicator, it's time to replace the CR2032 battery. Open the battery compartment on the underside, remove the old battery, and insert a new one, ensuring correct polarity.



Image: A side view of the NewlineNY scale, emphasizing its ultra-thin design for easy portability and storage.

## TROUBLESHOOTING

Problem	Possible Cause	Solution
Inaccurate Readings	Scale not on a flat, hard surface; initial calibration not performed; unstable surface.	Ensure the scale is on a firm, level floor. Perform initial calibration by stepping on and off once. Avoid placing on carpets or rugs.
No Display / Scale Not Turning On	Battery is dead or incorrectly installed; plastic insulator strip not removed.	Check battery installation and replace if necessary. Ensure the plastic insulator strip has been completely removed from the battery compartment.
Display shows 'Lo'	Low battery.	Replace the CR2032 battery.
Display shows 'Err' or 'O-Ld'	Overload beyond maximum capacity.	The scale's maximum capacity is 325 lbs (150 kg). Remove weight immediately to prevent damage.

## SPECIFICATIONS

Feature	Detail
Model Number	SBB0638SMTW
Product Dimensions	5.5 x 8.5 x 0.5 inches
Weight	1.2 Pounds (approximately 20 oz)
Weight Limit	Up to 325 Pounds (150 kg)
Graduation Increments	0.2 lb / 0.1 kg
Display Type	LED (3.5" Extra Large Display)
Battery Type	1 x CR2032 (included)
Color	White
Form Factor	Mini



Image: A diagram illustrating the compact dimensions of the scale (139mm x 219mm x 6mm).

## WARRANTY AND SUPPORT

---

For warranty information or product support, please refer to the documentation included with your purchase or contact NewlineNY customer service directly. You can also visit the official NewlineNY store on Amazon for more information and contact options: [NewlineNY Amazon Store](#).