

## Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

[manuals.plus](#) /

> [Whirlpool](#) /

> [Whirlpool WP3352287 OEM Top Load Washer Drive Motor Instruction Manual](#)

## Whirlpool WP3352287

# Whirlpool WP3352287 OEM Top Load Washer Drive Motor Instruction Manual

Model: WP3352287

## PRODUCT OVERVIEW

---

The Whirlpool WP3352287 OEM Top Load Washer Drive Motor is a genuine replacement part designed to ensure your washing machine's proper function. This motor is crucial for the washer to spin, agitate, and drain effectively during the washing cycle. It is engineered to meet Whirlpool's rigorous standards for quality and durability.

- **Genuine OEM Part:** Designed specifically for your appliance, meeting Whirlpool engineering standards to ensure quality.
- **Replacement Part Numbers:** WP3352287 replaces part numbers 3347642, 3349640, and 3352287.
- **One Year Warranty:** This part comes with a one-year warranty, ensuring reliability and peace of mind.




Image: Whirlpool Genuine OEM Parts and Accessories. This image illustrates the commitment to quality and engineering standards for genuine Whirlpool parts, ensuring they are designed specifically for your appliance.

## SPECIFICATIONS

<b>Brand</b>	Whirlpool
<b>Model Name</b>	Whirlpool WP3352287 Genuine OEM Top Load Washer Drive Motor
<b>Model Info</b>	WP3352287
<b>Material</b>	Multi-Material
<b>Item Weight</b>	18.2 Pounds (approximately 8.26 kg)
<b>Product Dimensions</b>	7 x 18.5 x 7.25 inches (approximately 17.78 x 46.99 x 18.42 cm)

UPC	883049505350
-----	--------------

## WHAT'S IN THE BOX

---

- Genuine OEM Top Load Washer Drive Motor Replacement Part

## COMPATIBILITY

---

The WP3352287 Top Load Washer Drive Motor is designed for use with select washing machine brands, including Whirlpool and Kenmore. Always verify compatibility with your specific appliance model number before installation. This part replaces previous part numbers 3347642, 3349640, and 3352287.

## SAFETY INFORMATION

---

**WARNING:** Before attempting any installation or repair, ensure the washing machine is completely disconnected from all power sources. Unplug the appliance or shut off the house circuit breaker for the washing machine. Additionally, turn off both the hot and cold water supplies to the appliance. Failure to follow these safety precautions can result in serious injury or electrical shock.

## INSTALLATION INSTRUCTIONS

---

Replacing the Top Load Washer Drive Motor requires basic hand tools, some disassembly of the washer, and novice repair experience. Due to the complexity and safety considerations, it is recommended that installation be performed by a qualified service technician. If you choose to perform the installation yourself, ensure you have reviewed relevant repair guides and understand the process thoroughly.

### **General Steps (Consult a detailed service manual for your specific washer model):**

1. Disconnect power and water supply as per safety instructions.
2. Access the drive motor compartment, which may involve removing the washer's outer casing or tilting the appliance.
3. Carefully disconnect electrical connections and mounting hardware from the old motor.
4. Remove the old drive motor.
5. Install the new WP3352287 drive motor, ensuring all connections and mounting hardware are securely fastened.
6. Reassemble the washer.
7. Restore power and water supply, then test the appliance for proper operation.



Image: Whirlpool WP3352287 Top Load Washer Drive Motor. This image displays the drive motor, which is responsible for the washer's spin, agitate, and drain functions.

## MAINTENANCE

---

To maintain the overall performance and longevity of your washing machine, including the drive motor, regular cleaning is recommended. Whirlpool suggests using affresh® Washing Machine Cleaner Tablets (item W10135699) once a month. This helps to reduce odor-causing residue that can accumulate in your washing machine's drain system without proper care.

## TROUBLESHOOTING

---

If your washing machine exhibits issues such as failure to spin, agitate, or drain, the drive motor may be a contributing factor. Before replacing the motor, ensure all electrical connections are secure and there are no obstructions preventing movement. If problems persist after verifying connections and clearing obstructions, consult a qualified appliance repair technician for diagnosis and repair. Attempting complex repairs without proper knowledge can lead to further damage or personal injury.

## WARRANTY AND SUPPORT

---

The Whirlpool WP3352287 OEM Top Load Washer Drive Motor is backed by a one-year warranty. This warranty covers defects in material and workmanship under normal use. For warranty claims, technical assistance, or to locate authorized service providers, please contact Whirlpool customer support or visit the official Whirlpool website. Always use genuine Whirlpool parts to ensure optimal performance and to maintain your appliance's warranty.



Video: Whirlpool Genuine Parts. This video provides an overview of Whirlpool Genuine OEM Parts, highlighting their quality, durability, and design to fit perfectly with Whirlpool appliances. It emphasizes the importance of using genuine parts for optimal performance and longevity.