

YATO YT-72453

YATO YT-72453 Digital Dial Indicator User Manual

[Introduction](#)

[Safety](#)

[Overview](#)

[Setup](#)

[Operation](#)

[Maintenance](#)

[Troubleshooting](#)

[Specifications](#)

[Warranty](#)

[& Support](#)

1. INTRODUCTION

This manual provides detailed instructions for the proper use, setup, and maintenance of your YATO YT-72453 Digital Dial Indicator. This precision measuring instrument is designed for accurate dimensional measurements in various applications. Please read this manual thoroughly before operating the device to ensure safe and efficient use.

2. SAFETY INFORMATION

- Always handle the dial indicator with care to prevent damage to the precision components.
- Avoid dropping the instrument or subjecting it to strong impacts.
- Do not expose the device to extreme temperatures, humidity, or direct sunlight.
- Keep the measuring probe and spindle clean and free from dust, oil, or other contaminants.
- Store the indicator in its protective case when not in use.
- Do not attempt to disassemble or modify the instrument, as this will void the warranty and may cause damage.

3. PRODUCT OVERVIEW

The YATO YT-72453 is a digital dial indicator featuring an easy-to-read LCD display and intuitive controls for precise measurements. Key components include:

- **LCD Display:** Shows measurement readings in metric (mm) or imperial (inch) units.
- **Measuring Probe/Spindle:** The movable part that contacts the surface to be measured.
- **Mounting Stem:** Used to secure the indicator to a stand or fixture.
- **Buttons:**
 - **inch/mm:** Toggles between metric and imperial units.
 - **OFF/ON:** Powers the device on or off.
 - **ZERO:** Sets the current position as the zero reference point.



Figure 1: Front view of the YATO YT-72453 Digital Dial Indicator, showing the LCD display and control buttons.

4. SETUP

4.1 Unpacking

Carefully remove the YATO YT-72453 Digital Dial Indicator from its protective plastic case. Inspect the instrument for any signs of damage during transit. Ensure all components are present.



Figure 2: The YATO YT-72453 Digital Dial Indicator stored in its red protective plastic case.

4.2 Mounting the Indicator

The dial indicator is typically mounted onto a stable stand or fixture using its mounting stem. Securely fasten the stem in the clamp of your chosen stand, ensuring the indicator is stable and perpendicular to the surface being measured, if required for your application.

5. OPERATING INSTRUCTIONS

5.1 Power On/Off

Press the **OFF/ON** button to power the indicator on. Press and hold the **OFF/ON** button for a few seconds to power it off.

5.2 Unit Conversion

Press the **inch/mm** button to switch between metric (millimeters) and imperial (inches) measurement units. The selected unit will be displayed on the LCD.

5.3 Zeroing the Display

To set a reference point:

1. Position the measuring probe against the surface or object that will serve as your zero reference.
2. Ensure the probe is stable and making proper contact.
3. Press the **ZERO** button. The display will reset to 0.00, and subsequent movements of the probe will show the deviation from this zero point.

5.4 Taking a Measurement

After zeroing, move the measuring probe to the point you wish to measure. The LCD display will show the precise displacement from your set zero point. For consistent readings, ensure the probe moves smoothly and without lateral force.

6. MAINTENANCE

- **Cleaning:** Wipe the instrument body and display with a soft, dry cloth. For stubborn dirt, a slightly damp cloth can be used, but ensure no liquid enters the electronic components. Do not use solvents or abrasive cleaners.
- **Probe Care:** Keep the measuring probe tip clean. If necessary, gently clean it with a soft cloth.
- **Storage:** When not in use, store the YATO YT-72453 Digital Dial Indicator in its original protective plastic case to shield it from dust, moisture, and physical damage.

7. TROUBLESHOOTING

Problem	Possible Cause	Solution
Display is blank or flickering.	Low or depleted internal battery (if applicable).	As per product specifications, user-replaceable batteries are not required. If the display is blank, ensure the device is powered on. If the issue persists, contact customer support.
Inaccurate readings.	Dirt on probe/spindle; improper zeroing; device not stable.	Clean the probe and spindle. Re-zero the device carefully. Ensure the indicator is securely mounted and stable.
Buttons unresponsive.	Device malfunction.	Try powering the device off and on again. If the issue persists, contact customer support.

8. SPECIFICATIONS

Model Number	YT-72453
Brand	YATO
Measurement Range	0 - 12.7 mm (0 - 0.5 inches)
Precision / Resolution	0.01 mm (0.0005 inches)
Display	LCD
Scale	Metric, Imperial
Product Dimensions (L x W x H)	9 x 6 x 10 cm
Product Weight	100 grams



Documents - YATO – YT-72453



[\[pdf\]](#) Catalog

KATALOG YATO 2024 indb 3717 D^aN̄D_iD_sN̄D_s D DD_i DD³%D¹/₄D_iD³%D¹/₂D_μD¹/₂N̄D_s D DDDDDD catalogue tme
eu Document c2141a06bd3d0f0c5ecc954eccddb174 |||

2024 AIR COMPRESSORS - KOMPRESORY Compressors are invaluable support in industry, construction, w ... re pressione del sistema frenante e ABS ES Probador de presin en el sistema de frenos y ABS CN ABS **YT-72453** Measuring range / Zakres pomiaru mm 0-12.7 50 For YT-72450, **YT-72453** Dla YT-72450, Y...

lang:en score:10 filesize: 92.74 M page count: 652 document date: 2024-01-30