

USARemote 6370B944

USARemote Key Fob Instruction Manual

Model: 6370B944 for Mitsubishi Lancer & Outlander Sport

1. PRODUCT OVERVIEW

This manual provides instructions for the USARemote Key Fob, designed as a replacement for specific Mitsubishi models. This key fob integrates remote locking/unlocking functions with a traditional key blade.



Image of the USA Remote key fob, featuring a black casing with a metal key blade and three control buttons.

2. COMPATIBILITY

This key fob is compatible with certain Mitsubishi Lancer and Outlander Sport models manufactured between 2010 and 2019. It is a direct replacement for Part Number (P/N): 6370B944.

3. FEATURES

- Complete key fob unit with integrated electronics.
- Includes a pre-installed lithium metal battery.
- Designed for remote locking, unlocking, and panic functions.

4. SETUP AND PROGRAMMING

Important: This key fob requires professional programming by a qualified dealer or locksmith. It is not self-programmable.

The key blade will also need to be cut by a professional to match your vehicle's ignition.

Your browser does not support the video tag.

Video demonstrating the programming process for a key fob using specialized equipment, typically performed by a dealer or locksmith.

5. OPERATING INSTRUCTIONS

Once programmed and the key blade is cut, operate the key fob as follows:

- **Lock Button:** Press once to lock all vehicle doors.
- **Unlock Button:** Press once to unlock the driver's door, press twice to unlock all doors.
- **Panic Button:** Press and hold to activate the vehicle's alarm system. Press again to deactivate.

Your browser does not support the video tag.

Short video showcasing the USARemote key fob and its basic functions.

6. MAINTENANCE

The key fob comes with a pre-installed lithium metal battery. When the remote functions become weak or unresponsive, the battery may need replacement. Consult a professional for battery replacement to ensure proper handling and functionality.

7. TROUBLESHOOTING

- **Remote not working:** Ensure the battery is not depleted. If the battery is new or recently replaced, the fob may need to be reprogrammed by a professional.
- **Vehicle not starting:** If the remote functions work but the vehicle does not start, the transponder chip inside the key fob may not be correctly programmed or recognized by the vehicle's immobilizer system. This requires professional diagnosis and programming.
- **Physical damage:** Avoid dropping the key fob or exposing it to water or extreme temperatures, as this can damage internal components.

8. SPECIFICATIONS

Manufacturer	USARemote
Brand	USARemote
Model	6370B944
Item Weight	0.634 ounces
Package Dimensions	6.61 x 4.57 x 0.71 inches
Batteries	1 Lithium Metal (included)
Manufacturer Part Number	US-MIT-B944-3B M
Compatible Devices	Mitsubishi Vehicle
Connectivity Technology	Infrared

9. IMPORTANT INFORMATION

Legal Disclaimer:

This product is an aftermarket part designed to function as a replacement for the original equipment. It is not manufactured by Mitsubishi.

10. SUPPORT

For further assistance or inquiries, please contact USARemote customer support. You can find more information and contact details on the official USARemote store page:

[Visit the USARemote Store](#)