



Manuals.plus /

› EtlIN /

› EtlIN Hepa Filter Instruction Manual for Midea M3L / I5C Robot Vacuum Cleaner

EtlIN 2269

EtlIN Hepa Filter Instruction Manual

For Midea M3L / I5C Robot Vacuum Cleaner

INTRODUCTION

This instruction manual provides essential information for the proper installation, maintenance, and replacement of your EtlIN Hepa filters. These filters are designed for compatibility with Midea M3L and I5C robot vacuum cleaner models. Regular replacement of the Hepa filter is crucial for maintaining the cleaning performance of your robot vacuum and ensuring optimal air filtration.

SAFETY INFORMATION

Please read all safety instructions before installing or replacing the Hepa filter. Keep this manual for future reference.

- Always turn off and unplug the robot vacuum cleaner before performing any maintenance or filter replacement.
- Ensure the filter is correctly seated to prevent damage to the vacuum cleaner and maintain filtration efficiency.
- Dispose of old filters responsibly according to local regulations.
- Keep filters out of reach of children.

INSTALLATION INSTRUCTIONS

Follow these steps to install your new EtlIN Hepa filter:

1. **Step 1: Power Off the Vacuum.** Ensure your Midea M3L or I5C robot vacuum cleaner is turned off and disconnected from its charging base.
2. **Step 2: Locate the Dust Bin.** Open the top cover of your robot vacuum cleaner to access the dust bin compartment. Remove the dust bin.
3. **Step 3: Remove the Old Filter.** Open the dust bin cover. The Hepa filter is typically located inside the dust bin. Carefully remove the old, dirty filter.



Image: Two new EtlIN Hepa filters, ready for installation. These filters feature a light grey frame and white pleated filtration material.

- 4. Step 4: Insert the New Filter.** Place the new EtlIN Hepa filter into the designated slot within the dust bin. Ensure it fits snugly and is properly seated to prevent air leakage.




Image: Packaging for the compatible filters, indicating use for Midea i5C, M3L, and NER200 models.

5. **Step 5: Reassemble.** Close the dust bin cover, then reinsert the dust bin back into the robot vacuum cleaner until it clicks into place. Close the top cover of the vacuum.
6. **Step 6: Power On.** You can now power on your robot vacuum cleaner and resume normal operation.

MAINTENANCE AND REPLACEMENT

To ensure optimal performance and longevity of your robot vacuum cleaner, regular maintenance of the Hepa filter is

essential.

- **Cleaning:** The Hepa filter is not washable. Gently tap the filter over a waste bin to remove accumulated dust and debris. A small brush or a handheld vacuum can also be used to clean the pleats. Do not use water or cleaning solutions on the Hepa filter.
- **Replacement Frequency:** It is recommended to replace the Hepa filter every 1 to 3 months, depending on usage frequency and the amount of pet hair or dust in your home. A dirty filter can reduce suction power and air filtration efficiency.
- **Signs of Replacement:** Replace the filter if you notice a decrease in cleaning performance, increased dust in the air after vacuuming, or if the filter material appears visibly clogged or damaged.

TROUBLESHOOTING

| Problem | Possible Cause | Solution |
|----------------------------------|--|---|
| Reduced suction power | Clogged or dirty Hepa filter | Clean or replace the Hepa filter. |
| Dust escaping from vacuum | Filter not properly installed or damaged | Ensure the filter is correctly seated. Inspect for damage and replace if necessary. |
| Unusual noise from dust bin area | Filter not seated correctly | Remove and reinsert the filter, ensuring it is securely in place. |

SPECIFICATIONS

- **Product Name:** EtlIN Hepa Filter
- **Compatibility:** Midea M3L, Midea I5C Robot Vacuum Cleaner
- **Quantity:** 2 Pieces per pack
- **Material:** High-efficiency particulate air (Hepa) filtration material
- **Dimensions:** Approximately 1.18 x 0.79 x 0.39 inches (based on package dimensions, actual filter size may vary slightly)
- **Model Number:** 2269

WARRANTY INFORMATION

EtlIN provides a standard manufacturer's warranty against defects in materials and workmanship. This warranty typically covers manufacturing faults but does not cover normal wear and tear, misuse, or damage caused by improper installation. For specific warranty terms and conditions, please refer to the product packaging or contact EtlIN customer support.

CUSTOMER SUPPORT

If you have any questions regarding the installation, maintenance, or compatibility of your EtlIN Hepa filters, please contact our customer support team. For the most up-to-date contact information, please visit the official EtlIN website or refer to the contact details provided on the product packaging.

Note: When contacting support, please have your product model number (2269) and the model of your Midea robot vacuum cleaner (M3L or I5C) ready.

