

Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

manuals.plus /

› [BORA](#) /

› [BORA CT15 Work Stand + 4pcs 20mm Table Tops User Manual](#)

BORA CT15

BORA CT15 Work Stand + 4pcs 20mm Table Tops User Manual

Model: CT15

INTRODUCTION

This manual provides essential information for the safe and effective use of your BORA CT15 Work Stand and accompanying 20mm Table Tops. Please read this manual thoroughly before assembly and operation to ensure proper setup, maintenance, and to understand the full capabilities of your product.

SAFETY INFORMATION

Always observe the following safety precautions:

- Ensure the work stand is placed on a stable, level surface before use.
- Do not exceed the maximum load capacity of 2000 pounds (907 kg).
- Distribute weight evenly across the tabletop surface.
- Keep hands and fingers clear of moving parts during setup and folding.
- Inspect the stand and tabletop for any damage before each use. Do not use if damaged.
- Store the unit in a dry, secure location when not in use.

PACKAGE CONTENTS

Verify that all components are present:

- 1 x BORA CT15 Centipede Work Stand
- 4 x 20mm Table Tops (CK22TM)
- Quick Clamps (quantity as supplied)
- X-Cups (quantity as supplied)

SETUP

Follow these steps to set up your CT15 Work Stand and Table Tops:

1. **Unfold the Centipede Work Stand:** Place the folded Centipede stand on a flat surface. Gently pull the legs outwards from

the center until the stand fully expands into its open position. Ensure all legs are locked into place and the stand is stable. The stand will expand to a 4-foot by 8-foot footprint, providing a large support area.

2. **Position the Table Tops:** Place the four CK22TM table tops onto the expanded Centipede stand. The table tops are designed to fit securely on the stand's support points. Each tabletop measures 24" x 48" (610 mm x 1200 mm).
3. **Secure the Table Tops (Optional but Recommended):** Use the provided quick clamps or X-cups to secure the table tops to the Centipede stand for added stability, especially when working with heavy materials or performing tasks that involve significant force.



Image: The BORA CT15 Centipede Work Stand in its fully expanded configuration, alongside the four 20mm table tops. This illustrates the primary components ready for assembly and use.

OPERATING INSTRUCTIONS

The BORA CT15 Work Stand and Table Tops provide a versatile and robust workstation:

- **Working Height:** The stand provides a comfortable working height of 36 inches, suitable for various tasks and users.
- **Load Capacity:** The system is designed to support up to 2000 pounds (907 kg). Always distribute the load evenly across the tabletop surface to prevent stress points.
- **Dog Holes:** The table tops feature 20mm dog holes spaced at 96mm on center. These holes are compatible with a wide range of 20mm dog hole accessories, allowing for versatile clamping and jig setups.
- **Portability:** The Centipede stand folds compactly for easy transport and storage. The table tops can also be stored flat.

MAINTENANCE

Proper maintenance ensures the longevity and performance of your work stand:

- **Cleaning:** Wipe down the metal frame and table tops with a damp cloth after use to remove dust, debris, and spills. Avoid harsh chemicals that may damage the finish.
- **Inspection:** Periodically inspect all joints, fasteners, and the overall structure for any signs of wear, damage, or loose components. Tighten any loose screws or bolts.
- **Storage:** When not in use, fold the Centipede stand and store it in a dry, protected area. Store the table tops flat to prevent warping.

TROUBLESHOOTING

If you encounter issues, refer to the following common problems and solutions:

- **Stand is wobbly:**
 - Ensure the stand is fully expanded and all leg joints are locked.
 - Verify it is placed on a level surface.
 - Check for any bent or damaged frame components.
- **Table tops do not sit flat:**
 - Ensure the Centipede stand is fully and correctly expanded.

- Check if the table tops are warped. Store them flat when not in use.
- **Difficulty folding/unfolding:**
 - Ensure no debris is obstructing the joints.
 - Apply a small amount of silicone lubricant to the pivot points if necessary.

SPECIFICATIONS







Feature	Specification
Brand	BORA
Model	CT15 Work Stand + CK22TM Table Tops
Material	Metal (Stand), Wood/Composite (Table Tops)
Color	Brown (Table Tops), Black/Brown (Stand)
Working Height	36 inches
Work Support Size (Expanded)	4 feet x 8 feet (full sheet of plywood)
Table Top Dimensions (each)	24" x 48" (610 mm x 1200 mm)
Load Capacity	2000 pounds (907 kg)
Dog Hole Size	20mm
Dog Hole Spacing	96mm on center
Assembly Required	Yes

WARRANTY AND SUPPORT

BORA products are manufactured to high-quality standards. For information regarding warranty coverage, please refer to the warranty card included with your product or visit the official BORA website. For technical support, replacement parts, or any inquiries not covered in this manual, please contact BORA customer service through their official channels.

BORA Official Website: www.boratool.com



	<p>IPC Gansow CT15, CT30, CT45 Scrubber Dryer Operator's Manual</p> <p>Comprehensive operator's manual for IPC Gansow CT15, CT30, and CT45 automatic scrubber dryers, covering technical specifications, safety information, operation, maintenance, and troubleshooting.</p>
	<p>Stanley CT15036GN Hydraulic Crimping Tool Parts Illustration and List</p> <p>Detailed parts illustration and comprehensive parts list for the Stanley CT15036GN hydraulic crimping tool, including item numbers, part numbers, quantities, and descriptions. Essential for maintenance and identification.</p>
	<p>MCombo Wooden Cat House Owner's Manual and Installation Guide</p> <p>Comprehensive owner's manual and installation guide for the MCombo Wooden Cat House (Model 6012-CT15), including assembly instructions, product precautions, warranty, and customer support information.</p>
	<p>SIMSEN CT15 Dehumidifier User Manual & Features Home Moisture Control</p> <p>Comprehensive user manual for the SIMSEN CT15 Dehumidifier. Learn about its features, specifications, safety guidelines, operating instructions, troubleshooting tips, and maintenance procedures for effective home humidity control.</p>
	<p>Bora Portamate PM-8000 Portacube STR Miter Saw Work Station Operator's Manual</p> <p>Comprehensive operator's manual for the Bora Portamate PM-8000 Portacube STR Miter Saw Work Station, covering assembly, operation, safety, and warranty information.</p>
	<p>Minco Sensors & Instruments Product Guide: Temperature Sensing Solutions</p> <p>Explore Minco's comprehensive product guide for advanced temperature sensors, instruments, heaters, and flex circuits. Offering solutions for demanding industrial, aerospace, and medical applications with decades of expertise.</p>

lang:de score:10 filesize: 1.51 M page count: 195 document date: 2022-03-25