

[Manuals.plus](#) /

> [Marg](#) /

> Marg Replacement AC Adapter Charger for Ferrex Mini-Cutter CS136KB (B6694557533) User Manual

## Marg B6694557533

# Marg Replacement AC Adapter Charger FOR FERREX 3.6V MINI-CUTTER MODEL CS136KB (B6694557533)

User Manual

---

## 1. Introduction

---

This manual provides essential information for the safe and efficient use of your Marg Replacement AC Adapter Charger, model B6694557533. This adapter is specifically designed to provide power and charge the Ferrex 3.6V Mini-Cutter Model CS136KB. Please read these instructions carefully before using the product to ensure proper function and longevity.



**Image 1.1:** Marg Replacement AC Adapter Charger. This image shows the compact design of the AC adapter, highlighting its plug and main body.

## 2. What's in the Box

Carefully unpack your product and ensure all items are present and in good condition. If any items are missing or damaged, please contact customer support.

- 2 x Marg Replacement AC Adapter Charger (Model B6694557533)

## 3. Setup

Follow these steps to properly set up your AC adapter for use:

1. **Inspect the Adapter:** Before connecting, visually inspect the AC adapter and its cable for any signs of damage, such as frayed wires or cracked casing. Do not use if damaged.
2. **Connect to Power Outlet:** Plug the AC adapter into a standard electrical wall outlet. Ensure the outlet provides the correct voltage (refer to specifications).
3. **Connect to Device:** Insert the output connector of the AC adapter firmly into the charging port of your Ferrex 3.6V Mini-Cutter Model CS136KB. Ensure a secure connection.
4. **Verify Connection:** Some devices may have an indicator light to show that charging has begun. Confirm that your device is receiving power.



**Image 3.1:** Marg AC Adapter with its integrated cable. This image illustrates the adapter's full form, including the power cord and device connector, ready for setup.

## 4. Operating Instructions

---

Once properly set up, the Marg AC Adapter Charger will provide power to your Ferrex Mini-Cutter and charge its battery.

- **Charging:** Connect the adapter to your Ferrex Mini-Cutter. The adapter is designed for efficient charging, ensuring your device powers up quickly.
- **Power Supply:** The adapter can also be used to power the device directly if it supports operation while connected to a power source.
- **Reliable Performance:** This adapter provides stable power delivery, ensuring consistent performance for your device.

## 5. Safety Information

---

Your safety and the safety of your device are paramount. Please observe the following safety guidelines:

- **Overcharging and Overheating Protection:** The adapter is equipped with advanced safety features to prevent overcharging and overheating, protecting your device during the charging process.
- **Indoor Use Only:** This adapter is designed for indoor use in dry conditions. Do not expose it to rain,

moisture, or extreme temperatures.

- **Proper Ventilation:** Ensure the adapter has adequate ventilation during use. Do not cover it or place it in an enclosed space where heat cannot dissipate.
- **Avoid Damage:** Do not drop, disassemble, or attempt to repair the adapter. Any damage can lead to electrical hazards.
- **Correct Voltage:** Always ensure the input voltage of the adapter matches the voltage of your power outlet. The adapter's input voltage is 240 Volts.
- **Children and Pets:** Keep the adapter and its cable out of reach of children and pets to prevent accidental injury or damage.

## 6. Maintenance

---

Proper care and maintenance will extend the life of your AC adapter:

- **Cleaning:** Disconnect the adapter from the power outlet and the device before cleaning. Use a soft, dry cloth to wipe the surface. Do not use liquid cleaners or solvents.
- **Storage:** When not in use, store the adapter in a cool, dry place, away from direct sunlight and moisture. Avoid tightly winding the cable to prevent damage.
- **Handling:** Always grasp the plug when disconnecting from an outlet; do not pull on the cable.

## 7. Troubleshooting

---

If you encounter issues with your AC adapter, try the following steps:

- **Device Not Charging:**
  - Ensure the adapter is securely plugged into both the wall outlet and the device.
  - Check if the wall outlet is functional by plugging in another device.
  - Verify that the device's charging port is clean and free of debris.
- **Adapter Feels Hot:**
  - It is normal for adapters to feel warm during operation. However, if it feels excessively hot, disconnect it immediately and allow it to cool. Ensure it has proper ventilation.
- **No Power Indicator:**
  - If your device has a charging indicator and it's not lighting up, recheck all connections. If the issue persists, the adapter or device may be faulty.

If these steps do not resolve the issue, please contact customer support.

## 8. Specifications

---

Feature	Specification
Brand	Marg
Model Number	B6694557533
Compatible Device	Ferrex 3.6V Mini-Cutter Model CS136KB
Input Voltage	240 Volts

Feature	Specification
Output Voltage	6V (as per product title compatibility)
Connector Type	ACC
Color	BLACK
Safety Certifications	CE, FCC



**Image 8.1:** Dimensions of the Marg AC Adapter. This image provides a visual representation of the adapter's physical size, including length, width, and height measurements.

## 9. Warranty and Support

For warranty information or technical support, please refer to the documentation provided with your purchase or contact Marg customer service directly. Keep your purchase receipt as proof of purchase.