

## Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

manuals.plus /

> [UranHub](#) /

> [UranHub G30 Drone 3-in-1 Charging Dock Instruction Manual](#)

## UranHub UNBN0

# UranHub G30 Drone 3-in-1 Charging Dock Instruction Manual

Model: UNBN0

## 1. INTRODUCTION

Thank you for choosing the UranHub G30 Drone 3-in-1 Charging Dock. This compact and efficient charging solution is designed to power up to three UranHub G30 drone batteries simultaneously, ensuring your drone is always ready for flight. This manual provides essential information for the safe and effective use of your charging dock. Please read it thoroughly before operation and retain it for future reference.

## 2. PRODUCT OVERVIEW

### 2.1 Key Features

- **Versatile Charging Station:** Allows simultaneous charging of up to 3 devices, streamlining your charging routine.
- **Compatibility:** Specifically designed for UranHub G30 drones.
- **Space-Saving Design:** Compact and sleek construction optimizes desk or counter space.
- **Safety Features:** Equipped with overcharge protection to prevent damage to your devices.
- **Durable Build:** Crafted with high-quality materials for long-lasting performance.

### 2.2 Package Contents

- UranHub G30 Drone 3-in-1 Charging Dock
- USB Charging Cable
- User Manual

## 3. SETUP

### 3.1 Connecting the Charging Dock

1. Unpack the UranHub G30 Drone 3-in-1 Charging Dock and its accessories.
2. Connect the provided USB charging cable to the input port on the charging dock.
3. Plug the other end of the USB cable into a compatible USB power adapter (not included) or a powered USB port. Ensure the power source provides sufficient voltage (15 Volts recommended).

4. The LED indicators on the dock will briefly illuminate, indicating it is powered on and ready for use.




Image: The UranHub G30 Charging Dock with a G30 drone battery, illustrating compatibility and how the battery fits into the charging slot.

## 4. OPERATING INSTRUCTIONS

### 4.1 Charging Batteries

1. Ensure the charging dock is properly connected to a power source.
2. Insert up to three UranHub G30 drone batteries into the designated charging slots on the dock. Ensure they are securely seated.
3. The LED indicators corresponding to each slot will illuminate to show the charging status.
4. Once a battery is fully charged, its indicator light will change (e.g., from blinking to solid, or turn off, refer to LED Indicators section for details).
5. Remove the fully charged batteries from the dock.



Image: Visual representation of three drone batteries simultaneously charging within the dock, with charging indicators.

### 4.2 LED Indicators

The charging dock features individual LED indicators for each battery slot. These lights provide real-time status updates:

- **Solid Blue:** Battery is fully charged.
- **Blinking Blue:** Battery is currently charging.
- **No Light:** No battery inserted, or charging dock is not powered.




Image: The charging dock with a visual representation of its overcharge protection feature, indicating safe charging.

## 5. MAINTENANCE

---

### 5.1 Cleaning

To maintain optimal performance, keep the charging dock clean:

- Disconnect the charging dock from the power source before cleaning.
- Use a soft, dry cloth to wipe the exterior of the dock.
- Avoid using liquid cleaners, solvents, or abrasive materials, as these can damage the device.
- Ensure no dust or debris accumulates in the charging slots. Use a soft brush or compressed air if necessary.

### 5.2 Storage

When not in use, store the charging dock in a cool, dry place, away from direct sunlight and extreme temperatures. Keep it out of reach of children and pets.

## 6. TROUBLESHOOTING

---

If you encounter issues with your UranHub G30 Drone 3-in-1 Charging Dock, refer to the following common problems and solutions:

- **Dock not powering on:**
  - Ensure the USB cable is securely connected to both the dock and the power source.
  - Verify that the power source (USB adapter or port) is functional. Try a different power source.
- **Battery not charging:**
  - Ensure the battery is correctly inserted into the charging slot.
  - Check if the battery itself is damaged or faulty. Try charging a different battery if available.
  - Clean the charging contacts on both the battery and the dock.

- **Slow charging:**

- Ensure your USB power adapter provides sufficient output (e.g., 5V/2A or higher). Lower power adapters may result in slower charging.
- Avoid charging in extremely hot environments, as this can affect charging efficiency.

If the problem persists after trying these solutions, please contact UranHub customer support for assistance.

## 7. SPECIFICATIONS



Image: The UranHub G30 Charging Dock with its compact dimensions labeled: 152 mm (5.98 inch) length, 85 mm (3.35 inch) width, and 46 mm (1.81 inch) height.

<b>Model Number</b>	UNBN0
<b>Brand</b>	UranHub
<b>Package Dimensions</b>	6.34 x 3.58 x 1.97 inches
<b>Item Weight</b>	6.4 ounces
<b>Hardware Interface</b>	USB
<b>Total USB Ports</b>	3
<b>Number of Charging Ports</b>	3
<b>Input Voltage</b>	15 Volts
<b>Color</b>	Black
<b>UPC</b>	810089906687

## 8. WARRANTY AND SUPPORT

---

UranHub products are designed for reliability and performance. This product comes with a standard manufacturer's warranty. For specific warranty details, please refer to the warranty card included with your purchase or visit the official UranHub website.

For technical support, troubleshooting assistance, or any inquiries regarding your UranHub G30 Drone 3-in-1 Charging Dock, please contact UranHub customer service through the contact information provided on our official website or your purchase platform.

*Please note: Unauthorized disassembly or modification of the product will void the warranty.*