



di-soric OT 18 FM 800 P3-B4 Diffuse Sensor Owner's Manual

[Home](#) » [di-soric](#) » di-soric OT 18 FM 800 P3-B4 Diffuse Sensor Owner's Manual 



207932
OT 18 FM 800 P3-B4
Diffuse sensor


Contents

- [1 OT 18 FM 800 P3-B4 Diffuse Sensor](#)
- [2 Function](#)
- [3 Documents / Resources](#)
- [4 Related Posts](#)


OT 18 FM 800 P3-B4 Diffuse Sensor



<https://di-soric.com/int-de/PM/207932>



- 1. Potentiometer
- 2. LED
- 3. Width over flats 24 mm



BK: black
 BN: brown
 BU: blue
 WH: white

Function




Technical data (typ.)	+20°C, 24 V DC
Service voltage	10 ... 30 V DC
No-load current (max.)	30 mA
Thread	M18 x 1
Housing material	Metal
Material	PMMA (Window)
Protection class	III, operation on protective low voltage
Operating principle	Diffuse sensor
Evaluation	digital
Design	Thread
Switching output	pnp, 100 mA, NO/NC
Light source	LED
Color	Infrared
Wavelength	880 nm
Modulation	Clocked
Ambient light immunity	3 kLx Clocked light, 10 kLx Sunlight
Scanning range	800 mm
Standardized measuring plate	200 x 200 mm
Sensitivity adjustment	Potentiometer
Switching frequency	1.000 Hz
Response time	0,50 ms
Release time	0,50 ms
Ambient temperature during operation	-25 ... +55 °C
Protection type	IP 67
Connection	Connector, M12, 4-pin
More information / accessories	https://www.di-soric.com/207932

Steinbeisstraße 6.
DE-73660 Urbach.

www.di-soric.com

© di-soric. Right to change reserved.
04.11.2022.

Documents / Resources

	di-soric OT 18 FM 800 P3-B4 Diffuse Sensor [pdf] Owner's Manual OT 18 FM 800 P3-B4 Diffuse Sensor, OT 18 FM 800 P3-B4, Diffuse Sensor, Sensor
---	---

Manuals+.