

HOLLYLAND H100 Full Duplex Wireless Intercom System User Guide

Home » HOLLYLAND » HOLLYLAND H100 Full Duplex Wireless Intercom System User Guide 1

HOLLYLAND H100 Full Duplex Wireless Intercom System User Guide



Contents

- 1 Version Introduction
- 2 Updating Guide
- **3 Updating Tool**
- **4 Operation Steps**
- 5 Special notes:
- 6 Documents /

Resources

- **6.1 References**
- **7 Related Posts**

Version Introduction

Released dat e	Firmware Ve rsion	Version introduction	Download Link	Remark
25/1/2024	v2.0.2.4	Initial Version	Google Drive cloud storage link: https://d rive.google.co m/file/d/1NFALMa9X8XdIXf Axj1U0QPffvKBtN8j/view?usp=drive_link	
12/4/2024	v2.0.4.5	Fixed Known Issu es	https://download-hollyland.oss-us-easta liyuncs.com/Firmware/Video_ transmissions/Mars_M1_Enhanced/HLD_V 9803Pro_ H100S2.0.4.5_ OTA_Common_20240412.zip	

Updating Guide

Kindly Note:


- It takes the risk to to do the upgrade, please avoid updating during the important events;
- Please make sure the device with enough power during updating;
- Please don't unplug the USB flash disk during updating to avoid updating failure;
- Please feel free to contact us if the updating failure or error causes the malfunction: Hollyland Technical Support Engineer: support@hollyland-tech.com

Updating Tool

- Windows 10/11 PC
- USB-C Cable

Operation Steps

1. Format the USB flash disk into FAT32 format first, then place the updating file in the USB flash disk root directly.



2. Insert the USB flash disk into the wireless monitor's Type-C port will the monitor enter the updating status automatically after 1 mins around. Then just waiting for the updating completion

Notes: If you dont wanna wait, you can enter Device info: Click the Folder Icon to choose the OTA file to start the upgarding manually.

Special notes:

- If the USB flash disk which over 32G, the Window/Mac system don't have the FAT32 options, so need the professional disk software tools (like Disk Genius) to format it.
- The USB flash disk needs to be formatted into the FAT32 format first can the device recognize the USB flash disk.
- The updating file need to be placed in the USB flash disk root directory can the device read the updating file, the file can't be placed in other **catalogue**.
- Checking whether the monitor firmware version is the latest or not on the device information after the update is completed.



Documents / Resources



HOLLYLAND H100 Full Duplex Wireless Intercom System [pdf] User Guide

HLD_V9803Pro, H100, H100 Full Duplex Wireless Intercom System, H100, Full Duplex Wireless Intercom System, Duplex Wireless Intercom System, Wireless Intercom System, Intercom System, System

References

- O word-render
- User Manual

Manuals+, Privacy Policy

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.