

Lemorele P10 Wireless USB C Transmitter User Manual

Home » Lemorele » Lemorele P10 Wireless USB C Transmitter User Manual

Contents


- 1 Lemorele P10 Wireless USB C
- **Transmitter**
- 2 Connection
- 3 Documents / Resources
 - 3.1 References
- **4 Related Posts**



Lemorele P10 Wireless USB C Transmitter



Connection



1. Install receiver:

• Connect the wireless display receiver to your screen and power it on.

2. Plug and mirror:

• Plug the transmitter H-1/C-1 into a laptop or mobile, connect it to the power supply, and wait for mirroring automatically.

3. Stop and restart:

• Remove the transmitter H-1/C-1 to stop mirroring, and plug the transmitter to restart mirroring.

If unable to mirror, please pair your transmitter to the receiver again. Scan the QRCode below and follow the steps in the full manual.

- Distributor: Shenzhen ShafanTechnology Co,.Ltd
- Brand Owner: Shenzhen Qixing Longyuan
- Technology Co,.Ltd
- Address: RM. 808, No. 1 Binhai Bay, RD. Yanxing, Dist.
- Bao'an, Shenzhen City, Guangdong Province, China support@lemorele.com

Documents / Resources



References

• User Manual

Manuals+,