






Screws must not be excessively long.
Otherwise, motor damage may occur.



GENERAL TOLERANCES PER ISO 2768-m

<=6	>6<=30	>30<=120	>120<=400	>400<=2000
±0.1	±0.2	±0.3	±0.5	±1.0

SCALE

1 : 1

4310-10SHSINSTALLATION DRAWING