

Full Factory Reset for Wireless USB Dongle Connection

1. Unplug the USB Dongle.
2. Scan the barcodes below in order.
 - No need to print these codes, they can be scanned from the screen.
 - The scanner may not make sounds or vibrate while scanning certain codes, this is normal behavior.

Step 1



Step 2



%%SpecCode93

SCANA VENG ER

Step 3



%%SpecCode79

Step 4



%%SpecCode77

SCANAVENGER

Step 5



%%SpecCode35

Step 6




%%SpecCode95

Step 7



%%SpecCode7B

Step 8



%%SpecCode9C

Step 9



Step 10



Step 11



%%SpecCode92

Step 12



%%SpecCodeA8

Step 13



%%SpecCode99

3. Plug the Dongle back in.
4. Confirm connection.
 - Your scanner will pair with the dongle.
 - A solid blue light on the scanner confirms a successful connection.