DT-1

Thermometer Manual

I 、General Description

The pen type thermometer has the advantages of low power consumption, high stability, and high accuracy. It is a simple-to-use and practical high-temperature testing equipment.

II , Product Functions

Temperature measurement range:-50°C \sim +300°C (-58°F \sim +572°F)

Temperature accuracy: $\pm 1^{\circ}$ C/1.8°F

Power supply: 1.5V(AG13)*1.

III、Description of Buttons Function

1、ON/OFF button: Power ON/OFF the meter.

 $2 \ ^{\circ} C/^{\circ} F$ button: Press this button to select the measuring unit ${}^{\circ} C$ or ${}^{\circ} F$.

3. HOLD button: Press the HOLD button momentarily to enter into the Data Hold mode; keep the button again to return to the normal measurement.



www.htcinstrument.com