

Version Info:

This firmware is fully adapted to Omada Controller v5.15.24.

Minimum FW Version for Update: 1.3.0 Build 20240828 Rel. 83857, for downloading of any firmware version, please refer to [Omada Download Center](#).

Enhancement:

1. Optimized memory utilization.

Bug fixed:

1. Fixed an issue where the Mesh AP entered isolated state repeatedly in specific scenarios

Notes:

1. This version of firmware is applied to the Omada APP v4.24 or above.