

Thermo-hygrometer user manual-KD50

Product specifications:

1. Temperature measurement range: -20°C ~ 60°C (-4°F ~ 140°F)
2. Temperature measurement accuracy: $\pm 1^{\circ}\text{C}$ (1.8°F)
3. Temperature resolution: 0.1°C(0.2°F)
4. Humidity range: 10%RH-99%RH
5. Humidity measurement accuracy: $\pm 5\%\text{RH}$
6. Humidity resolution: 1%
7. Power supply: 3V CR2032*1

Key Function:

- Hold (**A**) key for 1.5 seconds to power on
- Double click (**A**) key to select the temperature unit:°C or °F
- Click(**B**)key to check the MAX/MIN value,sequential MAX - MIN - QUIT,(5 seconds no operation automatically exit) , hold (**B**) key for 1.5 seconds to clear stored date
- Hold (**A**) key for 1.5 seconds to power off