

Firmware Update TX-RZ30

(03-12-2025)

We are pleased to offer this firmware update for the best possible performance of your AV Receiver.

This update may be installed via USB or Network.

TX-RZ30

(Current Version R138-0916-1282-0033)

The 03/12/2025 update will address the following:

1. A problem where sometimes no sound is produced while an iPhone is playing music via Bluetooth has been fixed.
2. Stability is improved and minor bugs are fixed.

Firmware Update Instructions

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.