

Starfrit

HIGH PRECISION SCALE




INSTRUCTIONS FOR USE



SPECIFICATIONS

- High precision strain gauge sensor
 - Stainless steel weighing platform
 - Units of measure include: grams (g), ounces (oz), carats (ct), grains (gn), Troy ounces (ozt), Tael (tl) and Pennyweight (dwt)
 - Tare function
 - Low battery and overload indicators
 - Auto-off after three minutes or manual-off
 - Capacity: 7 oz / 200 g
 - Accuracy: 0.001 oz / 0.01 g
 - Platform dimensions:
3" x 2.5" / 76 mm x 64.6 mm
 - Blue backlight LCD screen dimensions:
0.9" x 0.4" / 23.8 mm x 11 mm
-

BATTERIES




- Requires 2 AAA batteries (included).
- Remove isolation sheet before use.

TO REPLACE BATTERIES

- Open battery case cover underneath the scale.
- Take out the used batteries and install new ones.
Make sure to respect the polarity.
- Close battery case cover.

LCD SCREEN



BUTTONS



Tare
function




Mode and unit
conversion





Turn ON
Turn OFF

WEIGHING MODE



- Place the scale on a solid and flat surface.
- Press  button to turn on the scale.
- Wait until LCD screen shows “0.0” to start weighing.
- Press  button to convert to weight mode if needed.
- Load weighing object on scale. Always place the object in the center of the platform. LCD screen will show the weight reading.

UNIT CONVERSION




- Press  button to switch the weight measure.

TARE FUNCTION

To weigh different loads consecutively without removing loads from the scale, put the first load

on the scale to obtain a weight reading. Press **T** button to reset the LCD reading to “0.00” before adding next load. You can repeat operation.

AUTO SHUT OFF & MANUALLY SHUT OFF




Auto shut off occurs if display shows “0” or shows the same weight reading for 3 minutes.

To maximize battery life, it is recommended to shut off manually the scale. Press **⏻** button for 3 seconds and the scale will turn off.

INDICATORS



1. Please replace batteries.



2. Remove item to avoid damage. Maximum capacity of this scale is 7 oz / 200 g.



3. Place the scale on a flat and stable position.

ADVICE FOR USE & CARE

- Always use the scale on a hard flat surface.
- Clean the scale with a slightly damp cloth.
- Avoid contact with water. DO NOT immerse the scale in water.
- All plastic parts should be cleaned immediately after contact with fat, spices, vinegar and strongly flavored /colored food.
- Avoid contact with acid citrus juices.
- DO NOT use chemical or abrasive cleaning agents.
- Not for commercial use.

SUBSCRIBE TO THE NEWSLETTER TO LEARN MORE ABOUT OUR PROMOTIONS!

www.Starfrit.com



www.facebook.com/starfrit



PRINTED IN CHINA FOR : ATLANTIC PROMOTIONS INC, LONGUEUIL (QUÉBEC) J4G 1V6
CUSTOMER SERVICE : STARFRIT.COM/EN/CONTACT-US