

























MAX TIGHTENING
TORQUE
10-12 Nm

















INSTALLATION














MAINTENANCE







MAX TIGHTENING
TORQUE
10-12 Nm
















MAX TIGHTENING
TORQUE
10-12 Nm



MAX TIGHTENING
TORQUE
30 Nm





MAX TIGHTENING
TORQUE
30 Nm

