




Q101, Q102: MPS 9426C, 2SC1923
 Q103, Q104: MPS 9623H, 2SC373
 Q105: MPS 9426(B,C) 2SC1923
 Q201, Q202, Q203: MPS 9634 C.D. 2SC733
 Q206: MPS 9418(T) 2SC509
 Q206: MPS 9681(T) 2SA495
 Q301: MPS 9426(B,C) 2SC388A
 Q302: 2SC1957, 2SC2314, 2SC1678
 Q303: 2SC1306, 2SC2078, 2SC495

NOTE
 2VOLTS AT TRANSMIT CONDITION
 ALL VOLTAGES MEASURED FROM P.C. BOARD
 GND WITH D.C. VTVM AT NO SIGNAL
 (AT 13.8V POWER SUPPLY) IF MEASUREMENT
 VALUES OBTAINED ARE IN EXCESS OF $\pm 20\%$ OF
 VALUES SHOWN
 THEN REASON FOR DIFFERENCE
 SHOULD BE CORRECTED

CHASSIS GND BATTERY NEGATIVE

*VARIABLE **CONTROL NOT ACCESSIBLE
 FROM SIDE

