



ZONDA 9-FX SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V110	14-Mar-22	V1	First Release
			Error Record function added
V112	27-May-22	V1	Minor bug fix
			sACN improved
			Tilt range default set to 540°
V113	30-Jun-22	V113	New Vdeo Mapping
			Extended Mode 3 added:
			- Channels 1-51 : DMX/WDMX/ArtNet/sACN
			- Channels 52-199 : ArtNet/sACN
V120	31-Oct-22	V113B	Bug fixes:
			- Channel 38 corrected
			- Liquid effect slow speed improved
			Extended Modes 2 & 3 removed:
			- New Address Menu
			RDM function improved
			LED Pixels Maps select menu (Gen1 & Gen2)
			LED Bin info menu added
V121	17-Dec-22	V113B	Effect synchronisation bug fix
			sACN & ArtNet improvement
V122	16-Mar-23	V113B	Pan & Tilt speed menu modified
			Unicast function modified
			Chase effects improved
V123	3-Dec-24	V123	Corrected address issue :
			Fixed the bug of not being able to set DMX above 314
			Fixed the bug when set DMX address at 257 and above by SCAN
			Fix the issue "pix addr : 001 (001-148) » show instead of pix addr: 001 (052-199)" when do a factory default
			Optimized Interface to show software version on lower right of Display
			Improved the CCT channel :
			Adjusted Color Temperature value range(2500K to 8000K)
			Adjusted Chase and Color Preset :
			Optimized chase effect with fade
			Adjusted Speed range for chase pattern on the PowerLED and liquid LED
			Added folder channel to store different type of effect
			Improved the consistencies between effect LED and power LED when dimmer off
			Corrected the bug of Chase1 when move the Chase size
			Modified Chase Fade, work with Speed(ch28) and Fade(ch29)
			Fixed the strange behavior on the chase effect when background dimmer at 0
			Corrected some chase effects
			Corrected background color in PIXLE mode
			Improved the white channel when I pass from 256 to 255
			Improve color shift problem.
			Increased the maximum playspeed of liquid LED to 800% of the original content speed
			Remove fade time when at default speeds on the liquid effect
			Added Channel 25 to adjust effect background Size
			Improved interaction between Channel 51 and Channel 36, and interaction between different effects
			Improved the Channel 51/cross fade behavior (cross fade between power led and pixel control)
			Added the menu of "Reset From MAC" for IP address
			Basic and Standard modes modified to have same address menu
			Added "Extend Ring" mode
			Removed RDM queued message
			Hide store dimmer enable function.
V124	7-Aug-24	V124	Fix a chase issue in channel 36
			Fix the "DMX output" option
			Fix Liquid effect issue
			Upgrade RDM Code
			Fix Fan issue
			Change default mode to extended pixel
V130	23-Jun-25	V130	Fix a flash issue when using strobe, dim out and go to open with the dimmer at 0%
			Add Tungsten Simulation
			Add Tracking360
			Add PAN and TILT Option "360SC"
			Correct the RDM Modele ID "0A86"
			Improve Dimmer in Low level
			Add Function to read and set address, universe and signal via Fixture Manager Software
V131	3-Jul-25	V130	Added C39 options for "set LED BIN"

NOTE: Updating software does not restore factory default settings