

2012 BMW 650i Coupe (F13) V8-4.4L Turbo (N63)

Vehicle > Technical Service Bulletins

ALL TECHNICAL SERVICE BULLETINS

 Type term and hit enter to filter list below

TSB NUMBER	TSB DATE	TSB TITLE
SI B09 04 09	2019/10/30	ENABLING CODES
SI B09 01 18	2019/10/23	IRAP CONTROL UNIT RECOVERY
SI B01 29 18	2019/10/18	N63 CLASS ACTION SETTLEMENT FOR OIL CONSUMPTION AND BATTERY DRAIN - OVERVIEW
SI B52 15 19	2019/10/02	FRONT SEAT HAS SIDE TO SIDE PLAY AND CAN MAKE NOISES WHEN CORNERING
TRI B00 02 17	2019/10/02	BMW GROUP TECHNICAL SUPPORT AND NEW TSARA HOTLINE
TRI B00 12 19	2019/10/01	EVENT DATA RECORDERS IN BMW GROUP VEHICLES
SI B41 05 19	2019/09/27	PRELIMINARY DIAGNOSTICS FOR COLLISION REPAIRS
SI B00 07 06	2019/09/15	CBS Key Data from Key Reader is not Updated or Current
SI B52 18 19	2019/08/28	REQUIRED HARDWARE REPLACEMENT DURING SEAT SERVICE/REPAIR
SI B04 22 14	2019/08/15	TRANSPORT MODE SWITCHING DEVICE: TMSD
SI B34 10 19	2019/08/08	HELPFUL INFORMATION FOR CUSTOMER DISCUSSIONS REGARDING MOTORSPORT VEHICLE BRAKES
SI B11 01 15	2019/08/01	ENGINE OIL QUICK REFERENCE CHART AND DRAIN PLUG TORQUE
SI B65 15 19	2019/08/01	SECURITY IMPROVEMENTS FOR CONNECTEDDRIVE
SI B16 04 16	2019/08/01	RECALL CAMPAIGN 16V-746: REPLACE LOW-PRESSURE ELECTRIC IN-TANK FUEL PUMP
SI B04 13 19	2019/07/01	WIPER ARM ADJUSTMENT TOOL UPDATE KIT
SI B04 12 19	2019/07/01	NEW IGNITION COIL TEST CABLES
SI B11 12 16	2019/07/01	SERVICE ACTION: N63T ENGINE - CHECK AND REPLACE THE CRANKCASE VENTILATION HOSES
SI B24 05 12	2019/07/01	ZF Technical Support via PuMA Cases

TSB NUMBER	TSB DATE	TSB TITLE
SI B01 01 13	2019/07/01	BMW MAINTENANCE PROGRAM: RADIO REMOTE CONTROL/KEY BATTERY REPLACEMENT
SI B01 01 08	2019/07/01	QCI CLAIM PAYMENT AND PROCESS CHANGE 2013; JULY 2019 UPDATE
SI B65 13 12	2019/07/01	HEADUNIT NAVIGATION MAPS HU-H HU-H2 HU-B
SI B11 07 11	2019/06/01	TURBOCHARGER FAILURE: OIL SUPPLY AND RETURN LINE BLOCKAGE AND PROPER REPAIRS
SI B52 09 19	2019/06/01	CRACKING NOISE FROM SEAT BACKREST
SI B16 04 19	2019/06/01	NEW REPLACEMENT FUEL TANK INTERNAL FUEL LINE CONNECTION
SI B00 03 06	2019/06/01	TEILECLEARING
SI B00 09 19	2019/06/01	CBS DISPLAYS AN IMPLAUSIBLE AVERAGE MILEAGE PER WEEK VALUE OF 1,584 IN ISPA NEXT
SI B01 14 15	2019/06/01	BMW Empower(Legacy) Non-Repair Customer Goodwill Initiative
SI B63 05 16	2019/06/01	HEADLIGHT ASSEMBLIES HAVE VISIBLE INTERNAL MOISTURE/CONDENSATION
SI B52 08 19	2019/06/01	Front Seat Backrest Makes a Cracking Noise When Folded Forward
SI B52 07 19	2019/06/01	Noise From the Front Seats When Adjusting the Seat Length
SI B84 02 14	2019/05/28	CONNECTEDDRIVE/BMW ASSIST SYSTEM DIAGNOSIS INFORMATION
SI B11 07 18	2019/05/01	ENGINE OIL DRAIN PLUG THREAD REPAIR TOOL
SI B84 03 11	2019/05/01	TELEMATICS CONTROL UNIT ACTIVATION VIA DCSNET FOR BMW ASSIST
SI B04 03 19	2019/05/01	TSARA VISION
SI B11 08 18	2019/05/01	12MM AND 14MM ENGINE OIL DRAIN PLUG IDENTIFICATION DURING VEHICLE MAINTENANCE AND REPAIRS
SI B00 06 19	2019/05/01	BMW VEHICLES - LEATHER CARE
SI B10 01 18	2019/04/01	TIS 2.0 FULL LAUNCH DATE AND DEACTIVATION OF TIS 1.0
SI B11 05 18	2019/04/01	RECALL 18V-248: ELECTRONIC AUXILIARY WATER PUMP

TSB NUMBER	TSB DATE	TSB TITLE
TRI B61 32 17	2019/04/01	VEHICLE AT STANDSTILL WIPER SPEED RESET FUNCTION DISABLED
SI B01 07 03	2019/03/28	BMW ENHANCED DEALER SELF-AUTHORIZED (DSA) GOODWILL PROGRAM
SI B34 01 14	2019/02/21	VIBRATION WHEN BRAKING: DIAGNOSING AND REPAIRING
SI B65 08 07	2019/02/06	USB Audio Interface
SI B65 09 16	2019/02/05	RADIO / NAVIGATION/ HEAD UNIT IDENTIFICATION
SI B51 19 18	2019/02/01	STAINING ON CERIUM GRAY TRIM
SI B04 02 19	2019/02/01	RELEASE TOOL FOR HEAD AIR BAG RETAINING CLIP
SI B01 22 18	2019/01/23	N63 ENGINE CLASS ACTION SETTLEMENT: BATTERY SERVICE BENEFIT 90 AH TO 105 AH RETROFITS/90 AH BATTERY REPLACEMENTS ONLY
SI B61 30 14	2019/01/10	BMW Maintenance Program: 12-Volt Battery Replacement Measure
SI B04 18 15	2018/12/17	ACTRON OBD SCAN TOOL
SI B65 19 15	2018/12/10	XM SATELLITE RADIO RECEPTION
SI B01 21 18	2018/12/05	N63 ENGINE: OIL CONSUMPTION CLASS ACTION SETTLEMENT DIAGNOSIS AND REPAIR PROCEDURES
SI B01 28 18	2018/12/04	N63 ENGINE REPAIRS: RENTAL CARS FOR OUT OF SERVICE VEHICLES
SI B61 08 00	2018/12/01	Closed-circuit Current Measurement
TRI B07 03 18	2018/12/01	ISTA EXPERT MODE: MEASURING WHILE DRIVING
TRI B10 04 17	2018/12/01	TECHNICAL SERVICE VIDEOS AVAILABLE ON VIMEO
TRI B41 02 18	2018/12/01	ROUGH SURFACE TEXTURE ON CAST FRONT SPRING SUPPORTS
SI B04 15 18	2018/12/01	ACTRON ACCUMULATED MISFIRE COUNTER
SI B12 31 18	2018/12/01	ACTRON ACCUMULATED MISFIRE COUNTER
SI B01 16 15	2018/12/01	AN ADD ENGINE OIL CHECK CONTROL MESSAGE DISPLAYS
SI B04 11 18	2018/11/01	COMPRESSION ADAPTER WITH SEALING RING

TSB NUMBER	TSB DATE	TSB TITLE
SI B08 04 18	2018/11/01	TAKATA AIR BAG RECALL – TOWING OF CUSTOMER VEHICLES
SI B11 01 13	2018/10/30	N63 AND N63T ENGINE: ENGINE OIL CONSUMPTION, ENGINE OIL TOP-UPS AND REFILL CAPACITY
SI B61 30 17	2018/10/23	RAIN/LIGHT SENSOR (RLS): OIL LEAKAGE FROM GEL PAD
TRI M07 01 18	2018/10/01	NON ELECTRICAL DIAGNOSIS NED NEXT
TRI B84 11 18	2018/10/01	BLUETOOTH/CARPLAY: DIAGNOSIS INFORMATION OVERVIEW
SI B01 30 18	2018/10/01	NEW AND PRE-OWNED INVENTORY DELIVERY/STOP-SALE VEHICLE COMPENSATION PROGRAM
SI B01 23 18	2018/10/01	N63 ENGINE OIL CONSUMPTION/BATTERY DRAIN CLASS ACTION LAW SUIT SETTLEMENT: FUTURE ENGINE OIL SERVICE BENEFIT
TRI B07 01 18	2018/09/01	NON ELECTRICAL DIAGNOSIS NED NEXT
SI B84 06 16	2018/09/01	BMW ONLINE NON-FUNCTIONAL: CHECK ICC-ID IN ACCOUNT
SI B11 11 17	2018/09/01	ENGINE LEAK DIAGNOSIS ON TURBOCHARGED V8 ENGINES
SI B04 10 18	2018/09/01	COMPRESSION ADAPTER
SI B34 10 16	2018/09/01	BRAKE PAD MAINTENANCE SERVICES: BRAKE DISC RESURFACING GUIDELINES
SI B00 05 18	2018/08/01	VEHICLE LABELS FOR CALIFORNIA PROPOSITION 65
SI B01 25 18	2018/08/01	MAINTENANCE "REFRESH" UPDATE: NEW SYSTEM ENHANCEMENTS FOR STANDARD MAINTENANCE PROGRAM
SI B11 03 08	2018/07/17	CRANKCASE VENTILATION SYSTEM DIAGNOSIS AND MEASUREMENT
SI B64 04 03	2018/07/01	AIR CONDITIONING SYSTEM HAS A MUSTY ODOR
SI B52 03 18	2018/06/01	MEMORY SEAT ADJUSTMENT IS LIMITED
SI B04 06 18	2018/06/01	ENGINE OIL DRAIN PLUG THREAD REPAIR TOOL
SI B65 07 09	2018/06/01	NAVIGATION SYSTEM: REPORTING MISSING OR INCORRECT ROAD MAP DATA
SI B32 07 18	2018/06/01	REQUIRED HARDWARE REPLACEMENT DURING WHEEL ALIGNMENTS

TSB NUMBER	TSB DATE	TSB TITLE
SI B01 09 15	2018/05/01	BMW ENGINE OIL REPAIR ORDER INVOICING PROCEDURE
SI B32 03 18	2018/05/01	STEERING NOISES OR JERKING AT SLOW SPEED
SI B65 11 17	2018/05/01	NAVIGATION PRO (NBT EVO) MAP UPDATE NOT POSSIBLE, NAVIGATION DOES NOT START
SI B01 29 16	2018/05/01	BMW RECALL/SERVICE ACTION REPAIRS - ALTERNATIVE MOBILITY SOLUTIONS (AMS)
SI B84 08 18	2018/05/01	HEAD UNIT HIGH 2 RESET WHILE BLUETOOTH IS CONNECTED
SI B84 07 18	2018/04/01	IPHONE: CALL LIST MISSING AFTER RESTART
SI B66 05 18	2018/04/01	COMFORT ACCESS SPORADICALLY INACTIVE VIA DOOR HANDLE
SI B66 10 18	2018/04/01	REAR VIEW CAMERA CANNOT BE CONTROLLED VIA IDRIVE
SI B62 12 15	2018/04/01	INSTRUMENT CLUSTER OUTSIDE TEMPERATURE DISPLAY IMPLAUSIBLE
SI B34 05 08	2018/04/01	BRAKE ROTOR MINIMUM THICKNESS
SI B31 01 12	2018/04/01	CRACKING NOISES FROM THE FRONT AXLE AREA WHILE TURNING THE WHEELS, WHEN STATIONARY OR PARKING
SI B41 01 04	2018/03/01	STRUCTURAL REPAIR REQUIREMENTS
SI B06 03 18	2018/03/01	Service Roundtable: March Show
SI B51 30 16	2018/03/01	TAILGATE UNINTENTIONALLY OPENS
SI B01 02 06	2018/03/01	APPROVED BMW ELECTRONIC ARCHIVING SYSTEMS (EAS), SYSTEM EVALUATIONS AND CENTER CERTIFICATION
SI B11 02 13	2018/02/01	CPO INSPECTION GUIDELINES: ENGINES REQUIRING A TECHNICAL PUMA CASE
SI_B11_09_16	2018/02/01	N63, N63TU, S63 and S63TU Engines: Oil Leak from the Rear of the Engine and Transmission Bell Housing
SI B04 04 18	2018/02/01	TIRE VALVE TORQUE WRENCH
SI_B84_11_17	2018/02/01	BMW APPS RANDOMLY STARTS PLAYING ON ITS OWN
SI_B04_12_17	2018/02/01	FUEL TANK SIPHON KIT GASOLINE & DIESEL
SI B04 02 18	2018/02/01	DRIVESHAFT CENTERING BUSHING TOOL

TSB NUMBER	TSB DATE	TSB TITLE
SI_B84_03_14	2018/01/01	Bluetooth Connection Failures
SI_B65_03_18	2018/01/01	NO AUDIO PLAYBACK AFTER REPLACING THE HEAD UNIT HIGH 2 (HU-H2)
SI_B04_32_15	2018/01/01	UPDATING END OF SERVICE TESTER (EOS) SOFTWARE
SI_B61_06_03	2018/01/01	WIPER BLADE ASSEMBLIES AND REPLACEABLE RUBBER INSERTS
TRI_B84_01_18	2018/01/01	USB AUDIO INTERFACE CHARGING PROBLEMS
SI_B04_02_11	2017/12/01	MOBILE LIFTING TABLE
SI_B66_08_14	2017/12/01	Side View Camera Does Not Display Picture
SI_B65_09_15	2017/12/01	NBT Head Unit High (HU-H) Resets Intermittently or Permanently
SI_B08_08_17	2017/12/01	USE OF MOBILE SERVICE VEHICLES FOR TAKATA RECALLS
SI_B11_08_15	2017/11/01	N63 and S63 Engine: Valve Seal Replacement
SI_B04_10_17	2017/11/01	BRAKE ROTOR GAUGE KIT
SI_B65_25_15	2017/11/01	INCREMENTAL MAP UPDATE OF THE NBT EVO HEAD UNIT
SI_B34_06_13	2017/11/01	BRAKE DISC AND BRAKE PAD SERVICE AND REFERENCE INFORMATION
SI_B04_11_17	2017/11/01	WIRE INSULATION STRIPPERS
SI_B65_22_17	2017/11/01	CHECK CONTROL MESSAGE: RESTRAINT SYSTEMS FAILED
SI_B16_01_07	2017/11/01	TESTING EVAPORATIVE SYSTEMS FOR LEAKS
SI_B66_21_16	2017/10/02	KAFAS CAMERA-BASED ASSISTANCE SYSTEM LIMITS
SI_B84_03_16	2017/10/01	SERVICE ACTION: GLOBAL SYSTEM FOR MOBILE COMMUNICATIONS COMBOX DEACTIVATION / DISCONTINUATION WITH 4 YEAR ASSIST SERVICE
SI_B84_08_16	2017/10/01	SERVICE ACTION: GSM COMBOX DEACTIVATION / DISCONTINUATION WITH 10 YEAR ASSIST SERVICE
SI_B51_11_11	2017/10/01	Doors Will Not Open or Close when Outside Temperature Is Below Freezing
SI_B08_06_17	2017/10/01	SYSTEM ENHANCEMENTS TO INCREASE CAMPAIGN VISIBILITY

TSB NUMBER	TSB DATE	TSB TITLE
SI_B66_18_16	2017/10/01	INFORMATION ON THE OPERATION OF THE SMART OPENER
SI_B34_11_17	2017/10/01	NEW BMW BRAKE PAD PASTE CAN
SI_B84_05_17	2017/10/01	IPHONE CALLS NOT BEING ROUTED THROUGH HEAD UNIT
SI_B13_03_15	2017/10/01	N20, N26, N55, N63TU, S63TU and S55 Engines: Bosch Injector ETK Part Number Error
SI_B65_04_14	2017/09/01	AIRBAG WARNING LIGHT: ACSM FC 930A60 OR 930A1C SEAT OCCUPANCY DETECTION
SI_B01_05_14	2017/07/01	BMW PRODUCT QUALITY ANALYSIS: SPECIAL PARTS RETURN REQUESTS
TRI_B84_04_17	2017/07/01	KISU DATA UPDATE MESSAGE DISPLAYED
SI_B34_06_17	2017/07/01	"DRIVING STABILIZATION. DRIVE AT A MODERATE SPEED" MESSAGE
SI_TRI_B84_01_17	2017/07/01	KISU DATA UPDATE MESSAGE DISPLAYED
SI_B65_16_14	2017/07/01	CENTRAL INFORMATION DISPLAY INTERMITTENTLY DIMMING OR FLASHING OFF/ON
SI_B09_01_17	2017/07/01	PILOT PROGRAM: IRAP CONTROL UNIT RECOVERY
TRI_B09_02_17	2017/07/01	PILOT PROGRAM: IRAP CONTROL UNIT RECOVERY
SI_B01_12_17	2017/06/01	VDC (PORT-INSTALLED) ACCESSORIES: DEFECTS IN MATERIAL OR WORKMANSHIP OR NOT INSTALLED
SI_B01_13_17	2017/06/01	SHIPPING SPECIFIC NON-DEPLOYED VEHICLE SAFETY DEVICES TO LIGHTING RESOURCES, LLC
SI_B12_10_08	2017/06/01	AFTERMARKET "ENGINE PERFORMANCE TUNING" KITS
TRI_B09_01_17	2017/05/01	PROBLEM IN ACTIVATION OF ENABLING CODES
SI_B84_02_17	2017/05/01	BMW CONNECTED DRIVE SERVICE COCKPIT
SI_B11_09_15	2017/05/01	Engine Replacement and Engine Repairs
SI_B62_16_16	2017/05/01	VERTICAL LINES IN HEAD-UP DISPLAY
SI_B06_05_17	2017/05/01	Service Roundtable: May Show
SI_B34_11_16	2017/04/01	ON-CAR BRAKE LATHE

TSB NUMBER	TSB DATE	TSB TITLE
SI_B06_04_17	2017/04/01	Service Roundtable: April Show
SI_B65_06_16	2017/03/01	NBT HEAD UNIT ABORTS IMPORT OF CD
SI_B65_06_17	2017/03/01	SATELLITE RADIO DETERIORATION IN RECEPTION QUALITY DUE TO NEW CELLULAR FREQUENCIES
SI_B10_02_17	2017/03/01	LAUNCH OF TECHNICAL REFERENCE INFORMATION DOCUMENTS
SI_B04_06_17	2017/03/01	CRIMP CLAMP PLIERS
SI_B08_03_17	2017/02/01	VEHICLE CAMPAIGN STATUS
SI_B11_17_15	2017/02/01	UPPER OIL PAN REMOVAL AND INSTALLATION REPAIR INSTRUCTIONS
SI_B06_02_17	2017/01/01	Service Roundtable: January Show
SI_B34_12_16	2017/01/01	BRAKES REPAIR GUIDE - WORKSHOP POSTER
SI_B34_01_15	2016/12/01	BMW Brake Systems: Customer Information Brochure
SI_B04_27_16	2016/12/01	ENGINE INTAKE AIR SEAL PLUGS
SI_B01_06_13	2016/12/01	60-Day Bundling of Maintenance Services for Customer Satisfaction
SI_B61_27_16	2016/12/01	SERVICE ACTION: PROGRAMMING CONTROL UNITS (REAR WINDOW HEATING)
SI_B04_26_16	2016/11/02	ON-CAR BRAKE LATHE
SI_B01_22_16	2016/11/01	Dangerous Goods (DG) Part Return Program
SI_B04_23_10	2016/11/01	Approved Battery Charger/Power Supplies
SI_B65_26_16	2016/11/01	USB DEVICE IS NOT DETECTED BY CHAMP2 HEAD UNIT
SI_B01_25_16	2016/11/01	DCSNET REPAIR ORDER/CLAIM - DISABLED VEHICLE: TOW/EMERGENCY SERVICE INDICATOR AND ENHANCED QUALITY REPORTING
SI_B10_01_16	2016/11/01	Deactivated Service Information Bulletin List
NHTSA16V746000	2016/10/17	Recall - Loose Fuel Pump Wiring May Cause Stall/Fuel Leak
SI_B65_24_16	2016/10/01	NBT NAVIGATION DOES NOT ROUTE ON TOLL ROADS

TSB NUMBER	TSB DATE	TSB TITLE
SI_B65_25_16	2016/10/01	USB CABLE: BATTERY DISCHARGE/AUDIO FAILURE/RADIO RECEPTION
340516	2016/10/01	CBS Brake Pad Calculation and Correction
652316	2016/10/01	Audio Volume Not Restored After MSA Stop, Entry Head Unit
SI_B01_26_16	2016/10/01	ADMINISTRATIVE PAYMENT - ELIGIBILITY FOR VALID AND APPROVED TEILECLEARING CASES (TC)
012116	2016/09/01	Remote Key Read and Service Consultation Preparation
170216	2016/09/01	Cooling System Contaminated With Oil
010515	2016/08/12	In-Tank Fuel Delivery Module (Pump) Warranty Extension
SI_B07_06_08	2016/08/01	DIAGNOSIS AND PROGRAMMING FEEDBACK WITH ISTA
111616	2016/08/01	Crankshaft Seal and Bed Plate Liquid Sealer
SI_B11_03_13	2016/08/01	ENGINE OIL CONSUMPTION
SI_B84_05_16	2016/08/01	BMW ONLINE NON-FUNCTIONAL: CHECK ICC-ID IN ACCOUNT
SI_B51_24_16	2016/08/01	WATER LEAKING INTO REAR COMPARTMENT
090216	2016/08/01	IRAP Next
040312	2016/07/01	Workshop Engine Crane
043011	2016/07/01	TKR Spare Parts Ordering
041916	2016/07/01	New Crimping Die Jaws
041516	2016/06/01	132 Pin Breakout Box - Repair Kit
SI_B11_04_13	2016/06/01	N63TU ENGINE: ENGINE OIL CONSUMPTION
SI_B62_10_16	2016/06/01	Head-Up Display does not Show Full Street Names
070116	2016/05/02	Vehicle - Integrated Measurement Interface Box - IMIB R2 V6
SI_B62_07_16	2016/05/01	Unintentional Active ECO-PRO Bonus Miles Reset
660916	2016/05/01	Collision Avoid. - Collision Warning/Pedestrian Warning Failed
SI_B32_06_16	2016/05/01	Troubleshooting intermittent Steering Assistance with Electric Power Steering (EPS)

TSB NUMBER	TSB DATE	TSB TITLE
840715	2016/04/01	SOS Malfunction Displayed Sporadically
SI_B00_05_16	2016/04/01	Submitting PuMA/ TeileClearing Cases via PuMA App on Android Devices
SI_B04_10_16	2016/04/01	Antenna Test Cables
520116	2016/04/01	Interior - Front Seat Backrests Vibrate/Rattle On Rough Roads
SI_B00_04_16	2016/04/01	Long-term vehicle storage recommendations
041515	2016/03/01	Engine - Valve Seal Replacement Kit
SI_B00_05_15	2016/02/01	BMW Group Technical Support and "New" PuMA Hotline
SI_B00_05_14	2016/02/01	2016 Service Quality Toolbox Update
650216	2016/02/01	Audio - Speaker Testing
111614	2016/02/01	Engine - Check Timing Chain
610314	2016/02/01	Battery - Battery Related Check Control Message on Cold Days
240412	2016/02/01	A/T - ZF Automatic Transmission Oil Leaks, Diagnosis Repairs
611305	2016/02/01	Battery - Battery Discharged Diagnostics
510116	2016/01/01	Campaign - Heated Rear Window Module Software Update
161514	2016/01/01	Emissions - MIL ON, DTC 190302
090215	2016/01/01	Infotainment - Headunit Has An Invalid IP Address
124515	2015/12/01	Campaign - Criteria Based Service Intervals
620715	2015/11/01	Instruments - Instrument Cluster is Partially Blank
612215	2015/11/01	Body - Rear Window Defogger is Inoperative
010615	2015/11/01	Vehicle - Warranty Extension Due To Class Action Lawsuit
123715	2015/10/01	Engine Controls - Drivetrain Malfunction Lamp On Multiple DTC's
240315	2015/10/01	A/T - Out of Warranty Transmission Replacement 6HP and 8HP
651015	2015/10/01	Navigation Sys - Road Map Installation Using USB Stick
100115	2015/09/01	Vehicle - List of Deactivated Service Bulletins

TSB NUMBER	TSB DATE	TSB TITLE
111215	2015/08/01	Fuel - Damaged Vacuum Hoses Repair for turbocharged Vehicles
511615	2015/07/02	Delivery Stop: Remove Engine Oil Label
111814	2015/07/01	Engine - Engine Oil Residue Near Oil Fill Cap
130215	2015/07/01	Campaign - High Pressure Fuel Pump Replacement
360215	2015/05/01	Tires - Tire Pressure Lost After Replacing Wheel Electronics
011115	2015/04/01	Engine - Oil Pan Drain Plug Threads Stripped or Cross Threaded
130415	2015/04/01	Fuel System - Low Pressure Sensor, Line Installation Procedure
110614	2015/04/01	Campaign - N63 Engine Service
320511	2015/02/01	Interior - Leather is Peeling off The Steering Wheel
650509	2015/01/01	Navigation System - Navigation Software Information
610313	2015/01/01	Electrical - High Battery Discharge Warning Message
010410	2015/01/01	Engine - Condition Based Service and Maintenance
340514	2014/12/01	ABS/TCS - TCS Module Aborted When Programming Vehicle
840412	2014/12/01	Cell Phone - iPhone(R) 6, 6 Plus, 5, 5S, 4S, 4 3GS Information
012214	2014/11/01	Interior - Interior Trim Components, Wear Vs. Defects
652013	2014/11/01	Keyless Entry - Vehicle In Transport Mode Cannot Unlock
631114	2014/10/01	Lighting - LED Low Beam Flashes After Ignition Turned On
280114	2014/10/01	ASMT - Oil Leakage Diagnosis
111914	2014/10/01	Engine - Valve Guide to Valve Stem Wear Measurement
122414	2014/09/01	Electrical - Proper Ignition Harness and Ground Connections
660211	2014/09/01	Keyless Sys. - Remote Control And Comfort Access Inop.
511413	2014/08/01	Body - Rear License Plate Bracket Screws Seized
511613	2014/08/01	Audio System - Speaker Cover Rattles On Rough Roads
650214	2014/07/01	Infotainment System - Headunit High is Constantly Resetting
SI_B61_01_09	2014/07/01	Windshield Washer Malfunctions

TSB NUMBER	TSB DATE	TSB TITLE
660414	2014/07/01	Instruments - Front Collision Warning Control Mssg. Displayed
652113	2014/07/01	Memory Position Sys.- Mirrors in Wrong Position when Unlocking
660614	2014/07/01	Collision Avoidance - Rear View Camera Doesn't Display on CID
360314	2014/06/01	Tire Monitor System - Incorrect Tire Position Displayed
620613	2014/05/02	Instruments - Condition Based Service Date is Reset to 01/2000
540214	2014/05/01	Body - Sunroof Does Not Close
130712	2014/05/01	Fuel Sys. - High-Pressure Fuel Injector Replacement Procedure
360211	2014/05/01	Tire Monitoring System- TPMS Functional Changes
340213	2014/05/01	Brakes - Incorrect Remaining Service Life From CBS Data
650514	2014/04/01	Instruments - Traffic Information is Inoperative
840913	2014/04/01	Infotainment - My BMW Remote App From iPhone(R) Concern
612213	2014/03/01	Battery - 'Increased Battery Discharge' CC Message on Startup
610514	2014/03/01	Electrical - Battery State of Charge Reference Chart
840114	2014/03/01	Accessory Controls - BMW Assist System Info. & Availability
320201	2014/02/01	Steering/Suspension - Steering Gear Replacement Due to Accident
840613	2014/02/01	Accessories - iPhone(R) Charging Status Switches ON and OFF
625513	2014/01/01	Infotainment - ConnectedDrive(R)/BMW Assist(R) Features Inop.
510414	2014/01/01	Body - BMW Group ColorSystem Document
121512	2014/01/01	Automatic Start/Stop (MSA) System - Benefits and Operation
650009	2014/01/01	Navigation System - Enabling the Navigation Map at QC1
610211	2014/01/01	Electrical - Advanced Onboard Battery Diagnostics
720213	2013/12/01	Restraints - Lower Front/Rear Seat Belt Buckle Not functional
511813	2013/12/01	Body Controls - Door Mirror Function Delayed After Unlocking
611109	2013/11/01	Electrical - Battery Charging And Testing Procedure
121813	2013/11/01	Engine Controls - MIL ON/Code 1D2008 Stored

TSB NUMBER	TSB DATE	TSB TITLE
640113	2013/10/01	Interior, A/C - IHKA Operating Panel Buttons Are Peeling
651112	2013/10/01	Audio Sys- Stored FM Stations Intermittently Default To FM 87.7
651113	2013/10/01	Air Bag - CIS Seat Mat Replacement
510913	2013/09/01	Body - Door Springs into Pre-Locking Position
130206	2013/09/01	Fuel System - TOP TIER Gasoline Usage Recommendations
651913	2013/08/01	Infotainment - SDARS Radio Stations Cannot Be Stored in Presets
650813	2013/08/01	Audio Sys. - Bang & Olufsen(R) Loudspeaker Illumination
090407	2013/07/01	Infotainment - Programming Failure Due to CD or DVD in Drives
090509	2013/07/01	CCC(R) - Enabling Code Information
511113	2013/06/01	Interior - Rattling Noise From Windshield Defroster Vents
320113	2013/06/01	Steering - Squeak Noise When Turning Steering Wheel
SI B13 02 11	2013/05/01	High-pressure Direct Injection Fuel System Repairs
840513	2013/05/01	BMW Assist(R) - TCB: Emergency Call is Erroneously Triggered
840603	2013/05/01	Cell Phone - iPhone(R) Charging Status Switches ON and Off
240213	2013/05/01	A/T - 8-Speed ZF A/T Diagnosis and Troubleshooting Hints
122211	2013/05/01	Fuel System - Vapor Forming In Fuel System MIL ON
613812	2013/05/01	Campaign - Program Car Access System (CAS) Control Modules
511013	2013/05/01	Interior - Center Console Makes Clicking Noises
330212	2013/04/01	Steering/Suspension - Rattle Noise From Rear Axle
520113	2013/03/01	Restraints - Front Crash-Active Headrest Limited Height Adj.
840413	2013/03/01	Instruments - TCB: Emergency Call Is Disabled
651009	2013/03/01	Navigation System - Vehicle Position Missing/Incorrect
520413	2013/03/01	Interior - Front Seat Side-to-Side Play, Noises when Cornering
720113	2013/02/01	Interior - Damage To Side Airbag Trim Mount On Front Seat
513012	2013/02/01	Interior - Grating/Grinding Noise From Center Console

TSB NUMBER	TSB DATE	TSB TITLE
620213	2013/02/01	Instruments - Only Background Image And Gear Indicator Display
650713	2013/02/01	Audio Sys. - HiFi Audio Intermittently Cuts Out In All Modes
621012	2013/01/01	Instruments - Head-Up Display Is Too Dark
653209	2013/01/01	Audio System - Interference Noise From Speakers
651011	2012/12/01	Audio System - Cannot Select SIRIUS/XM(R) Preset 2
652212	2012/12/01	Campaign - CIC - Install Navigation Road Map Database 2013
340112	2012/12/01	Campaign - Replace Integrated Chassis Control Module
613512	2012/11/01	Radio/A/C - All Radio/A/C Functions Inop. With Vehicle Moving
110712	2012/11/01	Engine/Emissions - Oil Consumption/Rough Running Complaints
660612	2012/11/01	Collision Avoidance - Lane Change Warning Lamps On Mirrors Dark
512012	2012/11/01	Interior/HVAC - Rattle From Underneath Instrument Panel
160312	2012/10/01	Fuel System - Evaporative System Vacuum Leak Diagnosis
130612	2012/10/01	Fuel Sys. - Low Pressure Fuel Supply Sensor Diagnostic Error
652109	2012/09/01	Audio System - CD Artist/Song Titles Not Displayed
660512	2012/09/01	Collision Avoidance - Check Control Mssg. 'Front Camera Failed'
610212	2012/08/01	Computer/Controls - 'Electronic Malfunction' Displayed
110812	2012/08/01	Engine - Oil Pump Volume Control Valve Leaking
612212	2012/07/01	Electrical - 90AH Absorbed Glass Matt Battery Replacement
SI B00 03 11	2012/07/01	2012 Model Year New Vehicle Preparation and Maintenance Requirements
511912	2012/06/01	Interior - Creaking Noise From LH Center Console
511212	2012/06/01	Interior - Instrument Panel Rattle Noise From Passenger Side
840312	2012/06/01	Bluetooth(R) - iPhone(R) Is Not Displayed In Paired List
512112	2012/06/01	Interior - Rattle Noise From Steering Wheel Trim
110606	2012/05/01	Engine - Head Bolt Threads Pull Out of Engine Block

TSB NUMBER	TSB DATE	TSB TITLE
650612	2012/05/01	Audio/Battery - Failures Caused By Aftermarket USB Cable
110612	2012/05/01	Recall 12V-161 - Repl. Auxiliary Turbocharger Coolant Pump
640312	2012/05/01	Heating/A/C - Intermittent Knocking Heard Inside Vehicle
NHTSA12V161000	2012/04/05	Recall 12V161000: Auxiliary Water Pump Circuit Board
611212	2012/04/01	Body/Electrical - Drone From Front Of Vehicle When Horns Sound
620612	2012/04/01	Instruments - Maximum Permissible Speedometer Deviations
660112	2012/04/01	Collision Avoidance- Backup Camera Self-Calibration Mode
350112	2012/04/01	M/T - Repairs To Clutch Pedal Assembly
611512	2012/04/01	Electrical - Updated Battery Registration Procedure
840112	2012/04/01	Cell Phone - iPhone(R) Application (Apps) Stops Working
110109	2012/03/01	Engine - CPO Engine Inspection Information
111190	2012/03/01	Engine - E Series Engine Oil Capacities
090707	2012/03/01	Computers, Controls - Programming VS Veh. Data Status
650205	2012/02/01	Audio System - SIRIUS(R) Satellite Radio Information
110112	2012/02/01	Engine - N63 Cyl. Head Torque Spec. Missing From ISTA/D
SI B00 01 12	2012/02/01	Audit Process: BMW Warranty, CPO and Maintenance – 2012 Updates
512909	2012/02/01	Body - Windshield Urethane Sealant Information
610112	2012/01/01	Antitheft System - CAS Sys. Fault 93070D, No Start
651811	2012/01/01	Campaign 601 - 2012 CIC Navigation Road Map Database
520112	2012/01/01	Campaign 606 - Replace Bolted Connection On Front Seat
122010	2012/01/01	Fuel System - MIL ON Or Check Gas Cap Is Illuminated
110511	2011/12/01	Engine - Removal/Installation Tips
240511	2011/12/01	A/T - Failures Due To Incorrect Installation
620195	2011/11/01	Instruments - Odometer Reading Can't Be Recovered

TSB NUMBER	TSB DATE	TSB TITLE
611502	2011/11/01	Audio System/Instruments - Various System Complaints
330311	2011/11/01	Drivetrain - Clicking Noise From Rear Axle
540111	2011/10/01	Body - Test Plans For Panoramic Roof
513211	2011/10/01	Body - Front Window Inoperative
651511	2011/09/01	Entertainment Sys. - Audio Has Dropouts Or Distortions
840411	2011/09/01	BMW ASSIST(R) - System Isn't Working Properly
070211	2011/07/01	Computers/Controls - Recommended Diagnostic Procedures
650707	2011/07/01	Audio System - SDARS/SIRIUS(R) Radio Inoperative
130106	2011/05/01	Fuel System - Alcohol Fuel Blend Usage
161110	2011/04/01	Fuel System - Fuel Cap Tether Is Broken Or Lost
650410	2011/04/01	Navigation - Update Navigation After (CIC) Head Replaced
130510	2011/04/01	Fuel System - High Alcohol Fuel Detection
170106	2011/04/01	Cooling System - Information on Coolant Refilling