

iXSR Spektrum™ RaceWare™

Change Log – April 15th, 2025



Version 3.03.01

New Features

- Added a pre-built model configuration to the Model Setup screen supporting the LMT 2.0 vehicle.

Corrections & Improvements

- Fixed issue where custom Steering and Throttle mixing screens would crash if “None” was selected for the Target field.
- Changed ESC reported voltage telemetry to require a longer period of voltage below the alarm threshold before starting the alarm signal. This prevents the alarm from starting with a high current spike.

Version 3.02.06

New Features

- Motorcycle mode now includes Launch Control
- The New Model Setup Wizard has been updated
 - Pre-configured model configurations added to help ease model setup
 - Guided setup simplified.
- Adds support for SLT, this includes:
 - Binding Screen, the Desired Frame Rate options are now 5.5, 11, 22, and SLT
 - Refer to your receiver's instructions for putting the receiver into bind mode. It varies with receiver type.
 - Pre-configured SLT model options added to New Model Setup Wizard
 - SLT Basic
 - SLT with DSC
 - SLT with 4WS
- Update how Aux Channels are configured
 - On the Setup Screen all Aux configuration buttons have been combined into a single "AUX Setup" button that now displays a list of all AUX channels available.
 - Selecting an item on the AUX Setup screen will take you to the screen to edit the desired channel.
- Items were added to the Mixing screen to allow configuration of the built-in Steering and Throttle mixes that are available.
- Added the ability to create a MySpektrum account and register the radio directly within the RaceWare application.

Corrections & Improvements

- Fixed issue on Telemetry screen where Main Battery Voltage cannot be updated
- Fixed issue where unexpected ? characters were appearing at end of Firma Programming list
- Throttle Rate field now updates when switching between Drive Modes
- Time values now take affect when changed on screen, without having to first select Back on the screen
- Steering Rate values on the Home Screen are now updated properly with Drive Mode change.
- When a new Audio or Mix Event is created, it will be enabled by default
- When deleting the current active model, the model image in the upper right of the screen is now updated properly to the one for the newly activated model.

iXSR Spektrum™ RaceWare™

Change Log – February 20th, 2025



Version 3.01.01

New Features

- Added the ability to have the name of the current Drive Mode spoken when switching between modes

Corrections & Improvements

- Bluetooth model transfer between iXSR radios has been fixed
- Smart Battery startup voltage warning is now triggering correctly
- Transferring a trimmer from one function to another is now handled properly

iXSR Spektrum™ RaceWare™

Change Log



Version 3.00.12

Initial Release