

Product discontinuation notification (PDN)

Title / short description	Discontinuation of VARIOCON item selection
Affected article category	Connector
Change category	Discontinuation
Change number	IAB250001-01
Reason for PCN/PDN Revision	

Purpose/objective of the change

Discontinuation due to portfolio streamlining

Detailed description of the change

Our goal is to provide you with state-of-the-art products for your applications. However, it may be necessary to phase out certain components from time to time for commercial or technical reasons. For this reason, the listed items will be discontinued in due time.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2026-06-30
Effective date (EOP)	2026-06-30	End of Service (EOSR)	-
End of Sales (EOS)	2025-12-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IAB250001-01_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1852820	VC-TFS 8	-	-	-	-
1854022	VC-AMS 8				
1855128	VC-K-T4-R				
1852862	VC-AF				
1853913	VC-K-KV-PG21(11,5-15,5)				
1852846	VC-TFS 2				
1886566	VC-MEMV-T2-Z-M25				
1886579	VC-MEMV-T3-Z-M25				
1853476	VC-TFS 6				
1855115	VC-K-T3-R				
1424368	VC-K-T3-IN (13-25)				
1855102	VC-K-T2-R				
1607474	VC-TFS 5-PEA				
1852927	VC-TR4/5M				
1853900	VC-K-KV-PG21(9-13)				
1853007	VC-AR4/5M				
1607274	VC-TR4/5M-PEA-S88888-SET				
1853528	VC-AMS 2				
1885978	VC-AML-L228-2AF NZ				
1852833	VC-AML 8				
1853531	VC-AML 6				
1852985	VC-AR2/3M				
1855092	VC-K-T1-R				
1884885	VC-AMLV 8				
1647734	VC-AR3/4M(2+6)-EMV NZ				
1852930	VC-K-T1-Z				
1852972	VC-AR1/2M				
1852998	VC-AR3/4M				
1853890	VC-K-KV-PG21(7-10,5)				
1855107	VC-K-T2-R-M25				
1687244	VC-AMLV-L228-2AF NZ				
1583878	VC-AMC 5				
1885237	VC-AMLV-L2266-2AF NZ				
1886663	VC-MP-T4-R-M25				
1852914	VC-TR3/4M				
1852901	VC-TR2/3M				
1886605	VC-MEMV-T2-R-M25				
1852891	VC-TR1/2M				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
1607407	VC-AR2/3M-S888-SET				
1852948	VC-K-T2-Z-M25				
1607748	VC-AMS 5				
1853751	VC-K-KV-PG16(7-10,5)				
1855120	VC-K-T3-R-M25				
1607745	VC-AMS 4				
1853764	VC-K-KV-PG16(9-13)				
1853939	VC-K-KV-PG21(17-20,5)				
1885224	VC-AR3/4M-EMV NZ				
1607467	VC-TFS 4-PEA				
1582520	VC-TR-PE-POL4 METALL				
1854019	VC-AMS 6				
1853683	VC-SD2				
1607774	VC-AR2/3M-PEA				
1607178	VC-TR4/5M-PEA-S22222-SET				
1607154	VC-TR2/3M-PEA-S222-SET				
1607509	VC-AML 4				
1853696	VC-SD3				
1885567	VC-K-KV-PG21 2X7,2/1X10,5				
1853227	VC-AR2-EMV				
1607088	VC-TR4/5M-PEA				
1628246	VC-MP-T2/18 PEA				
1853353	VC-MEMV-T4-Z				
1583872	VC-TR2/3M-SEW				
1852859	VC-AML 2				
1623598	VC-M-T2/10() S822 NZ:TS02				
1884911	VC-MP-T3-Z				
1607732	VC-MP-S1-2M6				
1583880	VC-K-T2-IN (10-25) G				
1607761	VC-AR1/2M-PEA				
1852943	VC-K-T2-Z				
1886760	VC-SD-A1				
1583874	VC-TR3/4M-SEW				
1607298	VC-AR1/2M-S22-SET				
1854200	VC-EMV-KV-PG21(9-13/ 9,5)				
1607062	VC-TR2/3M-PEA				
1884568	VC-MP-K1				
1853926	VC-K-KV-PG21(14-18)				
1607059	VC-TR1/2M-PEA				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
1855133	VC-K-T4-R-M25				
1607457	VC-HS-M3X14				
1886647	VC-MP-T2-R-M25				
1854857	VC-M-KV-PG16(11,5-15,5)	-	-	-	-
1853230	VC-AR3-EMV				
1607143	VC-TR1/2M-PEA-S22-SET				
1607431	VC-AR4/5M-S88888-SET				
1886773	VC-SD-A2				
1886634	VC-MP-T1-R-M20				
1607841	VC-T4-PR-DI				
1854035	VC-M-KV-PG21(11,5-15,5)				
1583542	VC-AMS 2-PE				
1886650	VC-MP-T3-R-M25				
1854242	VC-EMV-KV-PG21(11,5-15,5/13,5)				
1886635	VC-MP-T1-R-M25				
1852875	VC-BZS WH				
1607523	VC-AML 5				
1855157	VC-MEMV-T3-R				
1855097	VC-K-T1-R-M20				
1853243	VC-AR4-EMV				
1665075	EWR				
1607075	VC-TR3/4M-PEA				
1855131	VC-MEMV-T1-R				

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1852820;VC-TFS 8;-;-;-;27440192;
1854022;VC-AMS 8;;;;;27440192;
1855128;VC-K-T4-R;;;;;27440202;
1852862;VC-AF;;;;;27440210;
1853913;VC-K-KV-PG21(11
1852846;VC-TFS 2;;;;;27440192;
1886566;VC-MEMV-T2-Z-M25;;;;;27440202;
1886579;VC-MEMV-T3-Z-M25;;;;;27440202;
1853476;VC-TFS 6;;;;;27440192;
1855115;VC-K-T3-R;;;;;27440202;
1424368;VC-K-T3-IN (13-25);;;;;27440202;
1855102;VC-K-T2-R;;;;;27440202;
1607474;VC-TFS 5-PEA;;;;;27440192;
1852927;VC-TR4/5M;;;;;27440210;
1853900;VC-K-KV-PG21(9-13);;;;;27140801;
1853007;VC-AR4/5M;;;;;27440210;
1607274;VC-TR4/5M-PEA-S88888-SET;;;;;27440192;
1853528;VC-AMS 2;;;;;27440192;
1885978;VC-AML-L228-2AF NZ;;;;;27440109;
1852833;VC-AML 8;;;;;27440192;
1853531;VC-AML 6;;;;;27440192;
1852985;VC-AR2/3M;;;;;27440210;
1855092;VC-K-T1-R;;;;;27440202;
1884885;VC-AMLV 8;;;;;27440192;
1647734;VC-AR3/4M(2+6)-EMV NZ;;;;;27440312;
1852930;VC-K-T1-Z;;;;;27440202;
1852972;VC-AR1/2M;;;;;27440210;
1852998;VC-AR3/4M;;;;;27440210;
1853890;VC-K-KV-PG21(7-10
1855107;VC-K-T2-R-M25;;;;;27440202;
1687244;VC-AMLV-L228-2AF NZ;;;;;27440109;
1583878;VC-AMC 5;;;;;27440202;
1885237;VC-AMLV-L2266-2AF NZ;;;;;27440192;
1886663;VC-MP-T4-R-M25;;;;;27440202;
1852914;VC-TR3/4M;;;;;27440210;
1852901;VC-TR2/3M;;;;;27440210;
1886605;VC-MEMV-T2-R-M25;;;;;27440202;
1852891;VC-TR1/2M;;;;;27440210;
1607407;VC-AR2/3M-S888-SET;;;;;27440192;
1852948;VC-K-T2-Z-M25;;;;;27440202;
1607748;VC-AMS 5;;;;;27440192;
1853751;VC-K-KV-PG16(7-10
1855120;VC-K-T3-R-M25;;;;;27440202;
1607745;VC-AMS 4;;;;;27440192;
1853764;VC-K-KV-PG16(9-13);;;;;27140801;
1853939;VC-K-KV-PG21(17-20
1885224;VC-AR3/4M-EMV NZ;;;;;27440312;
1607467;VC-TFS 4-PEA;;;;;27440192;
1582520;VC-TR-PE-POL4 METALL;;;;;27440192;
1854019;VC-AMS 6;;;;;27440192;
1853683;VC-SD2;;;;;27440192;
1607774;VC-AR2/3M-PEA;;;;;27440210;

1607178;VC-TR4/5M-PEA-S22222-SET;;;;;27440192;
1607154;VC-TR2/3M-PEA-S222-SET;;;;;27440192;
1607509;VC-AML 4;;;;;27440192;
1853696;VC-SD3;;;;;27440192;
1885567;VC-K-KV-PG21 2X7
1853227;VC-AR2-EMV;;;;;27440210;
1607088;VC-TR4/5M-PEA;;;;;27440210;
1628246;VC-MP-T2/18 PEA;;;;;
1853353;VC-MEMV-T4-Z;;;;;27440202;
1583872;VC-TR2/3M-SEW;;;;;27440192;
1852859;VC-AML 2;;;;;27440192;
1623598;VC-M-T2/10() S822 NZ:TS02;;;;;27440192;
1884911;VC-MP-T3-Z;;;;;27440202;
1607732;VC-MP-S1-2M6;;;;;27440202;
1583880;VC-K-T2-IN (10-25) G;;;;;27440202;
1607761;VC-AR1/2M-PEA;;;;;27440210;
1852943;VC-K-T2-Z;;;;;27440202;
1886760;VC-SD-A1;;;;;27440192;
1583874;VC-TR3/4M-SEW;;;;;27440192;
1607298;VC-AR1/2M-S22-SET;;;;;27440192;
1854200;VC-EMV-KV-PG21(9-13/ 9
1607062;VC-TR2/3M-PEA;;;;;27440210;
1884568;VC-MP-K1;;;;;27440202;
1853926;VC-K-KV-PG21(14-18);;;;;27140801;
1607059;VC-TR1/2M-PEA;;;;;27440210;
1855133;VC-K-T4-R-M25;;;;;27440202;
1607457;VC-HS-M3X14;;;;;27440192;
1886647;VC-MP-T2-R-M25;;;;;27440202;
1854857;VC-M-KV-PG16(11
1853230;VC-AR3-EMV;;;;;27440210;
1607143;VC-TR1/2M-PEA-S22-SET;;;;;27440192;
1607431;VC-AR4/5M-S88888-SET;;;;;27440192;
1886773;VC-SD-A2;;;;;27440192;
1886634;VC-MP-T1-R-M20;;;;;27440202;
1607841;VC-T4-PR-DI;;;;;27440192;
1854035;VC-M-KV-PG21(11
1583542;VC-AMS 2-PE;;;;;27440192;
1886650;VC-MP-T3-R-M25;;;;;27440202;
1854242;VC-EMV-KV-PG21(11
1886635;VC-MP-T1-R-M25;;;;;27440202;
1852875;VC-BZS WH;;;;;27440192;
1607523;VC-AML 5;;;;;27440192;
1855157;VC-MEMV-T3-R;;;;;27440202;
1855097;VC-K-T1-R-M20;;;;;27440202;
1853243;VC-AR4-EMV;;;;;27440210;
1665075;EWR;;;;;27440192;
1607075;VC-TR3/4M-PEA;;;;;27440210;
1855131;VC-MEMV-T1-R;;;;;27440202;

15.Mai 5),,,,,;27140801;

5),,,,,;27140801;

5),,,,,;27140801;

5),,,,,;27140801;

2/1X10 5);;;;27140801;

5);;;;27140801;

15.Mai 5);-;-;-;-;27140801;

15.Mai 5);;;;27140801;

15.Mai 13.Mai 5);;;;27140801;

Phoenix Contact Art.Nr.;	Phoenix Contact Art.Bez.;	Phoenix Contact Alternativ Art.Nr.;	Phoenix Contact Alternati
1852820	;VC-TFS 8;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1854022	;VC-AMS 8;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1855128	;VC-K-T4-R;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440202
1852862	;VC-AF;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440210
1853913	;VC-K-KV-PG21(11		
1852846	;VC-TFS 2;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1886566	;VC-MEMV-T2-Z-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	
1886579	;VC-MEMV-T3-Z-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	
1853476	;VC-TFS 6;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1855115	;VC-K-T3-R;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440202
1424368	;VC-K-T3-IN (13-25);	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2
1855102	;VC-K-T2-R;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440202
1607474	;VC-TFS 5-PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440
1852927	;VC-TR4/5M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1853900	;VC-K-KV-PG21(9-13);	;;31.12.2025;30.06.2026;eCl@ss 13.0:	
1853007	;VC-AR4/5M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1607274	;VC-TR4/5M-PEA-S88888-SET;	;;31.12.2025;30.06.2026;eCl@	
1853528	;VC-AMS 2;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1885978	;VC-AML-L228-2AF NZ;	;;31.12.2025;30.06.2026;eCl@ss 13.0	
1852833	;VC-AML 8;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1853531	;VC-AML 6;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1852985	;VC-AR2/3M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1855092	;VC-K-T1-R;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440202
1884885	;VC-AMLV 8;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744019
1647734	;VC-AR3/4M(2+6)-EMV NZ;	;;31.12.2025;30.06.2026;eCl@ss	
1852930	;VC-K-T1-Z;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440202
1852972	;VC-AR1/2M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1852998	;VC-AR3/4M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1853890	;VC-K-KV-PG21(7-10		
1855107	;VC-K-T2-R-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744
1687244	;VC-AMLV-L228-2AF NZ;	;;31.12.2025;30.06.2026;eCl@ss 13.	
1583878	;VC-AMC 5;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440202
1885237	;VC-AMLV-L2266-2AF NZ;	;;31.12.2025;30.06.2026;eCl@ss 13:	
1886663	;VC-MP-T4-R-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27
1852914	;VC-TR3/4M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1852901	;VC-TR2/3M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1886605	;VC-MEMV-T2-R-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	
1852891	;VC-TR1/2M;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744021
1607407	;VC-AR2/3M-S888-SET;	;;31.12.2025;30.06.2026;eCl@ss 13.0	
1852948	;VC-K-T2-Z-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744
1607748	;VC-AMS 5;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1853751	;VC-K-KV-PG16(7-10		
1855120	;VC-K-T3-R-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	2744
1607745	;VC-AMS 4;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440192
1853764	;VC-K-KV-PG16(9-13);	;;31.12.2025;30.06.2026;eCl@ss 13.0:	
1853939	;VC-K-KV-PG21(17-20		
1885224	;VC-AR3/4M-EMV NZ;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	
1607467	;VC-TFS 4-PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0:	27440
1582520	;VC-TR-PE-POL4 METALL;	;;31.12.2025;30.06.2026;eCl@ss 13:	

1854019	;VC-AMS 6;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440192
1853683	;VC-SD2;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440192
1607774	;VC-AR2/3M-PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274
1607178	;VC-TR4/5M-PEA-S22222-SET;	;;31.12.2025;30.06.2026;eCl@
1607154	;VC-TR2/3M-PEA-S222-SET;	;;31.12.2025;30.06.2026;eCl@ss
1607509	;VC-AML 4;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440192
1853696	;VC-SD3;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440192
1885567	;VC-K-KV-PG21 2X7	
1853227	;VC-AR2-EMV;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274402
1607088	;VC-TR4/5M-PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274
1628246	;VC-MP-T2/18 PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27
1853353	;VC-MEMV-T4-Z;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 2744
1583872	;VC-TR2/3M-SEW;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274
1852859	;VC-AML 2;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440192
1623598	;VC-M-T2/10() S822 NZ:TS02;	;;31.12.2025;30.06.2026;eCl@:
1884911	;VC-MP-T3-Z;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 2744020
1607732	;VC-MP-S1-2M6;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 2744
1583880	;VC-K-T2-IN (10-25) G;	;;31.12.2025;30.06.2026;eCl@ss 13.0:
1607761	;VC-AR1/2M-PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274
1852943	;VC-K-T2-Z;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440202
1886760	;VC-SD-A1;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440192
1583874	;VC-TR3/4M-SEW;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274
1607298	;VC-AR1/2M-S22-SET;	;;31.12.2025;30.06.2026;eCl@ss 13.0:
1854200	;VC-EMV-KV-PG21(9-13/ 9	
1607062	;VC-TR2/3M-PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274
1884568	;VC-MP-K1;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440202
1853926	;VC-K-KV-PG21(14-18);	;;31.12.2025;30.06.2026;eCl@ss 13.0
1607059	;VC-TR1/2M-PEA;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 274
1855133	;VC-K-T4-R-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 2744
1607457	;VC-HS-M3X14;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27440
1886647	;VC-MP-T2-R-M25;	;;31.12.2025;30.06.2026;eCl@ss 13.0: 27
1854857	;VC-M-KV-PG16(11	
1853230	;VC-AR3-EMV;	;;00.00.0000;00.00.0000;
1607143	;VC-TR1/2M-PEA-S22-SET;	;;00.00.0000;00.00.0000;
1607431	;VC-AR4/5M-S88888-SET;	;;00.00.0000;00.00.0000;
1886773	;VC-SD-A2;	;;00.00.0000;00.00.0000;
1886634	;VC-MP-T1-R-M20;	;;00.00.0000;00.00.0000;
1607841	;VC-T4-PR-DI;	;;00.00.0000;00.00.0000;
1854035	;VC-M-KV-PG21(11	
1583542	;VC-AMS 2-PE;	;;00.00.0000;00.00.0000;
1886650	;VC-MP-T3-R-M25;	;;00.00.0000;00.00.0000;
1854242	;VC-EMV-KV-PG21(11	
1886635	;VC-MP-T1-R-M25;	;;00.00.0000;00.00.0000;
1852875	;VC-BZS WH;	;;00.00.0000;00.00.0000;
1607523	;VC-AML 5;	;;00.00.0000;00.00.0000;
1855157	;VC-MEMV-T3-R;	;;00.00.0000;00.00.0000;
1855097	;VC-K-T1-R-M20;	;;00.00.0000;00.00.0000;
1853243	;VC-AR4-EMV;	;;00.00.0000;00.00.0000;
1665075	;EWR;	;;00.00.0000;00.00.0000;
1607075	;VC-TR3/4M-PEA;	;;00.00.0000;00.00.0000;

1855131

;VC-MEMV-T1-R;

;;00.00.0000;00.00.0000;

iv Art.Bez.;Last Order;Last Shipment;Bemerkung

15.Mai

27440202
27440202

7440202

192
.0
27140801
l0
ss 13.0: 27440192

: 27440109

l0

2
13.0: 27440312

l0
l0
5); ;;31.12.2025;30.06.2026;eCl@ss 13.0: 27140801
0202
0: 27440109

3.0: 27440192
440202
.0
.0
: 27440202
.0
l: 27440192
0202

5); ;;31.12.2025;30.06.2026;eCl@ss 13.0: 27140801
0202

27140801
5); ;;31.12.2025;30.06.2026;eCl@ss 13.0: 27140801
27440312
192
3.0: 27440192

40210
ss 13.0: 27440192
13.0: 27440192

2/1X10
10
40210
'440210
.0202
l40192

ss 13.0: 27440192
02
.0202
27440202
40210

l40192
27440192
5);
40210

;;31.12.2025;30.06.2026;eCl@ss 13.0: 27140801

l: 27140801
40210
.0202
192
440202

15.Mai

15.Mai

15.Mai

5);

;;31.12.2025;30.06.2026;eCl@ss 13.0: 27140801

5; ;;31.12.2025;30.06.2026;eCl@ss 13.0: 27140801

5); ;;00.00.0000;00.00.0000;-

5); ;;00.00.0000;00.00.0000;

13.Mai

5); ;00.00.0000;00.00.0000;

[illegible]

Phoenix Contact Art.Bez.;	Ihre Materialnr.;	Phoenix Contact Alternativ-Art.Nr.;	Phoenix Contact Alternativ-Art.Bez.
Inc.;;;Ganghoferstraße 34;82216;Maisach;1852820			;VC-TFS 8;PHX1852820;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1852862			;VC-AF;PHX1852862;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1852846			;VC-TFS 2;PHX1852846;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1853476			;VC-TFS 6;PHX1853476;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1855102			;VC-K-T2-R;PHX1855102;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1853531			;VC-AML 6;PHX1853531;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1855107			;VC-K-T2-R-M25;PHX1855107;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1852914			;VC-TR3/4M;PHX1852914;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1852901			;VC-TR2/3M;PHX1852901;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1852948			;VC-K-T2-Z-M25;PHX1852948;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1855120			;VC-K-T3-R-M25;PHX1855120;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1852859			;VC-AML 2;PHX1852859;
Inc.;;;Ganghoferstraße 34;82216;Maisach;1665075			;EWR;PHX1665075;

.;Last-Order;Last-Shipment;Menge 2023 ST;Menge 2024 ST;Menge 2025 ST;AE-Menge 2
;;31.12.2025;30.06.2026;2.050 ST;2.800 ST;800 ST;800 ST
;;31.12.2025;30.06.2026;5.500 ST;2.550 ST;450- ST;450- ST

107; ;;31.12.2025;30.06.2026;1.030 ST;2.685 ST;10 ST;10 ST
;;31.12.2025;30.06.2026;2.780 ST;1.020 ST;0 ST;0 ST

025 ST