

How to Install a Firmware Update

Installing the latest firmware update on your GHv4 is quick and straightforward. You have two options:

Using the Golden Harvest Commander:

- Open the Golden Harvest Commander web app.
- Click on the "Check Firmware" button to download and install the update.

Manual Installation:

- Download the .bin firmware file.
- Copy the file to your SD card.
- Insert the SD card into your GHv4 and reboot the board.

Update Progress Indication:

During the update, the onboard status LED and any connected accent LEDs will pulse, gradually speeding up as the process nears completion.

Firmware Changelog GHv4

v0.7.4-1

Release Date: 11.12.2024

New Features:

- Low Battery Protection:
 - When the battery voltage is less than 2.65V, the firmware automatically enters deep sleep upon powering the board to minimize current drain. At this low voltage, playing a voltage-critical warning is not feasible because doing so would trigger the battery's built-in protection, cutting off the battery from the load and shutting down the board.
 - If you attempt to wake up the board by pressing the power button while the voltage is still below 2.65V, the onboard status LED and any connected accent LEDs will blink once before the board re-enters deep sleep. Once the battery voltage exceeds 2.65V, pressing the power button will wake up the board as expected.

Bug Fixes:

- The firmware will automatically use default parameter values if the settings.txt file is missing, ensuring the user interface sounds work even in this scenario.
- Sound fonts using non-GHv4 naming schemes are supported again. Nevertheless, for best performance and compatibility, we strongly recommend using the GHv4 naming scheme for all sound fonts. This ensures optimal functionality and minimizes potential issues.
- Installing UI sound packages via the web app works now.
- Avoid potential firmware crash when entering deep sleep.
- Automatically limit the Bluetooth name of the GHv4, which is set in the general.txt, to 9 characters.
- Save the Bluetooth and WiFi name of the GHv4 that is set in the ForceSync app.

- Fix low voltage warning.
- Fix accent LEDs 8 - 10.
- Audio Distortion Fix:
 - Resolved an issue where audio distortion sometimes occurred after disabling Bluetooth or WiFi by pressing the power button following remote control. The audio now functions correctly under these conditions.

You can download the firmware update here:

<https://drive.google.com/file/d/1BJyvXjtTO7mbSAKKZsIOPaEBYWrA8OH/view?usp=sharing>

v0.7.3-86

Release Date: 19.11.2024

- Initial public release of the GHv4.