




THREE60

Conference Table

Includes Add-Ons: **S1** | **S2** | **S3**


General Installation Guide

Sections

S1 :: Sitting Height 1

S2 :: Standing Height 9

S3 :: Optional Power..... 15



S1: Sitting Height

Overview

THREE60 Conference Table

⚠ Quantities are for a 48" x 216" table, parts may vary depending on project, but install steps will remain same.

Parts List


Code	Qty.	Description	
GCNAB	2	Angled Sleigh Leg	
CNS48144	1	Trapezoid Surface	
	2	In-Surface Grommet	
CNCGB	2	Center Grommet Spacers	
	2	In-Surface Grommet	
CNCBV2	4	Cabinet Base	
BFB1	6	Flat Bracket	
GCNABCOV*	4	Covered Leg	

*If applicable.

1 | Prepare Surface and Measure for Legs


Carefully place surface upside-down on floor, a cushioned area is preferred. Measure 12" from surface edge and center-align to determine leg placement.

NOTE: Same process for square-ended table.







2 | Secure Angled Sleigh Legs

Follow measurements and insert screws per leg through metal plate and into laminate surface.




3 | Measure for Cabinet Base or Covered Leg

Place cabinet base, or covered leg, centered under table grommet cutouts.




4 | Install Cabinet base or covered Leg

Insert 4 screws per base through laminate top into bottom of surface.




5 | Attach Hardware to Surface Edge

Insert 2 wooden dowels, attach 2 flat brackets, and connect 4 sets of joint fasteners to one side of each surface edge.




6 | Flip and Assemble

Flip each piece over so that it is standing on a leg/cabinet base. Align open holes on surface edge with wooden dowels and threaded rods on other surface edge.





7 | Fully Secure Hardware



8 | Install Grommets

Insert wire management grommet.







S2: Standing height

Overview

THREE60 Conference Table

⚠ All parts listed are for a single standing height table; additional parts will be needed for additional standing height table.


Parts List

Code	Qty.	Description	
GCNABSH	2	Standing Height Angled Sleigh Leg	
CNS4896	1	Main Surface	
	1	In-Surface Grommet	
GCNABSHLE	2	Support Brace	
BFB1	2	Flat Brackets	

1 | Prepare Surface


Carefully place surface upside-down on floor, a cushioned area is preferred. Measure 12" from surface edge and center-align to determine leg placement. Attach 2 flat brackets on center seam of table.

NOTE: Leg placement may need to be adjusted based on surface size.




2 | Install Angled Sleigh Legs

Follow measurements and insert 15 screws per leg through metal plate and into laminate surface.




3 | Install Support Brace



4 | Flip and Insert Grommet

Insert wire management grommet.




Note: See page 13 for optional covered sleigh leg. See page 15 for power module install.




Optional Covered Sleigh Leg

All steps for installation are the same. However, leg will be aligned with grommet cutout on the table.

NOTE: Covered sleigh leg is optional for wire management.





S3: Optional Power Overview


THREE60 Conference Table

Parts List

Code	Qty.	Description	
BPCONF2V2 or BPCONF3	1	In-Surface Power Module	
JC1	5	J-Clips	
VB24	1	Cable Vertebrae	


1 | Attach Metal Clips and Insert into Surface

Attach 2 metal clips to back of module base then insert into pre-cut holes in surface.



2 | Secure Module into Place

Insert plastic clamps into holes on bottom of module. Rotate and then push against surface to clamp module into place.



3 | Optional Power Vertebrae

Attach vertebrae to underside of top panel. Insert wood screws through top bracket and into laminate panel.

NOTE: Power vertebrae will be mounted adjacent to power module.

