


Open battery cover, insert batteries and replace cover.



Warm your hands. Remove nail polish and false nails if necessary.



Rest for 5 minutes before taking your measurement.



Insert finger into device.



Press button to take measurement. Readings can take up to 1 minute to stabilise.



Kinetik JPD-500G UK QS Guide 20220921

