



New and Changed Information

- [New and Changed Information for This Release, on page 1](#)

New and Changed Information for This Release

The following table provides an overview of the changes to this guide for Cisco UCS Manager, Release 4.2.

Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.2(3b)

Feature	Description	Where Documented
Cisco UCS 6536 Fabric Interconnect	This release introduces Cisco UCS 6536 Fabric Interconnect that supports 36 x 100G/50G/40G/10G/1G Quad Small Form Pluggable (QFP28) ports.	• Cisco UCS 6536 Fabric Interconnect Overview • Cisco UCS 6536 Fabric Interconnect
Migrating Cisco UCS 6300 Series Fabric Interconnects	Cisco UCS Manager supports migration of UCS 6300 series Fabric Interconnects to Cisco UCS 6536 Fabric Interconnect.	• Cisco UCS 6500 Series Fabric Interconnect Hardware Compatibility Matrix • Cisco UCS 6300 Series Fabric Interconnect Migration Considerations • Migrating from UCS 6300 Series Fabric Interconnects to UCS 6536 Fabric Interconnects

Feature	Description	Where Documented
Migrating Cisco UCS 6200 Series Fabric Interconnects	Cisco UCS Manager supports migration of UCS 6200 series Fabric Interconnects to Cisco UCS 6536 Fabric Interconnect.	• Cisco UCS 6500 Series Fabric Interconnect Hardware Compatibility Matrix • Cisco UCS 6200 Series Fabric Interconnect Migration Considerations • Migrating from UCS 6200 Series Fabric Interconnects to UCS 6536 Fabric Interconnects

Table 2: New Features and Changed Behavior in Cisco UCS Manager, Release 4.2(1d)

Feature	Description	Where Documented
-	No significant changes were made to this guide for the current release.	-